
Site	Grey Mare Lane	**CCL Project Number**	NW 205	
Date Of Survey	24.09.25			

Item	Photograph Referance No	Location		Comments
1	4973	Newcombe Close		General Photographs. Patchy tarmac visible to the pavment area which is in need of repair
2	4974	Newcombe Close		Tarmac in need of repair. Damage visibile where striaght kerb meets radius kerb. Light scuff marks visible on kerbs
3	4975	Newcombe Close		Tarmac in need of repair. Damage visibile where striaght kerb meets radius kerb. Light scuff marks visible on kerbs Discolouration of kerbs and finishes present due to age
4	4976	Newcombe Close		Tarmac in need of repair. Light scuff marks visible on kerbs Discolouration of kerbs and finishes present due to age
5	4977	Newcombe Close		Tarmac in need of repair. Light scuff marks visible on kerbs Discolouration of kerbs and finishes present due to age
6	4978	Newcombe Close		Tarmac in need of repair. Light scuff marks visible on kerbs Discolouration of kerbs and finishes present due to age Low level kerbs appear to have been replaced previously

7	4979	Newcombe Close		Tarmac in need of repair. Light scuff marks visible on kerbs Discolouration of kerbs and finishes present due to age Low level kerbs appear to have been replaced previously
8	4980	Newcombe Close		Tarmac in need of repair. Light scuff marks visible on kerbs Kerbs Cracked front to back Discolouration of kerbs and finishes present due to age Low level kerbs appear to have been replaced previously
9	4981	Newcombe Close		Tarmac in need of repair. Light scuff marks visible on kerbs Corners of kerbs showing signs of damage Discolouration of kerbs and finishes present due to age Low level kerbs appear to have been replaced previously
10	4982	Newcombe Close		General photogrpah of edgings to inside edge of footpath. Light damage visible under the fallen leaves
11	4983	Newcombe Close		General photogrpah of edgings to inside edge of footpath. Light damage visible under the fallen leaves Section of kerb missing where old post is situated
12	4984	Newcombe Close		General photogrpah of edgings to inside edge of footpath. Light damage visible under the fallen leaves
13	4985	Newcombe Close		General photogrpah of edgings to inside edge of footpath. Light damage visible under the fallen leaves

14	4986	Newcombe Close		General photogrpah of edgings to inside edge of footpath. Light damage visible under the fallen leaves Joints of kerbs opening up Line of kerbs not straight appears to have been pushed back
15	4987	Newcombe Close		General photogrpah of edgings to inside edge of footpath. Light damage visible under the fallen leaves Joints of kerbs opening up Line of kerbs not straight appears to have been pushed back Backing kerbs do not run in to radius kerb (one appears to be missing)
16	4988	Newcombe Close		Kerbs appear to have been replaced and back line of kerbs do not line through Tarmac is in need of repair
17	4989	Newcombe Close		Tarmac is in need of repair Concrete level access has been formed
18	4990	Newcombe Close		Tarmac is in need of repair Concrete level access has been formed
19	4991	Newcombe Close		Tarmac is in need of repair Concrete level access has been formed
20	4992	Newcombe Close		Tarmac is in need of repair

21	4993	Newcombe Close		Tarmac is in need of repair
22	4994	Newcombe Close		Tarmac is in need of repair
23	4995	Newcombe Close		Tarmac is in need of repair Level access kerbs are not level
26	4998	Newcombe Close		Lamp post 05 has been hit/is damaged and in need or repair
27	4999	Newcombe Close		Kerbs are damage/cracked Riseng kerb to standard kerb is not level Tarmac is in poor condition
29	5001	Newcombe Close		Kerbs are damage/cracked Rising kerb to standard kerb is not level Tarmac is in poor condition
30	5002	Newcombe Close		Kerbs are damage/cracked/Chipped Tarmac is in need of repair, in poor condition

31	5003	Newcombe Close		Kerbs are un even along this stretch of road Gully is full of leaves which could potentially result in ponding water on the road Tarmac is in need of repair, in poor condition
32	5004	Newcombe Close		Kerbs are uneven along this stretch of road Gully is full of leaves which could potentially result in ponding water on the road Tarmac is in need of repair, in poor condition
33	5005	Newcombe Close		Kerbs are uneven along this stretch of road Tarmac is in need of repair, in poor condition
34	5006	Newcombe Close		Kerbs are uneven along this stretch of road Tarmac is in need of repair, in poor condition
35	5007	Newcombe Close		Kerbs are uneven along this stretch of road Tarmac is in need of repair, in poor condition
36	5008	Newcombe Close		Kerbs are uneven along this stretch of road Tarmac is in need of repair, in poor condition
37	5009	Newcombe Close		Kerbs are uneven along this stretch of road Tarmac is in need of repair, in poor condition

38	5010	Newcombe Close		Kerbs are uneven along this stretch of road Tarmac is in need of repair, in poor condition
39	5011	Newcombe Close		Kerbs are uneven along this stretch of road Tarmac is in need of repair, in poor condition
40	5012	Newcombe Close		Kerbs are uneven along this stretch of road Tarmac is in need of repair, in poor condition Kerb line has sunk next to gully
41	5013	Newcombe Close		Kerbs are uneven along this stretch of road Tarmac is in need of repair, in poor condition Kerb line has sunk next to gully
42	5014	Newcombe Close		Kerbs are uneven along this stretch of road Tarmac is in need of repair, in poor condition
43	5015	Newcombe Close		Kerbs are uneven along this stretch of road Tarmac is in need of repair, in poor condition Raised kerb line could be potential trip hazard
44	5016	Newcombe Close		Kerbs are uneven along this stretch of road Tarmac is in need of repair, in poor condition


45	5017	Newcombe Close		Kerbs are uneven along this stretch of road Tarmac is in need of repair, in poor condition
46	5018	Newcombe Close		Kerbs are uneven along this stretch of road Tarmac is in need of repair, in poor condition
47	5019	Newcombe Close		Kerbs are uneven along this stretch of road Tarmac is in need of repair, in poor condition
48	5020	Newcombe Close		Kerbs are uneven along this stretch of road Tarmac is in need of repair, in poor condition
49	5021	Newcombe Close		Edgings damaged/chipped Ed
50	5022	Newcombe Close		Edgings damaged/chipped Edging line does not line through
51	5023	Newcombe Close		Edgings damaged/chipped

52	5024	Newcombe Close		Edgings damaged/chipped
53	5025	Newcombe Close		Edgings damaged/chipped
54	5026	Newcombe Close		Edgings damaged/chipped
55	5027	Newcombe Close		Edgings damaged/chipped
56	5028	Newcombe Close		Edgings damaged/chipped
57	5029	Newcombe Close to Ashton New Road Link Path		Concretre repair visible around water meter box (assumed water meter box) Joints in flagging uneven
58	5030	Newcombe Close to Ashton New Road Link Path		Concretre repair visible around water meter box (assumed water meter box) Joints in flagging uneven

59	5031	Newcombe Close to Ashton New Road Link Path		Concretre repair visible around water meter box (assumed water meter box) Joints in flagging uneven Edgings do not line through
60	5032	Newcombe Close to Ashton New Road Link Path		Concretre repair visible around water meter box (assumed water meter box) Joints in flagging uneven Edgings do not line through
61	5033	Newcombe Close to Ashton New Road Link Path		Concretre repair visible around water meter box (assumed water meter box) Joints in flagging uneven Edgings do not line through Concrete can be seen around box to left of path
62	5034	Newcombe Close to Ashton New Road Link Path		Concretre repair visible around water meter box (assumed water meter box) Joints in flagging uneven Edgings do not line through Concrete can be seen around box to left of path
63	5035	Newcombe Close to Ashton New Road Link Path		Edgings do not line through
64	5036	Newcombe Close to Ashton New Road Link Path		Flag repair visible around water meter box (assumed water meter box) Joints in flagging uneven
65	5037	Newcombe Close to Ashton New Road Link Path		Flag repair visible around water meter box (assumed water meter box) Joints in flagging uneven

66	5038	Newcombe Close to Ashton New Road Link Path		Flag repair visible around water meter box (assumed water meter box) Joints in flagging uneven
67	5039	Newcombe Close to Ashton New Road Link Path		Flag repair visible around water meter box (assumed water meter box) Joints in flagging uneven Concrere around service box in path
68	5040	Newcombe Close to Ashton New Road Link Path		Flag repair visible around water meter box (assumed water meter box) Joints in flagging uneven Concrere around service box in path
69	5041	Newcombe Close to Ashton New Road Link Path		Flag repair visible around water meter box (assumed water meter box) Joints in flagging uneven Concrere around service box in path
70	5042	Newcombe Close to Ashton New Road Link Path		Flag repair visible around water meter box (assumed water meter box) Joints in flagging uneven
71	5043	Newcombe Close to Ashton New Road Link Path		Flag repair visible around water meter box (assumed water meter box) Joints in flagging uneven
72	5044	Newcombe Close to Ashton New Road Link Path		Flag repair visible around water meter box (assumed water meter box) Joints in flagging uneven

73	5045	Newcombe Close to Ashton New Road Link Path		Flag repair visible around water meter box (assumed water meter box) Joints in flagging uneven
74	5046	Newcombe Close to Ashton New Road Link Path		Flag repair visible around water meter box (assumed water meter box) Joints in flagging uneven
75	5047	Newcombe Close to Ashton New Road Link Path		Flag repair visible around water meter box (assumed water meter box) Joints in flagging uneven Concrete around service box seen to the left
76	5048	Newcombe Close to Ashton New Road Link Path		Flag repair visible around water meter box (assumed water meter box) Joints in flagging uneven Concrete around service box seen to the left
77	5049	Newcombe Close to Ashton New Road Link Path		Flag repair visible around water meter box (assumed water meter box) Joints in flagging uneven Concrete around service box seen to the left past water meter box
78	5050	Newcombe Close to Ashton New Road Link Path		Flag repair visible around water meter box (assumed water meter box) Joints in flagging uneven Concrete around service box seen to the left past water meter box
79	5051	Newcombe Close to Ashton New Road Link Path		Flag repair visible around water meter box (assumed water meter box) Joints in flagging uneven Concrete around service box seen to the left past water meter box

80	5052	Newcombe Close to Ashton New Road Link Path		Flag repair visible around water meter box (assumed water meter box) Joints in flagging uneven Concrete around service box seen to the left past water meter box
81	5053	Newcombe Close to Ashton New Road Link Path		Flag repair visible around water meter box (assumed water meter box) Joints in flagging uneven Concrete around service box seen to the left past water meter box
82	5054	Newcombe Close to Ashton New Road Link Path		Joints in flagging uneven Concrete around service box seen to the left past water meter box
83	5055	Newcombe Close to Ashton New Road Link Path		Flags uneven and joints inconsistant Damaged flags to various locations
84	5056	Newcombe Close to Ashton New Road Link Path		Flags uneven and joints inconsistant Damaged flags to various locations
85	5057	Newcombe Close to Ashton New Road Link Path		Flags uneven and joints inconsistant Damaged flags to various locations Edging can be seen to be damaged
86	5058	Newcombe Close to Ashton New Road Link Path		Flags uneven and joints inconsistant Damaged flags to various locations Edging can be seen to be damaged Transition between flagged path and tarmac path is uneven with damage visible to kerb line

87	5059	Newcombe Close to Ashton New Road Link Path		Flags uneven and joints inconsistant Damaged flags to various locations Edging can be seen to be damaged Transition between flagged path and tarmac path is uneven with damage visible to kerb line
88	5060	Newcombe Close to Ashton New Road Link Path		Flags uneven and joints inconsistant Damaged flags to various locations Edging can be seen to be damaged Transition between flagged path and tarmac path is uneven with damage visible to kerb line
89	5061	Newcombe Close to Ashton New Road Link Path		Flags uneven and joints inconsistant Damaged flags to various locations Edging can be seen to be damaged Transition between flagged path and tarmac path is uneven with damage visible to kerb line
90	5062	Record only - Adjacent path		Record only
91	5063	Newcombe Close to Ashton New Road Link Path		Edging kerb not visible due to over grown grass
92	5078	Newcombe Close to Ashton New Road Link Path		Edging kerb not visible due to over grown grass Broken concrete bollard
93	5079	Newcombe Close to Ashton New Road Link Path		Edging kerb not visible due to over grown grass

94	5080	Newcombe Close to Ashton New Road Link Path		Edging kerb not visible due to over grown grass Broken concrete bollard
95	5081	Newcombe Close to Ashton New Road Link Path		Edging kerb not visible due to over grown grass Broken concrete bollard
96	5082	Newcombe Close to Ashton New Road Link Path		Tarmac pathway in need of repairs Metal fencing not plumb, in need of repainting/repairs in areas Edgings unable to be inspected due to over grown vegitation
97	5083	Newcombe Close to Ashton New Road Link Path		Tarmac pathway in need of repairs Metal fencing not plumb, in need of repainting/repairs in areas Edgings unable to be inspected due to over grown vegitation
98	5084	Newcombe Close to Ashton New Road Link Path		Tarmac pathway in need of repairs Metal fencing not plumb, in need of repainting/repairs in areas Edgings unable to be inspected due to over grown vegitation
99	5085	Newcombe Close to Ashton New Road Link Path		Tarmac pathway in need of repairs Metal fencing not plumb, in need of repainting/repairs in areas Edgings unable to be inspected due to over grown vegitation
100	5086	Newcombe Close to Ashton New Road Link Path		Tarmac pathway in need of repairs Metal fencing not plumb, in need of repainting/repairs in areas Edgings unable to be inspected due to over grown vegitation

101	5087	Newcombe Close to Ashton New Road Link Path		Tarmac pathway in need of repairs Metal fencing not plumb, in need of repainting/repairs in areas Edgings unable to be inspected due to over grown vegitation
102	5088	Newcombe Close to Ashton New Road Link Path		Tarmac pathway in need of repairs Metal fencing not plumb, in need of repainting/repairs in areas Edgings unable to be inspected due to over grown vegitation
103	5089	Newcombe Close to Ashton New Road Link Path		Tarmac pathway in need of repairs Metal fencing not plumb, in need of repainting/repairs in areas Edgings unable to be inspected due to over grown vegitation
104	5090	Newcombe Close to Ashton New Road Link Path		Tarmac pathway in need of repairs Metal fencing not plumb, in need of repainting/repairs in areas Edgings unable to be inspected due to over grown vegitation
105	5091	Newcombe Close to Ashton New Road Link Path		Tarmac pathway in need of repairs Metal fencing not plumb, in need of repainting/repairs in areas Edgings unable to be inspected due to over grown vegitation
106	5092	Newcombe Close to Ashton New Road Link Path		Tarmac pathway in need of repairs Metal fencing not plumb, in need of repainting/repairs in areas Edgings unable to be inspected due to over grown vegitation Damaged paving can be seen on Ashton New Road footpath
107	5093	Newcombe Close to Ashton New Road Link Path		Tarmac pathway in need of repairs Metal fencing not plumb, in need of repainting/repairs in areas Edgings unable to be inspected due to over grown vegitation Damaged paving can be seen on Ashton New Road footpath


108	5094	Newcombe Close to Ashton New Road Link Path		Tarmac pathway in need of repairs Metal fencing not plumb, in need of repainting/repairs in areas Edgings unable to be inspected due to over grown vegitation Damaged paving can be seen on Ashton New Road footpath
109	5095	Newcombe Close to Ashton New Road Link Path		Tarmac pathway in need of repairs Metal fencing not plumb, in need of repainting/repairs in areas Edgings unable to be inspected due to over grown vegitation Damaged paving can be seen on Ashton New Road footpath
110	5096	Ashton New Road Footpath		Tarmac pathway in need of repairs Edgings unable to be inspected due to over grown vegitation Damaged paving can be seen on Ashton New Road footpath Existing lamp post is damaged with paint also in need of repair
111	5097	Ashton New Road Footpath		Tarmac pathway in need of repairs Edgings unable to be inspected due to over grown vegitation Damaged paving can be seen on Ashton New Road footpath
112	5098	Ashton New Road Footpath		General condition of lampost is poor Paving can be seen to be uneven
113	5099	Ashton New Road Footpath		Record of damage to lamp post
114	5100	Ashton New Road Footpath		Paving uneven Scuff marks present on flags Small localised chips to edges

115	5101	Ashton New Road Footpath		Paving uneven Scuff marks present on flags Small localised chips to edges
116	5102	Ashton New Road Footpath		Paving uneven Scuff marks present on flags Small localised chips to edges
117	5103	Ashton New Road Footpath		Paving uneven Scuff marks present on flags Small localised chips to edges
118	5104	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags
119	5105	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags
120	5106	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags
121	5107	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags

122	5108	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags
123	5109	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags
124	5110	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags
125	5111	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags
126	5112	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags
127	5113	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags
128	5114	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags


129	5115	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags
130	5116	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags
131	5117	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags
132	5118	Ashton New Road Footpath		Flags uneven Damaged flag which has been mitre cut Chips to flag edges
133	5119	Ashton New Road Footpath		Flags uneven Damaged flags Chips to flag edges
134	5120	Ashton New Road Footpath		Flags uneven Damaged flags Chips to flag edges
135	5121	Ashton New Road Footpath		Flags uneven Damaged flags Chips to flag edges

136	5122	Ashton New Road Footpath		Flags uneven Damaged flags Chips to flag edges
137	5123	Ashton New Road Footpath		Flags uneven Damaged flags Chips to flag edges
138	5124	Ashton New Road Footpath		Flags uneven Damaged flags Chips to flag edges
139	5125	Ashton New Road Footpath		Flags uneven Damaged flags Chips to flag edges
140	5126	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags
141	5127	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags
142	5128	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags

143	5129	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags
144	5130	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags
145	5131	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags
146	5132	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags Lampost paint in need of repainting with minor damage
148	5134	Ashton New Road Footpath		General condition of lampost is poor Paving can be seen to be uneven
149	5135	Ashton New Road Footpath		General condition of lampost is poor
150	5136	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags

151	5137	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags
152	5138	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags
153	5139	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags
154	5140	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags
155	5141	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags
156	20250924_135027	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags
157	20250924_135030	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags

158	20250924_135032	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags
159	20250924_135035	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags Edging detail not seen
160	20250924_135039	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags Edging in poor state of repair throughout Ashton New Road elevation to all areas
161	20250924_135042	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags Edging in poor state of repair throughout Ashton New Road elevation to all areas
162	20250924_135048	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags Edging in poor state of repair throughout Ashton New Road elevation to all areas Tactile paving at level crossing can be seen to be in a poor state of repair
163	20250924_135051	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags Edging in poor state of repair throughout Ashton New Road elevation to all areas Tactile paving at level crossing can be seen to be in a poor state of repair
164	20250924_135053	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags Edging in poor state of repair throughout Ashton New Road elevation to all areas Tactile paving at level crossing can be seen to be in a poor state of repair


165	20250924_135055	Ashton New Road Footpath		Various damaged flags Uneven flags Scuff marks on flags Edging in poor state of repair throughout Ashton New Road elevation to all areas
166	20250924_135057	Grey Mare Lane		Various damaged flags Uneven flags Scuff marks on flags Edging in poor state of repair throughout Ashton New Road elevation to all areas
167	20250924_135100	Grey Mare Lane		General Lamp post photograph
168	20250924_135103	Island on Grey Mare Lane		Traffic island general photograph at junction of Grey Mare Lane Ashton New Road
177	20250924_135512	Island on Grey Mare Lane		Open joints can be seen to kerbs Chip marks present on kerb edge/joint
178	20250924_135524	Island on Grey Mare Lane		Kebs can be seen out of position on traffic island Scuff marks present to kerbs
179	20250924_135528	Island on Grey Mare Lane		Kebs can be seen out of position on traffic island Scuff marks present to kerbs

180	20250924_135530	Island on Grey Mare Lane		Kebs can be seen out of position on traffic island Scuff marks present to kerbs
181	20250924_135532	Island on Grey Mare Lane		Kebs can be seen out of position on traffic island Scuff marks present to kerbs
182	20250924_135537	Island on Grey Mare Lane		Kebs can be seen out of position on traffic island Scuff marks present to kerbs
183	20250924_135541	Island on Grey Mare Lane		Kebs can be seen out of position on traffic island Scuff marks present to kerbs
184	20250924_135544	Island on Grey Mare Lane		Kebs can be seen out of position on traffic island Scuff marks present to kerbs
185	20250924_135547	Island on Grey Mare Lane		Kebs can be seen out of position on traffic island Scuff marks present to kerbs
186	20250924_135549	Island on Grey Mare Lane		Kebs can be seen out of position on traffic island Scuff marks present to kerbs

187	20250924_135602	Right turn in to GML from ANR		Damage can be seen on turning in point in point from Ashton New Road in to Grey Mare Lane Stone left on the pavement Chip marks present on kerbs
188	20250924_135605	Right turn in to GML from ANR		Damage can be seen on turning in point in point from Ashton New Road in to Grey Mare Lane Stone left on the pavement Chip marks present on kerbs
189	20250924_135608	Right turn in to GML from ANR		Damage can be seen on turning in point in point from Ashton New Road in to Grey Mare Lane Stone left on the pavement Chip marks present on kerbs
190	20250924_135628	Grey Mare Lane		Some kerbs not lining through between footpath and road Kerbs uneven Minor staining to footpath
191	20250924_135631	Grey Mare Lane		Some kerbs not lining through between footpath and road Kerbs uneven Minor staining to footpath
192	20250924_135633	Grey Mare Lane		Some kerbs not lining through between footpath and road Kerbs uneven Minor staining to footpath
193	20250924_135635	Grey Mare Lane		Open joints and minor damage along road

194	20250924_135639	Grey Mare Lane		Open joints and minor damage along road Staining to kerbs from tar
195	20250924_135641	Grey Mare Lane		Existing wall damaged (to be removed) Weeds over grown (various areas throughout walk seen)
196	20250924_135644	Grey Mare Lane		Existing wall damaged (to be removed) Weeds over grown (various areas throughout walk seen)
197	20250924_135645	Grey Mare Lane		Footpath repair completed around sign poist Damaged kerbs visible Kerbline not straight Tar staining on kerb line
198	20250924_135649	Grey Mare Lane		Damaged kerbs visible
199	20250924_135651	Grey Mare Lane		Change in tarmac finish noted along footpath minor open joints seen to kerbs Minor damage visible to kerbs
200	20250924_135653	Grey Mare Lane		Change in tarmac finish noted along footpath minor open joints seen to kerbs Minor damage visible to kerbs


201	20250924_135655	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places
202	20250924_135657	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places
203	20250924_135700	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places
204	20250924_135702	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places
205	20250924_135704	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places
206	20250924_135708	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
207	20250924_135710	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair

208	20250924_135713	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
209	20250924_135715	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
210	20250924_135721	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
211	20250924_135724	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
212	20250924_135731	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
213	20250924_135738	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
214	20250924_135741	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair

215	20250924_135745	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
216	20250924_135747	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
217	20250924_135750	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
218	20250924_135752	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
219	20250924_135755	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
220	20250924_135759	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
221	20250924_135802	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair

222	20250924_135806	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
223	20250924_135810	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
224	20250924_135812	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
225	20250924_135814	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
226	20250924_135816	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair Change in kerb profile
227	20250924_135818	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
228	20250924_135820	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair

229	20250924_135821	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
230	20250924_135824	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
231	20250924_135825	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
232	20250924_135832	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
233	20250924_135835	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
234	20250924_135837	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
235	20250924_135841	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair

236	20250924_135846	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
237	20250924_135850	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
238	20250924_135853	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
239	20250924_135857	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
240	20250924_135903	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
241	20250924_135906	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
242	20250924_135911	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair

243	20250924_135948	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
244	20250924_135954	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
245	20250924_135956	Grey Mare Lane		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
246	20250924_140310	Newcombe Close		General photograph Newcombe Close
247	20250924_140313	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
248	20250924_140315	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
249	20250924_140317	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair

250	20250924_140319	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
251	20250924_140321	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
252	20250924_140323	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
253	20250924_140325	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
254	20250924_140328	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
255	20250924_140330	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
256	20250924_140332	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair

257	20250924_140334	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
258	20250924_140336	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
259	20250924_140339	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
260	20250924_140342	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
261	20250924_140344	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
262	20250924_140346	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
263	20250924_140348	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair

264	20250924_140351	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
265	20250924_140353	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
266	20250924_140356	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
267	20250924_140358	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
268	20250924_140359	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
269	20250924_140401	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
270	20250924_140403	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair

271	20250924_140406	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
272	20250924_140408	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
273	20250924_140410	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
274	20250924_140412	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
275	20250924_140414	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
276	20250924_140417	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
277	20250924_140419	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair

278	20250924_140421	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
279	20250924_140424	Newcombe Close		Minor open joints seen to kerbs Minor damage visible to kerbs Kerb line not striaght in places Tarmac in poor state of repair
280	20250924_140430	Newcombe Close		General photograph Newcombe Close
281	20250924_140433	Newcombe Close		General photograph Newcombe Close

Notes No drainage or gullys were checked during this surve
Weeds etc can be seen in various locaitons and these were not highlighted seperatly
Some areas could not be seen due to fallen leaves so these have not been recorded