
1A






Minor surface damage.

1B






Large area of plaster lost historically.

Ceiling Inspection

Sheppard Robson

1C






Large area removed, some surface damage.

2A






Large area removed, some surface damage.

Ceiling Inspection

Sheppard Robson


2B






Surface delamination.

2C






Small holes within plaster, probably related to historic services.

Ceiling Inspection

3A






Large area lost, clear signs of historic repairs to rafters and wall plate.

3B






Minor damage due to service penetrations.

Ceiling Inspection

Sheppard Robson

3C






Minor damage due tot service penetrations.

4A






Large area removed, additional surface damage, assume due to rafter repair.

Ceiling Inspection

Sheppard Robson

4B






Some surface delamination.

4C






Small holes within surface, some plaster loss with expanded mesh exposed.

Ceiling Inspection

Sheppard Robson


5A





5B






Ceiling Inspection

Sheppard Robson


5C





6A






Small loss of fabric to side of truss.

Ceiling Inspection

Sheppard Robson

6B






Water damage with some surface declamination. Large area removed with area with plaster lost from lath.

6C






Holes from historic service penetrations.

Ceiling Inspection

Sheppard Robson


7A





7B






Small opening to truss end.

Ceiling Inspection

Sheppard Robson


7C





8A






Small hole to truss end.

Ceiling Inspection

Sheppard Robson

8B






Small water damage evident.

8C






Small service penetrations.

Ceiling Inspection

Sheppard Robson

9A






Large area of material loss. Evidence of splice repairs to rafters and wall plate.

9B






Ceiling Inspection

9C






Minor surface damage.

10A






Small areas of loss.

Ceiling Inspection

Sheppard Robson

10B






Area of loss to truss foot.

10C






Larger hold created by redundant services.

Ceiling Inspection

Sheppard Robson


11A





11B






Ceiling Inspection

Sheppard Robson

11C





Ceiling Inspection

Sheppard Robson

enquiries@sheppardrobson.com
www.sheppardrobson.com

SHEPPARD ROBSON

Sheppard Robson Architects LLP is a limited liability partnership registered in England and Wales under number OC391030. A list of the members is available for inspection at its registered office at 77 Parkway, London NW1 7PU, UK. Sheppard Robson Architects LLP uses the word “partner” to refer to a member of the LLP, or an employee or consultant of the Group with equivalent standing and qualifications.