

Description

Photo 131 - Evidence of surveys taking place on the footpath leading up to the pedestrian access staircase.

Taken date

24/09/2026 at 12:27

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 10:38

File name

19780F6D-D1DE-4ACD-A13C-019...

Album

castlefield Viaduct delapidation survey



Description

Photo 130- Access from the public footpath onto the gravel footpath leading to staircase. Footpath in poor condition, note a contractor h...

Taken date

24/09/2026 at 12:26

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 12:33

File name

3AD99960-4D6C-425F-8A42-76F...

Album

castlefield Viaduct delapidation survey



Description

Photo 129 - Showing pedestrian footpath route from the public highway leading to the pedestrian access staircase.

Taken date

24/09/2026 at 12:26

Uploaded by

Karl Mcdonald

Upload date


25/09/2026 at 12:22

File name

C5B73D31-D11D-459E-A64F-C36...

Album

castlefield Viaduct delapidation survey



Description

Photo 128- 12th landing to flight of stairs, paint damage to several areas and graffiti as shown in photos.

Taken date

24/09/2026 at 12:26

Uploaded by

Karl Mcdonald

Upload date


25/09/2026 at 12:12

File name

E47E4BBC-0578-4EE3-B045-5158...

Album

castlefield Viaduct delapidation survey



Description

Photo 127- 11th landing to flight of stairs, paint damage to several areas and graffiti as shown in photos.

Taken date

24/09/2026 at 12:26

Uploaded by

Karl Mcdonald

Upload date


25/09/2026 at 11:46

File name

B5C6FAD2-99D6-4A86-9391-5DF...

Album

castlefield Viaduct delapidation survey



Description

Photo 126- 10th landing to flight of stairs, paint damage to several areas and graffiti as shown in photos.

Taken date

24/09/2026 at 12:26

Uploaded by

Karl Mcdonald

Upload date


25/09/2026 at 12:27

File name

5A737AA6-1BC0-4C47-A9AB-B77...

Album

castlefield Viaduct delapidation survey



Description

Photo 125- 9th landing to flight of stairs, paint damage to several areas and graffiti as shown in photos.

Taken date

24/09/2026 at 12:25

Uploaded by

Karl Mcdonald

Upload date


25/09/2026 at 12:17

File name

0657950E-84FD-4278-A75E-4779...

Album

castlefield Viaduct delapidation survey



Description

Photo 124- 8th landing to flight of stairs, paint damage to several areas as shown in photos.

Taken date

24/09/2026 at 12:25

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 12:02

File name

35DDA165-32A8-4F0B-943B-DF2...

Album

castlefield Viaduct delapidation survey



Description

Photo 123- 7th landing to flight of stairs, paint damage to several areas as shown in photos.

Taken date

24/09/2026 at 12:25

Uploaded by

Karl Mcdonald

Upload date


25/09/2026 at 11:52

File name

67825EA5-1446-4BEC-B7E7-8A49...

Album

castlefield Viaduct delapidation survey



Description

Photo 122- 6th landing to flight of stairs, paint damage to several areas and graffiti as shown in photos.

Taken date

24/09/2026 at 12:25

Uploaded by

Karl Mcdonald

Upload date


25/09/2026 at 10:38

File name

DA939581-0BB1-418A-9705-7FA7...

Album

castlefield Viaduct delapidation survey



Description

Photo 121- 5th landing to flight of stairs, paint damage to several areas and graffiti as shown in photos.

Taken date

24/09/2026 at 12:25

Uploaded by

Karl Mcdonald

Upload date


25/09/2026 at 11:49

File name

1F8277B7-8189-4F4B-A81B-EBD...

Album

castlefield Viaduct delapidation survey



Description

Photo 120- 4th landing to flight of stairs, paint damage to several areas as shown in photos.

Taken date

24/09/2026 at 12:25

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 11:57

File name

DC9728D1-87DA-46AB-9CF1-725...

Album

castlefield Viaduct delapidation survey



Description

Photo 119- 3rd landing to flight of stairs, paint damage to several areas and graffiti present as shown in photos.

Taken date

24/09/2026 at 12:25

Uploaded by

Karl Mcdonald

Upload date


25/09/2026 at 10:38

File name

BFC82BF5-2794-4F53-B51A-3590...

Album

castlefield Viaduct delapidation survey



Description

Photo 118- 2nd landing to flight of stairs, paint damage to several areas as shown in photos.

Taken date

24/09/2026 at 12:25

Uploaded by

Karl Mcdonald

Upload date


25/09/2026 at 11:56

File name

1C35EB8B-D605-4BE4-B288-E7C...

Album

castlefield Viaduct delapidation survey



Description

Photo 117 - Top flight of stairs, paint damage to several areas as shown in photos.

Taken date

24/09/2026 at 12:25

Uploaded by

Karl Mcdonald

Upload date


25/09/2026 at 12:05

File name

75A78FFD-D5E5-46E4-9406-6C3...

Album

castlefield Viaduct delapidation survey



Description

Photo 116- Progressive photos of the staircase leading from the top. Photos taken at every landing looking down the staircase. Graffiti p...

Taken date

24/09/2026 at 12:25

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 12:01

File name

CA18F701-E416-4ABB-899A-E4A...

Album

castlefield Viaduct delapidation survey



Description

Photo 115- Block paving missing with infill repair to top of the pedestrian access staircase

Taken date

24/09/2026 at 12:24

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 11:49

File name

59279E1E-16DB-4EE1-BADF-B16...

Album

castlefield Viaduct delapidation survey



Description

Photo 114 - Tarmac surface layer wearing away to entrance to the viaduct.

Taken date

24/09/2026 at 12:24

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 12:01

File name

3BDAD628-790E-420A-8910-97E...

Album

castlefield Viaduct delapidation survey



Description

Photo 113- Showing access to the top of pedestrian staircase leading to the viaduct entrance.

Taken date

24/09/2026 at 12:24

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 10:38

File name

5E155D43-BCD5-4166-9471-62A...

Album

castlefield Viaduct delapidation survey



Description

Photo 112 - Surface layer of tarmac wearing away and surface staining adjacent to planter at viaduct entrance.

Taken date

24/09/2026 at 12:24

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 11:56

File name

9BCA7513-29DE-49EC-A6AC-982...

Album

castlefield Viaduct delapidation survey



Description

Photo 111- Tarmac surface wearing away, staining to surface, vegetation overgrowth and some existing cones and contractor fencing left to...

Taken date

24/09/2026 at 12:24

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 12:07

File name

2F08529D-9E98-46F1-BC23-C3C3...

Album

castlefield Viaduct delapidation survey



Description

Photo 110- Surface layer of tarmac wearing away to parking bays on LH side adjacent to Metrolink line.

Taken date

24/09/2026 at 12:24

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 12:21

File name

893A30D5-37B1-4E2C-862A-2B3...

Album

castlefield Viaduct delapidation survey



Description

Photo 109 - View of remaining survey section outside viaduct access gates.

Taken date

24/09/2026 at 12:23

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 12:18

File name

E092046B-4272-4A79-A533-65BE...

Album

castlefield Viaduct delapidation survey



Description

Photo 108- Surface damage to tarmac in central access section heading towards viaduct staircase.

Taken date

24/09/2026 at 12:23

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 15:53

File name

E9EF94D2-E311-4059-8853-0033...

Album

castlefield Viaduct delapidation survey



Description

Photo 107 - Tarmac damage to parking bay to RH side adjacent to pedestrian access.

Taken date

24/09/2026 at 12:23

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 12:28

File name

C4D89762-9997-416E-A8AC-EE8...

Album

castlefield Viaduct delapidation survey



Description

Photo 106 - Vegetation present in central road gully.

Taken date

24/09/2026 at 12:23

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 23:56

File name

5BDE2BC1-312B-4792-8795-99D...

Album

castlefield Viaduct delapidation survey



Description

Photo 105 - Signs of surface depressions in parking bays on RH side. Vegetation present along kerb line.

Taken date

24/09/2026 at 12:23

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 12:33

File name

B4B6FDD7-24A7-454A-AD9B-7DA...

Album

castlefield Viaduct delapidation survey



Description

Photo 104- Potholes visible to central road area adjacent to parking bays down the RH side.

Taken date

24/09/2026 at 12:23

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 17:37

File name

0A154766-AD57-460F-995F-ADD...

Album

castlefield Viaduct delapidation survey



Description

Photo 103- Potholes visible in central area of road between parking bays.

Taken date

24/09/2026 at 12:23

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 22:05

File name

ADB423B2-DD4A-47D1-B682-804...

Album

castlefield Viaduct delapidation survey



Description

102 - Road condition in central area showing pot hole and small concrete lump.

Taken date

24/09/2026 at 12:23

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 23:55

File name

7207DD2C-9CD5-4BA0-B90F-AE0...

Album

castlefield Viaduct delapidation survey



Description

Photo 101 - Pot holes and gouges to road surface in central area.

Taken date

24/09/2026 at 12:23

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 23:55

File name

DE75FC53-0500-421A-9FBF-CF7C...

Album

castlefield Viaduct delapidation survey



Description

Photo 100 - Heavy gouges and depressions to central road section adjacent to RH side parking bays.

Taken date

24/09/2026 at 12:23

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 21:57

File name

FB32B771-B34D-4CE7-8EA9-FE6...

Album

castlefield Viaduct delapidation survey



Description

Photo 99- General condition of parking bays along RH side of carpark, adjacent to the public walkway leading to the staircase.

Taken date

24/09/2026 at 12:23

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 12:33

File name

73300BCB-A73D-45B2-8410-38D...

Album

castlefield Viaduct delapidation survey



Description

Photo 98 - Parking bay surface depression with some vegetation growth.

Taken date

24/09/2026 at 12:23

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 22:21

File name

5023CEED-3573-454E-95B6-865...

Album

castlefield Viaduct delapidation survey



Description

Photo 97 - View of the remainder of the carpark to pedestrian staircase. Road gully has vegetation present.

Taken date

24/09/2026 at 12:22

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 12:19

File name

1BF0C997-C438-4965-A87D-7E5...

Album

castlefield Viaduct delapidation survey



Description

Photo 96- General condition of road surface condition showing heavy gouges in several locations.

Taken date

24/09/2026 at 12:22

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 12:19

File name

7443422C-B955-4655-BADD-07C...

Album

castlefield Viaduct delapidation survey



Description

Photo 95 - General condition of road surface in central area between the parking bays.

Taken date

24/09/2026 at 12:22

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 22:55

File name

57D9EF68-8B70-47C6-AA53-E00...

Album

castlefield Viaduct delapidation survey



Description

Photo 94 - Depressions to road surface in central area.

Taken date

24/09/2026 at 12:22

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 12:42

File name

BC3BDF81-55B0-4D29-A86A-F53...

Album

castlefield Viaduct delapidation survey



Description

Photo 93 - Scratches and gouges to road surface in central area.

Taken date

24/09/2026 at 12:22

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 12:35

File name

1FA294C5-5BA6-4F68-ADAC-57B...

Album

castlefield Viaduct delapidation survey



Description

Photo 92 - Gouges to road surface in central area.

Taken date

24/09/2026 at 12:22

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 23:55

File name

B33FFAC2-A240-4FC0-AECB-8A9F...

Album

castlefield Viaduct delapidation survey



Description

Photo 91 - wider view of the road capturing the next batch of photographs.

Taken date

24/09/2026 at 12:22

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 23:56

File name

D94098F0-A24F-4098-91B6-4A4B...

Album

castlefield Viaduct delapidation survey



Description

Photo 90 - Potholes present in the bays and road.

Taken date

24/09/2026 at 12:22

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 12:30

File name

416458F0-9147-4372-88D6-9703...

Album

castlefield Viaduct delapidation survey



Description

Photo 89 - General condition photo of the parking bays and access road. The next 26 photos are progressive carpark condition working towa...

Taken date

24/09/2026 at 12:22

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 12:28

File name

36E632D7-4BA3-45DF-A6A9-A93...

Album

castlefield Viaduct delapidation survey



Description

Photo 88 - Bay 3 has potholes present.

Taken date

24/09/2026 at 12:21

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 21:52

File name

D6647407-D707-43FC-81BC-893...

Album

castlefield Viaduct delapidation survey



Description

Photo 87- Road gully adjacent to bay 3.

Taken date

24/09/2026 at 12:20

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 23:56

File name

62CBC778-E4CE-4D84-9D2D-C07...

Album

castlefield Viaduct delapidation survey



Description

Photo 86 - Carpark bay 1, LH side on entry has potholes present.

Taken date

24/09/2026 at 12:19

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 12:29

File name

AA111B5B-81D1-4822-8554-954...

Album

castlefield Viaduct delapidation survey



Description

Photo 85 - Iron works in centre of road has vegetation growth. General photo of gully condition.

Taken date

24/09/2026 at 12:19

Uploaded by

Karl Mcdonald

Upload date


25/09/2026 at 23:56

File name

79C3A243-C456-4691-9744-E545...

Album

castlefield Viaduct delapidation survey



Description

Photo 84 - View of the carpark area from the end of the access road.

Taken date

24/09/2026 at 12:19

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:27

File name

03E25F61-9F9F-4346-988F-DEE4...

Album

castlefield Viaduct delapidation survey



Description

Photo 86 - RH side of access road on radius kerb bend, tarmac surface in poor condition, yellow lines faded, concrete infill present.

Taken date

24/09/2026 at 12:19

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 12:09

File name

32BD4971-F700-428F-9F27-E2AF...

Album

castlefield Viaduct delapidation survey



Description

Photo 85 - Services scaring crossing the road, infilled with concrete. concrete is cracking and road is generally in poor condition.

Taken date

24/09/2026 at 12:18

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:28

File name

87F74719-101B-4A36-9408-9AD...

Album

castlefield Viaduct delapidation survey



Description

Photo 84 - Concrete infill to RHS side of access road towards turning point into carpark. Tarmac abutment junction in poor condition.

Taken date

24/09/2026 at 12:18

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 10:28

File name

1E7E6FBF-A949-4F35-9A31-346A...

Album

castlefield Viaduct delapidation survey



Description

Photo 83 - Kerb infill detail to LH side of access road. Yellow lines faded, block paving showing vegetation growth.

Taken date

24/09/2026 at 12:17

Uploaded by

Karl Mcdonald

Upload date

25/09/2026 at 10:33

File name

13325150-58ED-4D93-B879-49C...

Album

castlefield Viaduct delapidation survey



Description

Photo 82 - Steel road plate installed in centre of the road, infill concrete around plate is deteriorating.

Taken date

24/09/2026 at 12:17

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:23

File name

AD71E035-5209-47EE-B201-A913...

Album

castlefield Viaduct delapidation survey



Description

Photo 81 - Ironworks raised, infill concrete and tarmac showing signs of cracking etc. RHS of access road.

Taken date

24/09/2026 at 12:16

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:23

File name

4DC6C658-297D-4A51-9152-66C...

Album

castlefield Viaduct delapidation survey



Description

Photo 80 - Double yellow lines faded along the kerb edge down LHS of access road.

Taken date

24/09/2026 at 12:16

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:23

File name

6E7EB95D-D066-4B7D-A852-8AE...

Album

castlefield Viaduct delapidation survey



Description

Photo 79- Infill detail present along kerb junction down the remainder of the LHS of the access road. Road surface generally in poor cond...

Taken date

24/09/2026 at 12:15

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:23

File name

A5FA117A-88DD-46FE-ABF7-0E64...

Album

castlefield Viaduct delapidation survey



Description

Photo 78 - Large concrete infill present along remainder of the kerb line along the RHS of access road.

Taken date

24/09/2026 at 12:15

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:22

File name

37198FF3-524F-425F-891E-F0AA...

Album

castlefield Viaduct delapidation survey



Description

Photo 77- Concrete surround around ironworks is cracking to RHS of the access road.

Taken date

24/09/2026 at 12:14

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:22

File name

38E19C14-05E1-4662-B831-2CCF...

Album

castlefield Viaduct delapidation survey



Description

Photo 76 - Concrete surround around ironworks to RHS of access road.

Taken date

24/09/2026 at 12:14

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:22

File name

E1378F70-0EED-4AEB-B98D-E79...

Album

castlefield Viaduct delapidation survey



Description

Photo 75 - Large tarmac and concrete repair undertaken around manhole to LHS of access road.

Taken date

24/09/2026 at 12:14

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:22

File name

8FF76FBF-D810-423E-91BF-0BF1...

Album

castlefield Viaduct delapidation survey



Description

Photo 74 - Ironworks are raised with tarmac surround installed. Signal cable present. some vegetation along kerb abutments.

Taken date

24/09/2026 at 12:13

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:23

File name

29502087-E85B-47B7-8EB6-0FD...

Album

castlefield Viaduct delapidation survey



Description

Photo 73 - Concrete surround around ironworks shown. Vegetation growth present. Kerb slightly damaged to RHS of access road.

Taken date

24/09/2026 at 12:13

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:23

File name

91318128-E492-4B2D-9639-40A...

Album

castlefield Viaduct delapidation survey



Description

Photo 72 - Concrete surround around ironworks to RHS of access road. Kerb damaged in front of tactile paving.

Taken date

24/09/2026 at 12:13

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:23

File name

40AAD48B-80B8-491A-A558-97A...

Album

castlefield Viaduct delapidation survey



Description

Photo 71 - Drop kerbs are damaged to LHS of crossing point. tarmac infill at kerb junction is deteriorating. road markings are faded.

Taken date

24/09/2026 at 12:12

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:22

File name

3C8EFE85-85AC-4B41-A264-836...

Album

castlefield Viaduct delapidation survey



Description

Photo 70- Cracking to concrete surround around manhole in road.

Taken date

24/09/2026 at 12:12

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:22

File name

8B7A522B-780C-4B77-8063-5CE...

Album

castlefield Viaduct delapidation survey



Description

Photo 69- View of section of access road to the carpark just before traffic lights/ crossing point.

Taken date

24/09/2026 at 12:12

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:22

File name

67AA16EC-C457-476B-924D-24B...

Album

castlefield Viaduct delapidation survey



Description

Photo 68 - Raised ironworks with tarmac surround. Signal cable install. Infill detail to kerb and road junction visible.

Taken date

24/09/2026 at 12:11

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:22

File name

A2F31CF5-0325-464A-88E6-17D4...

Album

castlefield Viaduct delapidation survey



Description

Photo 67 - Cracking visible to concrete surround on manhole in middle of the road.

Taken date

24/09/2026 at 12:11

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:22

File name

4DE998F9-E32B-4AC4-B5F9-A303...

Album

castlefield Viaduct delapidation survey



Description

Photo 66- Damage to 5 kerbs along LHS of access road. Raised Aco drain shown with some vegetation in junctions.

Taken date

24/09/2026 at 12:10

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:22

File name

8D9783F6-4317-495D-81B6-245...

Album

castlefield Viaduct delapidation survey



Description

Photo 65 - Damaged kerb, raised iron works and signal cable present to LHS of access road.

Taken date

24/09/2026 at 12:10

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:23

File name

42B4DB20-0A94-426B-85F0-F122...

Album

castlefield Viaduct delapidation survey



Description

Photo 64 - Concrete infills around manhole covers in the centre of the road appear to be failing with cracking visible. Concrete also dro...

Taken date

24/09/2026 at 12:09

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:22

File name

F0B3E9DA-231C-405A-8545-7D7...

Album

castlefield Viaduct delapidation survey



Description

Photo 63 - Access road to carpark shown from opposite side of the bridge.

Taken date

24/09/2026 at 12:09

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:22

File name

91263206-98CA-4F3D-809B-2A3...

Album

castlefield Viaduct delapidation survey



Description

Photo 62 - Infill present to kerb junction. Damaged kerb visible on LHS of access road.

Taken date

24/09/2026 at 12:09

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:23

File name

F9FF2B0A-373E-44F0-A3E7-0411...

Album

castlefield Viaduct delapidation survey



Description

Photo 61 - Vegetation present, kerb infill detail shown. Damaged kerb to LHS of access road.

Taken date

24/09/2026 at 12:08

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:23

File name

0B75816B-6017-419A-8A03-990...

Album

castlefield Viaduct delapidation survey



Description

Photo 60 - Vegetation present to kerb abutment. Iron works raised to LHS of road with tarmac surround installed.

Taken date

24/09/2026 at 12:08

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:22

File name

23E1FF57-0269-489C-BCC4-D700...

Album

castlefield Viaduct delapidation survey



Description

Photo 59 - Vegetation present along both edges of kerb & road abutments. Infill detail to LHS kerb continues further down the line. Signa...

Taken date

24/09/2026 at 12:07

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:07

File name

22990334-ABFA-4078-9798-8A9A...

Album

castlefield Viaduct delapidation survey



Description

Photo 58 - Steel road plates installed in the road, appear to semi permanent measure with tarmac installed to perimeter edges which is no...

Taken date

24/09/2026 at 12:07

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:08

File name

706E0D9A-683B-44F0-9761-8E29...

Album

castlefield Viaduct delapidation survey



Description

Photo 57 - View down access road to carpark from start of bridge junction.

Taken date

24/09/2026 at 12:05

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:06

File name

250A4E11-144F-4EB5-998A-4FB0...

Album

castlefield Viaduct delapidation survey



Description

Photo 56 - Damage to 3 kerbs, RHS of access road viewed from photo 44.

Taken date

24/09/2026 at 12:05

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:06

File name

165452C1-993C-4ED0-A241-9F7...

Album

castlefield Viaduct delapidation survey



Description

Photo 55 - Raised ironworks and tarmac surround showing signs of depression, viewed from photo 44. Continuation of infill material betwee...

Taken date

24/09/2026 at 12:04

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:05

File name

699838CD-C276-4FD4-A6A4-B67...

Album

castlefield Viaduct delapidation survey



Description

Photo 54 - Damaged kerbs to LHS edge of access road, viewed from photo 44. Continuation of infill material between kerb and road surface ...

Taken date

24/09/2026 at 12:04

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:05

File name

D0EB6A37-FCB6-4DEF-83C8-C58...

Album

castlefield Viaduct delapidation survey



Description

Photo 53 - Damaged kerbs to LHS edge of access road, viewed from photo 44. Continuation of infill material between kerb and road surface ...

Taken date

24/09/2026 at 12:04

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:05

File name

E11AF547-7385-4D3F-AFB1-6BA...

Album

castlefield Viaduct delapidation survey



Description

Photo 52 - Damaged kerbs to LHS edge of access road, viewed from photo 44. Continuation of infill material between kerb and road surface ...

Taken date

24/09/2026 at 12:04

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:05

File name

0590DDED-46D3-4A34-AB67-4F7...

Album

castlefield Viaduct delapidation survey



Description

Photo 51 - Damage to 3 kerbs along the RHS of the access road to the carpark, as viewed from photo 44.

Taken date

24/09/2026 at 12:04

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:04

File name

21C50536-F76E-4BDF-A7EB-1FDF...

Album

castlefield Viaduct delapidation survey



Description

Photo 50 - Damaged kerbs on LHS of access road as viewed from photo 44.

Taken date

24/09/2026 at 12:03

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:04

File name

76471AD7-7EB5-4E73-AEA3-712...

Album

castlefield Viaduct delapidation survey



Description

Photo 49 - Damage visible to kerb down RHS of access road, viewed from photo 44.

Taken date

24/09/2026 at 12:03

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:04

File name

7175CD63-C4BA-4CB9-BD5B-8EB...

Album

castlefield Viaduct delapidation survey



Description

Photo 48 - Continuation of different surface material, down LHS road surface to kerb abutment.

Taken date

24/09/2026 at 12:02

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:04

File name

FDB71585-E869-4C6C-A1DE-E71...

Album

castlefield Viaduct delapidation survey



Description

Photo 47 - Aco drain protrudes existing road surface along RHS side kerb line.

Taken date

24/09/2026 at 12:02

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:04

File name

6BD7D472-E9DC-4A06-BC8F-DD...

Album

castlefield Viaduct delapidation survey



Description

Photo 46 - Raised ironworks with concrete perimeter surround to RHS of service road, viewed form photo 44. Concrete appears to be crackin...

Taken date

24/09/2026 at 12:01

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:04

File name

FAC8A07B-3F69-48C0-AA40-0ED...

Album

castlefield Viaduct delapidation survey



Description

Photo 45 - Raised ironworks with tarmac perimeter surround to LHS of service road, viewed form photo 44. Different material also present ...

Taken date

24/09/2026 at 12:01

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:03

File name

629AB8E7-49C5-44BA-81B6-CF6...

Album

castlefield Viaduct delapidation survey



Description

Photo 44- View of the access road to the carpark from start of Aloft by Marriott hotel.

Taken date

24/09/2026 at 12:01

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:01

File name

A8506B05-A9F0-4411-A073-DF95...

Album

castlefield Viaduct delapidation survey



Description

Photo 43 - Kerb line on LHS of service road, viewed from image 38 shows infill material on abutment between kerb and road surfacing.

Taken date

24/09/2026 at 12:00

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:01

File name

F1248D23-EDBB-4F62-AFD2-74A...

Album

castlefield Viaduct delapidation survey



Description

Photo 42 - Vegetation present to kerb line along the RHS of service road, as viewed from photo 38. Ironworks are also raised with build u...

Taken date

24/09/2026 at 12:00

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:01

File name

0A5E0CDC-2B5D-460D-B11B-0F4...

Album

castlefield Viaduct delapidation survey



Description

Photo 41 - Concrete infill around the MH cover appears to be failing with cracking visible.

Taken date

24/09/2026 at 11:59

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:01

File name

7CEC54C2-BE2D-4480-A99E-CD1...

Album

castlefield Viaduct delapidation survey



Description

Photo 40 - Tarmac ramp installed to crossing is failing at abutment with main road surface to RHS of service road. Perimeter demarcation ...

Taken date

24/09/2026 at 11:59

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:00

File name

5C691733-70C1-4EAD-8FCD-904...

Album

castlefield Viaduct delapidation survey



Description

Photo 39 - Tarmac ramp installed to crossing is failing at abutment with main road surface to LHS of service road. Perimeter demarcation ...

Taken date

24/09/2026 at 11:59

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:59

File name

D7B4F9EF-9609-4CA7-81AF-1328...

Album

castlefield Viaduct delapidation survey



Description

Photo 38 - View from crossing point on access road to carpark area.

Taken date

24/09/2026 at 11:58

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:59

File name

170CA00E-617D-4143-A066-71D...

Album

castlefield Viaduct delapidation survey



Description

Photo 37 - RHS of service road viewed from photo 33 shows concrete surface repair that in cracking at corner junctions. vegetation also p...

Taken date

24/09/2026 at 11:57

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:59

File name

9BB3AF72-D469-40E9-80C8-7B9...

Album

castlefield Viaduct delapidation survey



Description

Photo 36 - LHS kerb line showing further evidence of vegetation, abutment infill and pot hole appearing.

Taken date

24/09/2026 at 11:56

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 12:00

File name

B26C9A49-337C-4817-9057-596...

Album

castlefield Viaduct delapidation survey



Description

Photo 35 - LHS kerb line viewed from photo 33 shows infill at junction of kerb and road surface. Vegetation present at abutment junctions...

Taken date

24/09/2026 at 11:56

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:59

File name

B11D0422-23B7-453B-914F-0FBF...

Album

castlefield Viaduct delapidation survey



Description

Photo 34 - MH cover to centre of the road sunken. Road surfacing to perimeter is deteriorating.

Taken date

24/09/2026 at 11:56

Uploaded by

Karl Mcdonald

Upload date


24/09/2026 at 11:59

File name

37267091-0942-426D-BE02-9694...

Album

castlefield Viaduct delapidation survey



Description

Photo 33 - View of access road to carpark from barrier junction.

Taken date

24/09/2026 at 11:55

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:56

File name

1A6B342A-86E6-4A27-A71F-A219...

Album

castlefield Viaduct delapidation survey



Description

Photo 32 - Some slight damage to the barrier. Service trench scaring along line of barrier present. Infill done with different surface fi...

Taken date

24/09/2026 at 11:54

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:56

File name

AFFECE65-BC2C-4D61-AD1F-222...

Album

castlefield Viaduct delapidation survey



Description

Photo 31 - General condition of the road surfacing is poor in front of the barrier system. Looks like a central island may have been remo...

Taken date

24/09/2026 at 11:54

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:55

File name

E11FAEB0-BFFF-4870-ACD9-2926...

Album

castlefield Viaduct delapidation survey



Description

Photo 30 - Yellow box junction to the top of the ramp is faded.

Taken date

24/09/2026 at 11:54

Uploaded by

Karl Mcdonald

Upload date


24/09/2026 at 11:54

File name

A246F4FD-4AB3-4DA2-9890-759...

Album

castlefield Viaduct delapidation survey



Description

Photo 29 - Photo at the top of the ramp section looking towards the barrier to narrow section leading to Castlefield viaduct.

Taken date

24/09/2026 at 11:54

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:54

File name

A3A7A2D8-7D3A-4E80-A31D-686...

Album

castlefield Viaduct delapidation survey



Description

Photo 28 - Service trench scaring across the full width of the service road at the top of the ramp section. Circa 3m from RH turn.

Taken date

24/09/2026 at 11:52

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:54

File name

F9636B1E-A3B1-4BE3-AEEC-3C7...

Album

castlefield Viaduct delapidation survey



Description

Photo 27 - Brick pillar to the top of the ramp on LH side viewed from photo 25 shows lead flashings missing to base of pillar. Service tr...

Taken date

24/09/2026 at 11:52

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:54

File name

54D9A734-39B9-49C4-9C05-39C...

Album

castlefield Viaduct delapidation survey



Description

Photo 26 - Road marking faded on ramp section.

Taken date

24/09/2026 at 11:51

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:54

File name

0FEA77B7-8B4E-4C79-88CE-F31E...

Album

castlefield Viaduct delapidation survey



Description

Photo 25 - View further up the service road. general condition of the road surfacing and road markings visible.

Taken date

24/09/2026 at 11:50

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:53

File name

61801188-BE84-41E8-8259-7E95...

Album

castlefield Viaduct delapidation survey



Description

Photo 24 - No parking sign damaged on RH side of the ramp, viewed from photo 23 direction.

Taken date

24/09/2026 at 11:49

Uploaded by

Karl Mcdonald

Upload date


24/09/2026 at 11:52

File name

C450AA8F-30D2-4626-B2F2-B2A...

Album

castlefield Viaduct delapidation survey



Description

Photo 23 - View up the service road from bottom of ramp section.

Taken date

24/09/2026 at 11:49

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:50

File name

FAAE5231-8906-4AA5-8C96-7E51...

Album

castlefield Viaduct delapidation survey



Description

Photo 22- Sunken MH in centre of the service road. Service trench scaring visible and white lining fading.

Taken date

24/09/2026 at 11:48

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:50

File name

50AF2382-1745-4534-968D-AA1...

Album

castlefield Viaduct delapidation survey



Description

Photo 21 - Kerb damaged to RH side of road viewed from photo 17.

Taken date

24/09/2026 at 11:47

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:48

File name

2C565E2F-C644-4906-9FAD-6DE...

Album

castlefield Viaduct delapidation survey



Description

Photo 20 - Kerb damaged and vegetation present to kerb/ road abutment to RH side of service road, viewed from photo 17.

Taken date

24/09/2026 at 11:47

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:48

File name

CC62EAF8-D945-48A1-9E69-CA6...

Album

castlefield Viaduct delapidation survey



Description

Photo 19 - MH / Inspection cover has depression around the perimeter.

Taken date

24/09/2026 at 11:47

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:48

File name

BD65039D-C14B-4652-8285-38A...

Album

castlefield Viaduct delapidation survey



Description

Photo 18 - Service trench scaring to main road. Loading bay markings fading.

Taken date

24/09/2026 at 11:46

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:48

File name

09A7D836-D208-4FD3-B9EE-FE9...

Album

castlefield Viaduct delapidation survey



Description

Photo 17 - View down the service road. General condition of the road surfacing is poor, vegetation present at kerb abutments and line mar...

Taken date

24/09/2026 at 11:46

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:46

File name

D6D6E6E1-C3D0-47E8-AC89-737...

Album

castlefield Viaduct delapidation survey



Description

Photo 16 - Damaged kerbs to RHS of exit service road.

Taken date

24/09/2026 at 11:45

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:46

File name

D25FE3E3-9C3B-43A7-BF0E-5B7...

Album

castlefield Viaduct delapidation survey



Description

Photo 15 - General condition of the tarmac finish to the island is showing signs or wear. Cracking and depressions are present throughout.

Taken date

24/09/2026 at 11:43

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:46

File name

72D73D4C-7CFB-40A5-911F-9C0...

Album

castlefield Viaduct delapidation survey



Description

Photo 14 - Tarmac on the island is showing visible signs of cracking and areas have sunk in several places.

Taken date

24/09/2026 at 11:43

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:46

File name

66EB8ED3-BE47-43DE-A5B6-7C0...

Album

castlefield Viaduct delapidation survey



Description

Photo 13- point of the junction is damaged on radius kerb and adjacent kerbs on both faces.

Taken date

24/09/2026 at 11:43

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:46

File name

3AF2289E-2276-4E21-A5BF-443E...

Album

castlefield Viaduct delapidation survey



Description

Photo 12 - Shows photo of exit road junction to main carriageway. MH cover to Albion Rd has dropped with cracking of road surface visible.

Taken date

24/09/2026 at 11:43

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:46

File name

A820F01D-A07F-43F1-AA6E-FF4A...

Album

castlefield Viaduct delapidation survey



Description

Photo 11 - Inspection chamber to the footpath on LHS of service road, viewed in direction of photo 6 has sunk.

Taken date

24/09/2026 at 11:42

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:43

File name

ECE53ECE-B227-496F-BBE3-0391...

Album

castlefield Viaduct delapidation survey



Description

Photo 10 - Sunken kerb line, possible drop kerb crossing point along LHS of service exit road, viewed from photo 6. Pavement infill sunke...

Taken date

24/09/2026 at 11:41

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:44

File name

7AAE6CF9-8A23-4B42-A60C-4B7...

Album

castlefield Viaduct delapidation survey



Description

Photo 9 - Sunken kerb to RHS of exit road, viewed from photo 6 position.

Taken date

24/09/2026 at 11:41

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:43

File name

A3EBC31F-130A-4F07-A8FD-844A...

Album

castlefield Viaduct delapidation survey



Description

Photo 8 - Service trench scaring to main footpath along full length. Vegetation to perimeter edges.

Taken date

24/09/2026 at 11:40

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:43

File name

E6412825-DDB1-45C3-A6B0-A5D...

Album

castlefield Viaduct delapidation survey



Description

Photo 7 - Separation line in tarmac at the junction.

Taken date

24/09/2026 at 11:39

Uploaded by

Karl Mcdonald

Upload date


24/09/2026 at 11:43

File name

6DE2A894-9F92-4AB1-BF30-2E62...

Album

castlefield Viaduct delapidation survey



Description

Photo 6 - Exit side of the service road onto junction with main carriage way on Albion street. General condition shows vegetation to kerb...

Taken date

24/09/2026 at 11:39

Uploaded by

Karl Mcdonald

Upload date


24/09/2026 at 11:43

File name

6901A106-427B-48C0-8675-5732...

Album

castlefield Viaduct delapidation survey



Description

Photo 5 - General condition of the road upon entry at main junction. Service installation scaring to the road surface and fading white li...

Taken date

24/09/2026 at 11:38

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:38

File name

9BB30924-F30E-4243-807E-9FCC...

Album

castlefield Viaduct delapidation survey



Description

Photo 4 - Depressions in tarmac to north of traffic island, viewed from direction of photo 1

Taken date

24/09/2026 at 11:37

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:37

File name

1A43D9BB-CDDD-46CA-9FA5-A9...

Album

castlefield Viaduct delapidation survey



Description

Photo 3 - Tactile paving damage to crossing point, RHS viewed from direction of photo 1

Taken date

24/09/2026 at 11:36

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:37

File name

12157907-A833-4A40-97DF-C536...

Album

castlefield Viaduct delapidation survey



Description

Photo 2 - Tactile paving damage to crossing point, LHS viewed from direction of photo 1

Taken date

24/09/2026 at 11:36

Uploaded by

Karl Mcdonald

Upload date


24/09/2026 at 11:38

File name

0ECFBD60-9886-469F-B064-47B7...

Album

castlefield Viaduct delapidation survey



Description

Photo 1 - View of main junction on Albion Street to service road

Taken date

24/09/2026 at 11:34

Uploaded by

Karl Mcdonald

Upload date

24/09/2026 at 11:36

File name

1739F0E0-007D-45A9-8856-6106...

Album

castlefield Viaduct delapidation survey