

DO NOT SCALE FROM THIS DRAWING.
ALL DIMENSIONS TO BE CHECKED ON SITE.
(DRAWINGS MAYBE SCALED FOR LOCAL AUTHORITY & PLANNING PURPOSE ONLY)
COPYRIGHT PROTECTED.

FOR PLANNING
DO NOT USE FOR CONSTRUCTION

CONSULTANT REFERENCES IN DRAWING:

STRUCTURAL - REF/REVISION

WINDOW SCHEDULE								
REFERENCE	LOCATION	ELEVATION	HERITAGE TYPE	SIZE	FRAME	DESCRIPTION	SUITABLE FOR DOUBLE GLAZING	COMMENTS
W.L.2	STAIR LANDING	REAR	N/A	1000 x 1200	TIMBER	NEW CASEMENT WINDOW	NO	NO ACCESS ON INITIAL SURVEY
W.5.1	4th FLOOR	REAR	N/A	2180 x 1050	TIMBER	NEW CASEMENT WINDOW	NO	
W.5.2	4th FLOOR	ST.MARY'S	TYPE D	1084 x 1449	TIMBER	BOX SASH REPAIR	YES	
W.5.3	4th FLOOR	ST.MARY'S	TYPE D	1080 x 1450	TIMBER	BOX SASH REPAIR	YES	
W.5.4	4th FLOOR	ST.MARY'S	TYPE D	1080 x 1450	TIMBER	BOX SASH REPAIR	YES	
W.5.5	4th FLOOR	ST.MARY'S	TYPE D	1080 x 1450	TIMBER	BOX SASH REPAIR	YES	
W.5.6	4th FLOOR	DEANSGATE	CORNER	1100 x 1500	TIMBER	CASEMENT WINDOW REPAIR	NO	WIDTH APPROX ACROSS OPENING
W.5.7	4th FLOOR	DEANSGATE	TYPE D	1080 x 1459	TIMBER	BOX SASH REPAIR	YES	
W.5.8	4th FLOOR	DEANSGATE	TYPE D	1080 x 1450	TIMBER	BOX SASH REPAIR	YES	
W.5.9	4th FLOOR	DEANSGATE	TYPE D	1080 x 1450	TIMBER	FULL BOX SASH REPLACEMENT	NO	
W.5.10	4th FLOOR	DEANSGATE	TYPE D	1080 x 1450	TIMBER	BOX SASH REPAIR	YES	
W.5.11	4th FLOOR	DEANSGATE	TYPE D	1080 x 1450	TIMBER	BOX SASH REPAIR	YES	
W.5.12	4th FLOOR	REAR	N/A	1080 x 1450	TIMBER	BOX SASH REPAIR	YES	
W.5.13	4th FLOOR	REAR	N/A	820 x 930	TIMBER	NEW CASEMENT WINDOW	NO	
W.5.14	4th FLOOR	REAR	N/A	530 x 930	TIMBER	NEW CASEMENT WINDOW	NO	
W.L.3	3rd FLOOR	REAR	N/A	1200 x 3000	TIMBER	BOX SASH REPAIR	YES	
W.L.4	3rd FLOOR	REAR	N/A	1200 x 3000	TIMBER	BOX SASH REPAIR	YES	
W.4.1	3rd FLOOR	ST.MARY'S	TYPE C	1070 x 2115	TIMBER	BOX SASH REPAIR	YES	
W.4.2	3rd FLOOR	ST.MARY'S	TYPE C	1070 x 2115	TIMBER	BOX SASH REPAIR	YES	
W.4.3	3rd FLOOR	ST.MARY'S	TYPE C	1070 x 2115	TIMBER	BOX SASH REPAIR	YES	
W.4.4	3rd FLOOR	ST.MARY'S	TYPE C	1070 x 2115	TIMBER	BOX SASH REPAIR	YES	
W.4.5	3rd FLOOR	DEANSGATE	CORNER	1000 x 2150	TIMBER	NEW CASEMENT WINDOW	NO	WIDTH APPROX ACROSS OPENING
W.4.6	3rd FLOOR	DEANSGATE	TYPE C	1070 x 2115	TIMBER	BOX SASH REPAIR	YES	
W.4.7	3rd FLOOR	DEANSGATE	TYPE C	1070 x 2115	TIMBER	BOX SASH REPAIR	YES	
W.4.8	3rd FLOOR	DEANSGATE	TYPE C	1070 x 2115	TIMBER	BOX SASH REPAIR	YES	
W.4.9	3rd FLOOR	DEANSGATE	TYPE C	1070 x 2115	TIMBER	BOX SASH REPAIR	YES	
W.4.10	3rd FLOOR	DEANSGATE	TYPE C	1070 x 2115	TIMBER	BOX SASH REPAIR	YES	
W.L.5	3rd FLOOR	REAR	N/A	1000 x 1665	TIMBER	BOX SASH REPAIR	YES	
W.4.11	3rd FLOOR	REAR	N/A	400 x 1800	TIMBER	FULL BOX SASH REPLACEMENT	NO	
W.4.12	3rd FLOOR	REAR	N/A	1100 x 900	TIMBER	NEW CASEMENT WINDOW	NO	
W.3.1	2nd FLOOR	ST.MARY'S	TYPE B	1070 x 1900	TIMBER	BOX SASH REPAIR	YES	
W.3.2	2nd FLOOR	ST.MARY'S	TYPE B	1070 x 1900	TIMBER	BOX SASH REPAIR	YES	
W.3.3	2nd FLOOR	ST.MARY'S	TYPE B	1070 x 1900	TIMBER	BOX SASH REPAIR	YES	
W.3.4	2nd FLOOR	ST.MARY'S	TYPE B	1070 x 1900	TIMBER	BOX SASH REPAIR	YES	
W.3.5	2nd FLOOR	ST.MARY'S	CORNER	1000 x 1900	TIMBER	NEW CASEMENT WINDOW	NO	WIDTH APPROX ACROSS OPENING
W.3.6	2nd FLOOR	DEANSGATE	TYPE B	1070 x 1900	TIMBER	BOX SASH REPAIR	YES	
W.3.7	2nd FLOOR	DEANSGATE	TYPE B	1070 x 1900	TIMBER	BOX SASH REPAIR	YES	
W.3.8	2nd FLOOR	DEANSGATE	TYPE B	1070 x 1900	TIMBER	BOX SASH REPAIR	YES	
W.3.9	2nd FLOOR	DEANSGATE	TYPE B	1070 x 1900	TIMBER	BOX SASH REPAIR	YES	
W.3.10	2nd FLOOR	DEANSGATE	TYPE B	1070 x 1900	TIMBER	BOX SASH REPAIR	YES	
W.3.11	2nd FLOOR	REAR	N/A	1300 x 1650	TIMBER	BOX SASH REPAIR	YES	
W.3.12	2nd FLOOR	REAR	N/A	1300 x 1650	TIMBER	BOX SASH REPAIR	YES	
W.3.13	2nd FLOOR	REAR	N/A	700 x 1400	TIMBER	BOX SASH REPAIR	YES	
W.2.1	1st FLOOR	ST.MARY'S	TYPE A	1060 x 2140	TIMBER	DECORATION ONLY	-	WINDOW TO BE RETAINED WITH EX VENTING & GRILLS
W.2.2	1st FLOOR	ST.MARY'S	TYPE A	1060 x 2140	TIMBER	BOX SASH REPAIR	YES	
W.2.3	1st FLOOR	ST.MARY'S	TYPE A	1060 x 2140	TIMBER	BOX SASH REPAIR	YES	
W.2.4	1st FLOOR	REAR	N/A	500 x 1200	TIMBER	CASEMENT WINDOW REPAIR	YES	
W.2.5	1st FLOOR	REAR	N/A	450 x 860	TIMBER	NEW CASEMENT WINDOW	NO	
W.2.6	1st FLOOR	REAR	N/A	450 x 860	TIMBER	NEW CASEMENT WINDOW	NO	
W.2.7	1st FLOOR	REAR	N/A	450 x 1060	TIMBER	NEW CASEMENT WINDOW	NO	
W.2.8	1st FLOOR	REAR	N/A	450 x 860	TIMBER	NEW CASEMENT WINDOW	NO	
W.2.9	1st FLOOR	DEANSGATE	TYPE A	1060 x 2140	TIMBER	BOX SASH REPAIR	YES	
W.2.10	1st FLOOR	ST.MARY'S	TYPE A	1060 x 2140	TIMBER	EXTERNAL DECORATION ONLY	-	WINDOW TO BE RETAINED AS EXISTING AS INACCESSIBLE BEHIND EXISTING FREEZER
W.2.11	1st FLOOR	ST.MARY'S	CORNER	1100 x 2140	TIMBER	EXTERNAL DECORATION ONLY	-	WINDOW TO BE RETAINED AS EXISTING AS INACCESSIBLE BEHIND EXISTING FREEZER
W.2.12	1st FLOOR	DEANSGATE	TYPE A	1080 x 2140	TIMBER	EXTERNAL DECORATION ONLY	-	WINDOW TO BE RETAINED AS EXISTING AS INACCESSIBLE BEHIND EXISTING FREEZER
W.2.13	1st FLOOR	DEANSGATE	TYPE A	1080 x 2140	TIMBER	BOX SASH REPAIR	YES	
W.2.14	1st FLOOR	DEANSGATE	TYPE A	1080 x 2140	TIMBER	BOX SASH REPAIR	YES	
W.2.15	1st FLOOR	DEANSGATE	TYPE A	1080 x 2140	TIMBER	BOX SASH REPAIR	YES	
GENERAL NOTES								
- ALL DIMENSIONS APPROXIMATE AND TO BE CONFIRMED ON SITE PRIOR TO INSTALLATION/MANUFACTURE. - REFER TO WINDOW CONDITION SURVEY FOR ADDITIONAL INFORMATION ON EXISTING. - ALL FRAMING IN TIMBER TO BE RETAINED, REPAIRED AND/OR REPLACED AS REQUIRED. - ALL FRAMES IN WHITE PAINT TO BE RETAINED AS EXISTING. - ALL GROUND FLOOR SHOPFRONT WINDOWS TO BE RETAINED AS EXISTING.								

01	14/04/22	REVISED FOR PLANNING following consultant's comments	SO	ARB
REV	DATE	DESCRIPTION	DRAWN	CHECKED
A X I				
ADDRESS : 41 SOUTH KING STREET, MANCHESTER, M2 6DE TELEPHONE : +44 (0)161 879 7357 EMAIL : www.aki.studio COMPANY No : 11847325				
CLIENT				
CONWAY ESTATES LIMITED 58 MONEYMORE RD, MAGHERFELT, BT45 6HG				
PROJECT				
92-96 DEANSGATE MANCHESTER M3 2QG				
DRAWING REFERENCE				
WINDOW SCHEDULE				
JOB REFERENCE				
DRAWING SCALE				
DATE				
DRAWN				
CHECKED				
20-054				
NTS				
19/05/2021				
FWE				
ARB				
DRAWING REFERENCE No				
STAGE				
REV				
901				
4				
01				