

rot

Replace damage
area of timber

mold and rot
repair by Resin-base "Epoxy"



rot

Repair damage
timber by Epoxy

NOTE :
-

REMARK :
1.) NO unauthorized copying / reproduction permitted without expressed written permission.
2.) The contractor shall check all dimensions and level on site before commencement of work.
3.) No dimension to be scaled off this drawing.

LEGEND :
-

CLIENT :

PROJECT :
BARRACKS HOUSE
M15 4HA
-

DRAWING TITLE :
WINDOW INSPECTION RECORD

DRAWN	gw	feb/22
CHKD	-	-
SCALE	AS SHOWN	

rev	date	description
00		
12		
11		
10		
09		
08		
07		
06		
05		
04		
03		
02		
01		
00		

Revision / Version

DWG BH-P-002 00

JOB NO

GW 設計工作室有限公司
GARYWONG WORKSHOP LIMITED