

Sign A

Mechanically fixed by rawbolts - size and quantity to be determined by experienced installation operatives on site according to site conditions.

Signs B1, B2, C, D

Mechanically fixed by screws and rawplugs – size and quantity to be determined by experienced installation operatives on site according to site conditions. Indicative fixing method detailed on drawing 225778 The Unicorn (pl).pdf

Sign E

Mechanically fixed by rawbolts - size and quantity to be determined by experienced installation operatives on site according to site conditions.

Sign F

Mechanically fixed by screws and rawplugs – size and quantity to be determined by experienced installation operatives on site according to site conditions.

Sign G

Mechanically fixed by screws and rawplugs - size and quantity to be determined by experienced installation operatives on site according to site conditions. Indicative fixing method detailed on drawing 225778 The Unicorn (pl).pdf

Where signs and lighting are to replace existing items, existing holes will be used where possible to minimise penetrations into the building.