

Photographic Schedule

Demolition of existing structures in rear yard and erection of 3 no. residential apartments to the rear

Client: Nasser Khodadadi

Address: 82 Mauldeth Road West
Manchester
M20 1AB

Prepared by: CA&D Architects
Moss House
Moss Lane
Altrincham
WA15 6HS

Revision: A

Date of photographs: 17/09/2021

Date of Schedule: 06/09/2021

This schedule of photographs has been prepared in line with the ongoing COVID-19 Pandemic to fulfil the Planning Officers requests and help give a better indication about the current property and surrounding area. All photos were taken on the date/s stated above.

FRONT AND REAR STREETSCENES



Fig. 1IMG_20210906_134209_155.jpg



Fig. 2IMG_20210906_134210_640.jpg



Fig. 3IMG_20210906_134212_284.jpg



Fig. 4IMG_20210906_134214_032.jpg



Fig. 5IMG_20210906_134215_525.jpg



Fig. 6IMG_20210906_134217_457.jpg



Fig. 7IMG_20210906_134219_558.jpg



Fig. 8IMG_20210906_134224_608.jpg



Fig. 9IMG_20210906_134230_720.jpg



Fig. 10IMG_20210906_134327_482.jpg



Fig. 11IMG_20210906_134731_507.jpg



Fig. 12IMG_20210906_134733_143.jpg



Fig. 13 IMG_20210906_134734_860.jpg



Fig. 14 IMG_20210906_134736_374.jpg



Fig. 15 IMG_20210906_134737_948.jpg



Fig. 16 IMG_20210906_134739_453.jpg



Fig. 17 IMG_20210906_134741_042.jpg



Fig. 18 IMG_20210906_134742_665.jpg



Fig. 19IMG_20210906_134744_223.jpg



Fig. 20IMG_20210906_134839_330.jpg



Fig. 21IMG_20210906_134840_460.jpg



Fig. 22IMG_20210906_134849_046.jpg



Fig. 23IMG_20210906_134850_273.jpg



Fig. 24IMG_20210906_134852_613.jpg

VIEWS FROM WITHIN SITE



Fig. 25IMG 20210906 131151 282.jpg



Fig. 26IMG 20210906 131154 897.jpg



Fig. 27IMG 20210906 131157 039.jpg



Fig. 28IMG 20210906 131158 933.jpg



Fig. 29IMG 20210906 131201 111.jpg



Fig. 30IMG 20210906 131203 870.jpg



Fig. 31IMG_20210906_131205_148.jpg



Fig. 32IMG_20210906_131207_498.jpg



Fig. 33IMG_20210906_131209_143.jpg



Fig. 34IMG_20210906_131212_052.jpg



Fig. 35IMG_20210906_131213_625.jpg



Fig. 36IMG_20210906_131215_866.jpg



Fig. 37IMG_20210906_131218_702.jpg



Fig. 38IMG_20210906_131221_497.jpg



Fig. 39IMG_20210906_131231_935.jpg



Fig. 40IMG_20210906_131233_857.jpg



Fig. 41IMG_20210906_131237_350.jpg



Fig. 42IMG_20210906_131239_124.jpg



Fig. 43 IMG_20210906_131240_668.jpg



Fig. 44 IMG_20210906_131242_288.jpg



Fig. 45 IMG_20210906_131243_759.jpg



Fig. 46 IMG_20210906_131245_059.jpg



Fig. 47 IMG_20210906_131246_301.jpg



Fig. 48 IMG_20210906_131304_007.jpg



Fig. 49IMG_20210906_131305_549.jpg



Fig. 50IMG_20210906_131307_057.jpg



Fig. 51IMG_20210906_131309_790.jpg



Fig. 52IMG_20210906_131311_890.jpg



Fig. 53IMG_20210906_131313_243.jpg



Fig. 54IMG_20210906_131314_475.jpg



Fig. 55IMG_20210906_131315_768.jpg



Fig. 56IMG_20210906_131318_669.jpg



Fig. 57IMG_20210906_131323_404.jpg



Fig. 58IMG_20210906_131324_812.jpg



Fig. 59IMG_20210906_131327_548.jpg



Fig. 60IMG_20210906_131333_525.jpg





Fig. 61



Fig. 62



Fig. 63





Fig. 64





Fig. 65




Fig. 66



Fig. 67IMG_20210906_131420_460.jpg



Fig. 68IMG_20210906_131422_560.jpg



Fig. 69IMG_20210906_131424_160.jpg



Fig. 70IMG_20210906_131427_193.jpg



Fig. 71IMG_20210906_131436_902.jpg




Fig. 72IMG_20210906_131451_570.jpg



Fig. 73IMG_20210906_131455_418.jpg



Fig. 74IMG_20210906_131456_798.jpg



Fig. 75IMG_20210906_131517_973.jpg



Fig. 76IMG_20210906_131519_647.jpg



Fig. 77IMG_20210906_131521_944.jpg



Fig. 78IMG_20210906_131523_154.jpg



Fig. 79IMG_20210906_131524_444.jpg



Fig. 80IMG_20210906_131528_430.jpg



Fig. 81IMG_20210906_131529_985.jpg



Fig. 82IMG_20210906_131534_154.jpg



Fig. 83IMG_20210906_131541_287.jpg



Fig. 84IMG_20210906_131542_867.jpg



Fig. 85IMG_20210906_131549_223.jpg



Fig. 86IMG_20210906_131553_983.jpg



Fig. 87IMG_20210906_131555_937.jpg




Fig. 88IMG_20210906_132300_869.jpg



Fig. 89IMG_20210906_132307_173.jpg



Fig. 90IMG_20210906_132320_479.jpg



Fig. 91IMG 20210906 134301 223.jpg



Fig. 92IMG 20210906 134302 658.jpg



Fig. 93IMG 20210906 134327 482.jpg