

Mrs R.Akinlamilo
200 Blackley New Road
Blackley
Manchester
M9 8FQ

Treestyle Consultancy

BS5837:2012 Assessment

Tree ID : G1				Tag :				Assessor : Carl Riva				Bats :									
Species : A Group				TPO :				Inspected : 20 September 2021				Cons Area :									
--								Next Insp : Not Required													
Estimated Measurements												1st Branch: S 1									
Stems				Health				RP				Clearance (m)				Spread (m)					
H (m)	No	Eq Ø (mm)	Maturity	Crown	Stem	Basal	Phy Con	Cat	ERC	A (m²)	R (m)	Site Status	Priority	N	E	S	W	N	E	S	W
8	16	620	Mature	Poor	Fair	Fair	Fair	C.2	10 to 20 yrs	173.9	7.44	Pre Construction	N/A	0.5	1.5	0.5	2	12.5	1.5	1.5	12.5
Survey Comment : Group 16 Leylandii cypress. Suppressed & previously reduced crowns. Limited Longevity. Removed to facilitate Development.																					
Tree Comment :																					
Work Category				Action				Hours				Completed									
Fell				Fell and removes stump(s)								No									

Tree ID : G2				Tag :				Assessor : Carl Riva				Bats :									
Species : A Group				TPO :				Inspected : 20 September 2021				Cons Area :									
--								Next Insp : Not Required													
Estimated Measurements												1st Branch: N 3									
Stems				Health				RP				Clearance (m)				Spread (m)					
H (m)	No	Eq Ø (mm)	Maturity	Crown	Stem	Basal	Phy Con	Cat	ERC	A (m²)	R (m)	Site Status	Priority	N	E	S	W	N	E	S	W
8	3	191	Semi-mature	Fair	Fair	Fair	Fair	C.2	10 to 20 yrs	16.5	2.29	Pre Construction	N/A	2.5	2.5	2.5	2.5	2	3	2	3
Survey Comment : Group of 2 Prunus, Wild Cherry, Co-dominant stem. Included bark, Bark wounds. Occluding tissue. Leaf discoloration – potential leaf spot, fungal disease																					
Tree Comment :																					
Work Category				Action				Hours				Completed									
No action				No action								No									

BS5837:2012 Assessment

Tree ID : G3
Species : A Group
 --

Tag :
TPO :

Assessor : Carl Riva
Inspected : 20 September 2021
Next Insp : Not Required
1st Branch: N 4

Bats :
Cons Area :

Estimated Measurements

Stems			Health					RP		Clearance (m)				Spread (m)			
H (m)	No	Eq Ø (mm)	Maturity	Crown	Stem	Basal	Phy Con	Cat	ERC	A (m ²)	R (m)	Site Status	Priority	N	E	S	W
11	2	403	Mature	Fair	Fair	Fair	Fair	C.2	10 to 20 yrs	73.5	4.83	Pre Construction	N/A	4	4	4	4

Survey Comment : Group of 2 Maple, Fraxinus. Bark wounds/Occluding tissue. Poor pruning. Cross rubbing branches. Minor deadwood. Limited Inspection due to access

Tree Comment :

Work Category	Action
No action	No action

Hours	Completed
	No

BS5837:2012 Assessment

Report selection criteria.

Projects.

200 Blackley New Road

Date Range.

Any Date

Work types.

----> Fell :: Fell and removes stump(s)

----> No action :: No action

Latest Survey.

All surveys for the selected trees.

---> Last survey for each selected tree.

Work Completed.

---> Work Completed

---> Work Not Completed

Number of trees in selected Project(s) **3**

Number of trees in Report selection **3**