



14 January 2022

Reform Construction services ltd
53 Spear St, Manchester,
M1 1DF

RE: CDN/21/0944

To whom it may concern,

We acted on the above project as Principal Contractor and oversaw the groundworks package.

We are writing to confirm that the groundworks phase went as planned, excavation of existing basement fill contained no contaminants and upon breaking through the existing basement screed we were met with virgin clay ground which is where the new foundations were laid.

I have attached a few images showing the basement works and ground conditions we found.

Should you require further clarification don't hesitate to get in touch on the below number.

Yours sincerely,

Richard Frain

Managing Director

Reform construction services ltd

07875203576