

## HEATON PARK HORTICULTURAL CENTRE BOUNDARY WALL RE-BUILDING - EXISTING PHOTOGRAPHS



**Photo No.1** – View along the West Elevation Boundary Wall to the Horticultural Centre. Due to the walls instability, the area adjacent to it has been cordoned off and temporary raking shores erected.



**Photo No.2** – View along the West Elevation Boundary Wall to the Horticultural Centre.



**Photo No.3** – View of collapsed section of the West Elevation Boundary Wall where it meets the Southern Boundary to the Horticultural Centre.



**Photo No.4** – View showing cross section of boundary wall where collapse has occurred.



**Photo No.5** – View along South Elevation Boundary Wall to Horticultural Centre – Section of wall has collapsed completely.



**Photo No.6** – View along South Elevation Boundary Wall to Horticultural Centre – Section of wall has collapsed completely.



**Photo No.7** – View of trail hole at base of collapsed section of South Elevation Boundary Wall to Horticultural Centre. Wall was originally built with no foundation in sandy sub-strata.



**Photo No.8** – View of trail hole at base of West Elevation Boundary Wall to Horticultural Centre. Wall was originally built with no foundation in sandy sub-strata.