



Red line indicates revised cladding line. Cladding zone increased to accommodate insulation changes post Grenfell
see note 2 of HMA commentary