COVID-19 Risk Assessment

MCFS/COVID-19/RA

This Risk Assessment is to be read in conjunction with all other health & safety information. This RAMS deals only with the risk posed by COVID-19

Part 1 - Risk Assessment Details

Title.	RA Ref No.
Electrical Refurbishment	**MCFS/MC/WC/221-861**

Contract	Site
MC Construction Ltd	Westwood Cottages

Assessed by…	Approved by…
Ian Lowe	Ian Lowe

Part 2 - Review History

All Risk Assessments must as a minimum be reviewed annually. Once reviewed the updated document must be communicated to all those who use it. Once a document has been reviewed twice (or three years since it was created) it must be rewritten

Date Established: 03.06.2020

	Signature	Review date
Review 1 Reviewer: Mark Power		26.10.20
Review 2 Reviewer:		

Part 4 - Additional Safety Information

Details of related safety information; i.e. further documents required for the activity.

PPE is the last resort - Avoid shaking hands and comply with social distancing protocol.

Where works may affect others in the building or work area you must report to the Client Representative before starting to explain what you will be doing and obtain authority to work, you must comply with all rules and instructions given by the Client representative.

THIS RISK ASSESSMENT IS GENERIC, ENSURE LOCAL WORKPLACE HAZARDS AND SPECIFIC WORK ACTIVITY HAZARDS ARE ASSESSED PRIOR TO THE WORKS COMMENCING.

Risk Rating Matrix

1. All Risk Assessments must be written by a Competent Person
2. The Risk Rating should be determined using the matrix set out on the right.
3. Hazards should be assessed before and after determining what the control measures are to be.
4. Once a final Risk Rating has been established the rules set out below must be applied.

R	Red	Do not proceed – Re-assess
A	Amber	Review the Control Measures
G	Green	Proceed with activity

Contact the IMS Team for further guidance.



Part 3 - Hazards & Risks

What might go wrong? **(Hazard)**	Outcome or consequence **(Risk)**	Who could be affected? Select all relevant options. Specify "other" in the Additional Safety Information box.	To what extent? Select only one option. This Risk Rating is determined using the Risk Rating Matrix.	How we will stop this activity from going wrong? **(Control Measures)** Control measures should always seek to eliminate the hazards that are described.	This is how safe we have made it! Residual Risk. This Risk Rating is determined using the Risk Rating Matrix.
Access to site work area by unauthorised personnel	Possible spread of COVID-19	Employee Client Co-worker Contractor Public	(High) Red	When working in an area a minimum of 2m needs to be kept between persons.All doors/ access/ egress to be lept secured at all times to avoid unauthorised access Work areas to be cordoned/ barried off and suitable warning signs displayed as necessary to prevent unauthorised access	(Medium) Amber
Contact with materials/ Slipping & Tripping	Possible spread of COVID-19	Employee Co-worker Contractor Client	(High) Red	PPE to be worn at all times If working in or accessing through a high risk or high traffic area, FFP3 disposable mask, disposible gloves and Cat3 Type5/6 disposable coverall must be worn	(Medium) Amber

Contact with Infected Surfaces	Infection and spread of COVID-19	Employee Co-worker Contractor Public	(High) Red	Washing hands for 20 seconds is required regularly and sanitiser to be used where possible Minimum 2 metre distance to be observed from any persons Where 2 metre distance is not possible PPE must be worn, FFP3 masks, nutrile gloves Windows to be kept open where possible Work areas to be thoroughly cleaned Where possible implement a "1 man 1 room" working policy Doors to be opened with sterile wipes if possible. If not feet, elbows or shoulders and gloved hands as the last resort All hop ups, ladders, scaffold handrails are to be regularly cleaned	(Medium) Amber

