


Items in Need of Repair	
ITEM	ACTION
1	All Windows cleaned and repaired where required
2	Graffiti to be removed and brickwork cleaned
3	Brickwork spalling and staining to be rectified
4	Repair or replace like for like roof tiles that are damaged
5	Damp by skylight to be rectified
6	Degradation at basement level. To be repaired




1 South Elevation
1 : 100



2 East Elevation
1 : 100



3 North Elevation
1 : 100



4 West elevation
1 : 100

revision	date	drawn	description
-	06.03.20	TH3M	Issued For Planning

Do not scale from drawings unless by agreement with architect. Use figured dimensions only. Check all dimensions on site prior to commencing the works. Drawing to be read in conjunction with other relevant consultant information.

This drawing is the copyright of TH3M Architects Ltd and must not be copied or reproduced in part, or in whole, without the express permission of the architect. Drawing to be read in conjunction with specification.

T H ∃ M

0m 2m 4m 6m 8m 10m

Elevations - Restoration Notes
Existing

MKCC Parsonage St

T-0230-2-0004-Elevations - ~~Res~~toration Notes

-
revision

1:100 @ A1
scale

0230
job reference

MGS
drawn

FOR PLANNING