

P17

Building has now been insulated and installed in accordance with the approved details, these have been inspected by MBC as the works have progressed down the floors.