Exterior Side Elevation

Scope of Works

1.1 Re-finish existing wordmark black
1.2 Re-paint signage fascia grey
1.3 Replace existing blade sign logo with new logo
1.4 Repaint existing light fittings to match signage fascia
1.5 Make good conduit at side entrance





Existing Storefront



Proposed Storefront