
PANEL 6





Structure currently exposed to be made good but moulding not recreated

Area missing. Lime-based plaster moulding to be repaired.

Area missing. Lime-based plaster ceiling to be repaired.

Structure currently exposed. Plaster moulding to be repaired.

Area missing. Lime-based plaster moulding to be repaired.

C

A

5

4

ALL SMALL MISSING AREAS TO BE REPAIRED

St James Basement

Ceiling plan detail
Panel 6

scheme 1552
no. **P(116)**
rev -

scale **1:50@A4**
date 17 Apr 2014
drawn CP

Atelier MB Urban Architects
www.ateliermb.co.uk
t 0161 236 0051
e architect@ateliermb.co.uk

COPYRIGHT OF ATELIER MB LTD
DO NOT SCALE FROM THIS DRAWING
DIMENSIONS TO BE CHECKED ON SITE

***SK** sketch **P** proposed **T** tender **C** construction **AB** asbuilt*