
CRL
CONCRETE REPAIRS LIMITED
multi-disciplined *structural* renovation


Zone 16


Defect Survey

CRL
CONCRETE REPAIRS LIMITED
multi-disciplined *structural* renovation

Defect Survey Sheet







Notes

The parts of the drawings which are shaded in have not been surveyed as they are not yet accessible and will have to be surveyed separately.

Throughout the zone there are a few cracks which run up the corners of the columns in the mortar joints, these are numbers 5, 10, 14, 15, 24, 40, 47.

There are also two large cracks which are repairs number 17 and 24.

Photo References






3


4


5


6


7


8


9


10


11


12
13


14


15


16


18


17



19
20


21


22


23


24


25


26


27


28


30


29


31


32
33


34


35


36



37



38


39


40


41


44
43
42


46
45


47


48


49


50

CRL
CONCRETE REPAIRS LIMITED
multi-disciplined *structural* renovation

