

PORTLAND ST WINDOW SCHEDULE

Portland st (NW GROUP

Wednesday 3 July 2024

Prepared For Nw Group

58 Issues Identified



W4B1

Restoration of existing sash window
Replacement glass with new 12mm heritage glass
Replacement cill section with new hardwood cill



W4B2

Restoration of existing sash window
Replacement glass with new 12mm heritage glass
Replacement cill section with new hardwood cill



W4B3

Restoration of existing sash window
Replacement glass with new 12mm heritage glass
Replacement cill section with new hardwood cill



W4B5

Restoration of existing sash window
Replacement glass with new 12mm heritage glass
Replacement cill section with new hardwood cill



W4B6

Restoration of existing sash window
Replacement glass with new 12mm heritage glass
Replacement cill section with new hardwood cill



W4B7

These windows are currently direct glazed modern timber frames installed into the existing box sash frames. These old original sash frames must have been removed from site.

We propose 2 new sash's to install into the existing box frames to match all other windows with 12mm heritage glass.

Replace any rotten cills



W3B1

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W3B2

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W3B3

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W3B4

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



WB35

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



WB36

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W3B7

These windows are currently direct glazed modern timber frames installed into the existing box sash frames. These old original sash frames must have been removed from site.

We propose 2 new sash's to install into the existing box frames to match all other windows with 12mm heritage glass.

Replace any rotten cills




W2B1

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W2B2

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W2B3

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W2B4

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W2B5

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill




W2B6

These windows are currently direct glazed modern timber frames installed into the existing box sash frames. These old original sash frames must have been removed from site.

We propose 2 new sash's to install into the existing box frames to match all other windows with 12mm heritage glass.

Replace any rotten cills




W2B7

These windows are currently direct glazed modern timber frames installed into the existing box sash frames. These old original sash frames must have been removed from site.

We propose 2 new sash's to install into the existing box frames to match all other windows with 12mm heritage glass.

Replace any rotten cills



W1B7

These windows are currently direct glazed modern timber frames installed into the existing box sash frames. These old original sash frames must have been removed from site.

We propose 2 new sash's to install into the existing box frames to match all other windows with 12mm heritage glass.

Replace any rotten cills



W1B2

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W1B3

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W1B4

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W1B5

These windows are currently direct glazed modern timber frames installed into the existing box sash frames. These old original sash frames must have been removed from site.

We propose 2 new sash's to install into the existing box frames to match all other windows with 12mm heritage glass.

Replace any rotten cills



W1B6

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W1B7

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill

WGB1

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



WGB2

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



WGB3

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



WGB5

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill

WGB4 LIFT SHAFT

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



WGB6

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W4F6

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W4F5

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W4F4

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W4F3

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W4F2


Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W4F1



W3F6

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W3F5

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W3F4

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W3F3

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W3F2

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W3F1

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W2F6

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W2F5

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W2F4

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W2F3

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W2F2

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W2F1

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W1F6

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W1F5

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W1F4

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W1F3

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W1F2

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



W1F1

Restoration of existing sash window

Replacement glass with new 12mm heritage glass

Replacement cill section with new hardwood cill



1FW5 , 6 , 7 , 8

These windows are currently direct glazed modern timber frames installed into the existing box sash frames. These old original sash frames must have been removed from site.

We propose 2 new sash's to install into the existing box frames to match all other windows with 12mm heritage glass.

Replace any rotten cills