
CONCRETE REPAIRS LIMITED
multi-disciplined *structural* renovation

Zone 3

Defect Survey


Defect Survey Sheet




Repair Survey

■ - Repairs

■ - Cracks.



Spring Garden Return



Brown Street Return

Notes


Numbers 19 and 20 have already been highlighted on the Zone 15 repair survey, as numbers 39 and 40, as repairs that will need further review and inspection.

There are some areas above the windows which may also need further review, show in the numbers 27, 28, 29 and 50.


Photo References







5


7
6


8



9


10


12
11



13


14


16
15


17


18


20


19


21


22


23


24



25



26


27


28


29


30


31



32
33


34


35


36


37
38
39


40
41


42


44
43


45


46


47



48


49


51
52


50


53


54


55


56


57


58


59


60


61


62


63


64


65


66


67