
CRL
CONCRETE REPAIRS LIMITED
multi-disciplined *structural* renovation

Zone 4

Defect Survey


CONCRETE REPAIRS LIMITED
multi-disciplined *structural* renovation

Defect Survey Sheet




■ - Repairs
● - Cracks

Zone 4 Repair Survey



Spring Garden Return



Brown Street

Notes

As with Zone 16 not all the zone is accessible via the scaffold, these parts have been highlighted on the drawing and will have to be surveyed later when we have access to the terrace and the roof.

The main parts of concern for this zone are a number of large cracks running up the sides of the cylinder columns in several different places, these are shown through numbers 1, 15, 16, 17, 22 and 31.

Photo References







5
3
4


6


7


8


9


10


11


11a


14
12
13


15


16


17


18


19


20


21


22


23


24
25


26
27


28


29


30


31


32


33


34


35


36


37


38



39


40


41


42


43


45
44


46


47



48


49


50


51


52


55
54
53