
CRL
CONCRETE REPAIRS LIMITED
multi-disciplined *structural* renovation

Zone 15

Defect Survey

Defect Survey Sheet




Notes


There are several repairs to be reviewed on Zone 15. There are several large previous repairs above the windows on this Zone highlighted with the numbers 12, 13, 18, 19, 26, 27, 28, 29, 30, 32, 38, 39, 40 and all of these run next to where the system is going to be placed in. Please find below the photo references to these and the other repairs.


On the photos the green chalk shows where the system will be.


CONCRETE REPAIRS LIMITED
multi-disciplined *structural* renovation

Photo References











5



6



7
8


9


11



10


12


13
14


15


16


17



19



18



20


21
22


24
23


25


28
27
26



31


29
30


32



33


41



34
35
36


37



38
39


40



43
42


44



45


47


46



48


49


50


51


52



53


54
55



56



58


59


60



61


62


63


64


65




70
69
68
67


71


72


73


74



75


76


77
R15-3


78


79


81
80



82


83



84



85


86


87


88


89
90


91
92


93



94


95


96


97


98


99


100
101


102


103


104


105


57