

Method Statement for Removal of Metal Access Ladder

Existing metal vertical ladder has been assessed by structural Engineer as being unsafe and not fit for purpose for safe access to the different area of roofs.

We are proposing to remove the vertical ladder by using a metal grinder to cut the ladder into smaller sections using a scaffold lift. Once the ladder has been removed the masonry will be repaired either with a new reclaimed brick or with repair as previously agreed for other brick masonry repairs.

