



117 119 Portland Street Fabric Repair Sample

PHOTOGRAPHS OF EXISTING DAMAGE & SAMPLE REPAIR



Figure 1.0 - Existing holes for previous sign and handrail



Figure 2.0 - Sign holes repaired with colour match sample mortar repair



Figure 3.0 - Old handrail holes with colour match sample mortar repair



Figure 4.0 - Old handrail fixing holes



Figure 5.0 - Old handrail holes with colour match sample mortar repair

APPENDIX A

Proposed repair mortar colour match - MASON MORTAR STONE REPAIR MORTAR - COLOUR 10S



- Proposed colour reference - 10S



- Proposed colour match



- Proposed colour match on alternative side of opening