

Stone indent repair to Great Hall south-west cornice



Remove remnants of lead and cut opening square as indicated

125

Joint

Indent manufactured from stone reclaimed from elsewhere on site. Minimum depth 125mm

Revision: -
First issue
Date: 20 June 2024

OTH-PUR-EX-ZZ-SKE-A-3670