




CIS Tower,
Miller Street,
Manchester.
M60 0AL.

CIS Tower Refurbishment.

Recording Strategy and Photographic Audit of internal & external features.

APPENDIX 28 – LEVEL 22. INTERNAL.

Planning Permission ref: 126118/FO/2020. Condition 29.

&

LBC ref: 126119/LO/2020. Condition 10.

Prepared by:



Stephen Levrant Heritage Architecture Ltd
Canada House, Suite 1.6
3 Chepstow Street
www.heritagearchitecture.co.uk

Prepared for:
Devonshire (CIS Tower) Ltd.
27 October 2020.



CIS Tower. Appendix 28 - Level 22 Recording Strategy and Photographic Audit of internal features, 2020.

All rights reserved.

Copyright © Stephen Levrant: Heritage Architecture Ltd.

Whilst copyright of this report as a whole is vested in Stephen Levrant: Heritage Architecture Ltd., copyright of individual contributions regarding sections of referenced works belongs to their respective authors, and no part may be reproduced, transmitted, stored in a retrieval system in any form or by any means whether electronic, mechanical, via photocopying, recording or otherwise, without the previous consent of the author.

Stephen Levrant: Heritage Architecture Ltd.

Document production © Stephen Levrant: Heritage Architecture Ltd 2020.

Final issued: 27 October 2020

Heritage Architecture Ltd is Registered in England, Number 3053944 • VAT GB656883581.

Registered office: 5 Technology Park, Colindeep Lane, Colindale, London NW9 6BX

Correspondence to be addressed to 62 British Grove, London, W4 2NL; or: Suite 1.06, Canada House, Chepstow Street, Manchester M1 5FW

FLOOR LEVEL 22. Typical tower office workspace.**Level 22. Context and general character.**

- i) Floor level 22 (photographed on 16 September 2020) is an illustrative example of the extant form of the cleared, standard tower office workspaces which face Miller Street.
- ii) In common with the entire building the office floor has been comprehensively altered, retaining none of the original Design Research Unit (DRU) designed interior furniture, furnishings and decorative details.
- iii) The floor plan has been heavily altered from its original 1962-plan form by means of the movement and removal of office partitions. The floor was originally designed to house the secretarial staff to the executives on floors 23 and 24
- iv) The floor-coverings, ceilings, lighting, heating and ventilation have all been substantially altered from the original layout.
- v) The lift lobby retains original doors, although with upgraded fire-protection, but the lift cars are an early C21st replacement.
- vi) Refer to the below plan for the location and direction of views.



22-01 View through lift lobby looking north.



22-02 View of original timber double doors to office space.



22-03 View north towards Miller Street as you enter the office space.



22-04 View south across office space back towards the lift lobby.



22-05 View south across office space.




22-06 View west across office space.



22-07 View within east stairwell.



22-08 View within female WC looking towards the sink and original glazed screen to the right-hand side.



22-09 View within west stairwell.



22-10 View within men's WC with original glazed screen and non-original sink, fixtures, fittings, wall finishes and vinyl floor covering.



22-11 Detail of terrazzo floor covering to stairwell,



22-12 View of curtain walling and Weathermaster.



22-13 View of partition screen and Telelift outlet.




Figure 1. Location and direction of **Level 22**. Extract from Hollis drg.no.: 79048-HLS-00-ZZ-22-M3-G-10800

