



RUTHERFORD BUILDING REFURBISHMENT

Cornice Survey

Submitted by Arcadis
May 2025



Ground Floor




Image 1



Image 2




Image 2i




Image 3



Image 3i



Image 4



Image 4i



Image 4ii



Ground Floor




Image 5



Image 6



Image 6i



Image 7



Image 7i



Image 8



Image 9



Image 11



Ground Floor




Image 10



Image 10i



Image 11i



Image 12



Image 13



Image 14



Image 15



Image 15i





Ground Floor




Image 16



Image 17



Image 18



Image 19



Image 20



Ground Floor




Image 63



Image 64



Image 65



Image 66



Image 67



Image 68



Image 69



First Floor




Image 70



Image 71



Image 72



Image 73



Image 74



Image 75



Image 76



Image 77



First Floor




Image 21



Image 22



Image 23



Image 24



Image 25



Image 26



Image 26i



Image 27



First Floor




Image 27i



Image 28



Image 28i



Image 29



Image 29i



Image 30



Image 31



Image 31i



First Floor




Image 32



Image 33



Image 34



Image 35



Image 36



Image 37



Image 38



Image 39



First Floor




Image 40



Image 41



Image 42



Image 43



Image 43i



Image 44



Image 45



First Floor




Image 46



Image 47



Image 48



Image 48i



Image 49



Image 50



Image 51



Image 52



Second Floor




Image 53



Image 54



Image 54i



Image 55



Image 55i



Image 56



Image 56i



Image 56ii



Second Floor




Image 57



Image 57i



Image 58



Image 59



Image 59i



Image 60



Image 61



Image 62







CONTACT US

Dantzic Building
Fourth Floor
Dantzic Street
Manchester M4 2AL

Tel: +44 161 696 4980
www.ibigroup.com