ATELIER.MB

SAMPLE SIGN OFF SHEET

Project 2045 | Midland West Entrance - Fire
Issued

NO.	TYPE	NBS REF.	LOCATION	DETAILS	DATE	AGREED WITH ARCHITECT	AGREED WITH PLANNER/CO
7	Recreation of faience in mortar, and pointing.	n/a – refer to BC methodology.	Front elevation	Bedding and repointing to mortar repairs Mix: 2 Waddington 1 white silica 1 3.5NHL lime 2 tablespoon black natural earth pigment ½ an equal measure of clinker. Mortar repairs in Monolite Class R2 Lightweight Repair Mortar	25-05-23	Y	

Image 1	Image 2
Existing – faience, and fire damaged fibreglass 	Proposed mortar sample in situ, and glazed effect sample (please note that this colour is not finalised as site trials are ongoing. Sample can be viewed by CO prior to proceeding. 