

Whitecarr Lane, Wythenshawe

Dilapidaiton Report **Revision 1 (01/04/25)**



Contents:

1. Introduction

2. Appendices


- I. Photograph Location Drawing**
- II. Photographs**

1. Introduction

JG Engineering had been instructed to carry out a dilapidation report for JCT building services of the road condition of Whitecarr lane either side of the site entrance. The survey has also included a small part of Newall Road up until the speed bumps. Photo locations have been recorded using a RTK GPS rover on OS national grid. A photograph location drawing has been produced to show and reference each photos position. Any notable damage has then been marked on the photo in a yellow callout box.

2. Appendices

I. Photograph Location Drawing



II. Photographs

