


JDW Waterhouse, Manchester


Thursday 16 January 2025

Prepared For Empowered

13 Identified

AMENDED 30.01.25 - HARRISON INCE

AMENDED 03.02.25 - HARRISON INCE



Main Office Basement
Hole will need to be drilled here to get 2 new cables through for AP01-03





CABLE will need to cut across and hole drilled here to get cables through



Ground Floor Stairwell
Cabling will come through here above door, can either be tacked to wood boxing in o



Ground Floor Stairwell
tac across wooden boxing in



Ground Floor Stairwell




Ground Floor Stairwell

CABLE ALONG SKIRTING UP THE STAIRCASE





1st Floor Stairwell



1st Floor Stairwell

hole will need to be drilled through interior wall



1st Floor Corridor


hole drilling through internal wall



1st Floor Corridor

hole drilling through internal wall

PICTURE OF LOCATION



New AP Location

Back box mounted on other side of wall and drilled through, AP mounted where circle shows