

1. A general view of the rooflights.



2. A general view of the rooflights.



3. A general view of the rooflights.



4. A general view of the rooflights.



5. The rooflight that is due to be removed and re-covered with a zinc material to match the existing roof.



6. The condition of perimeter flashing of one of the rooflights.



7. A zoomed in photo of the condition of one of the rooflights.



8. An internal picture of the rooflight. All of the rooflights look the same internally.



9. A view of the small rooflight in Flat 23. This is the only rooflight of this size that is down for replacement.