Photographic Record: Capping Layer Depth Validation

Project: Gorton Lane, North, 'Site 1'.
Sheet: 24

Plot: Plot 12 (Front)
Hole: HP24









Curtins Consulting Ltd
17-19 Whitworth Street West, Manchester, M1 5WG
0161 236 2394 manchester@curtins.com www.curtins.com

Photographic Record: Capping Layer Depth Validation

Project: Gorton Lane.
Sheet: 25

Hole: HP25





Curtins Consulting Ltd
17-19 Whitworth Street West, Manchester, M1 5WG
0161 236 2394 manchester@curtins.com www.curtins.com

Photographic Record: Capping Layer Depth Validation

Project: Gorton Lane.
Sheet: 26

Hole: HP26





Curtins Consulting Ltd
17-19 Whitworth Street West, Manchester, M1 5WG
0161 236 2394 manchester@curtins.com www.curtins.com

Photographic Record: Capping Layer Depth Validation

Project: Gorton Lane.
Sheet: 27

Hole: HP27





Curtins Consulting Ltd
17-19 Whitworth Street West, Manchester, M1 5WG
0161 236 2394 manchester@curtins.com www.curtins.com

Photographic Record: Capping Layer Depth Validation

Project: Gorton Lane.
Sheet: 28

Hole: HP28





Curtins Consulting Ltd
17-19 Whitworth Street West, Manchester, M1 5WG
0161 236 2394 manchester@curtins.com www.curtins.com

Photographic Record: Capping Layer Depth Validation

Project: Gorton Lane.
Sheet: 29

Hole: HP29





Curtins Consulting Ltd
17-19 Whitworth Street West, Manchester, M1 5WG
0161 236 2394 manchester@curtins.com www.curtins.com

Photographic Record: Capping Layer Depth Validation

Project: Gorton Lane.
Sheet: 30

Hole: HP30





Curtins Consulting Ltd
17-19 Whitworth Street West, Manchester, M1 5WG
0161 236 2394 manchester@curtins.com www.curtins.com

Photographic Record: Capping Layer Depth Validation

Project: Gorton Lane.
Sheet: 31

Hole: HP31





Curtins Consulting Ltd
17-19 Whitworth Street West, Manchester, M1 5WG
0161 236 2394 manchester@curtins.com www.curtins.com

Photographic Record: Capping Layer Depth Validation

Project: Gorton Lane.
Sheet: 32

Hole: HP32





Curtins Consulting Ltd
17-19 Whitworth Street West, Manchester, M1 5WG
0161 236 2394 manchester@curtins.com www.curtins.com

Photographic Record: Capping Layer Depth Validation

Project: Gorton Lane.
Sheet: 33

Hole: HP33





Curtins Consulting Ltd
17-19 Whitworth Street West, Manchester, M1 5WG
0161 236 2394 manchester@curtins.com www.curtins.com

Photographic Record: Capping Layer Depth Validation

Project: Gorton Lane.
Sheet: 34

Hole: HP34





Curtins Consulting Ltd
17-19 Whitworth Street West, Manchester, M1 5WG
0161 236 2394 manchester@curtins.com www.curtins.com

Photographic Record: Capping Layer Depth Validation

Project: Gorton Lane.
Sheet: 35

Hole: HP35





Curtins Consulting Ltd
17-19 Whitworth Street West, Manchester, M1 5WG
0161 236 2394 manchester@curtins.com www.curtins.com

Photographic Record: Capping Layer Depth Validation

Project: Gorton Lane.
Sheet: 36

Hole: HP36





Curtins Consulting Ltd
17-19 Whitworth Street West, Manchester, M1 5WG
0161 236 2394 manchester@curtins.com www.curtins.com

Photographic Record: Capping Layer Depth Validation

Project: Gorton Lane.
Sheet: 37

Hole: HP37





Curtins Consulting Ltd
17-19 Whitworth Street West, Manchester, M1 5WG
0161 236 2394 manchester@curtins.com www.curtins.com

Photographic Record: Capping Layer Depth Validation

Project: Gorton Lane.
Sheet: 38

Hole: HP38





Curtins Consulting Ltd
17-19 Whitworth Street West, Manchester, M1 5WG
0161 236 2394 manchester@curtins.com www.curtins.com

Photographic Record: Capping Layer Depth Validation

Project: Gorton Lane.
Sheet: 39

Hole: HP39





Curtins Consulting Ltd
17-19 Whitworth Street West, Manchester, M1 5WG
0161 236 2394 manchester@curtins.com www.curtins.com

Photographic Record: Capping Layer Depth Validation

Project: Gorton Lane.
Sheet: 40

Hole: HP40





Curtins Consulting Ltd
17-19 Whitworth Street West, Manchester, M1 5WG
0161 236 2394 manchester@curtins.com www.curtins.com

Photographic Record: Capping Layer Depth Validation

Project: Gorton Lane.
Sheet: 41

Hole: HP41





Curtins Consulting Ltd
17-19 Whitworth Street West, Manchester, M1 5WG
0161 236 2394 manchester@curtins.com www.curtins.com

Photographic Record: Capping Layer Depth Validation

Project: Gorton Lane.
Sheet: 42

Hole: HP42





Curtins Consulting Ltd
17-19 Whitworth Street West, Manchester, M1 5WG
0161 236 2394 manchester@curtins.com www.curtins.com

Photographic Record: Capping Layer Depth Validation

Project: Gorton Lane.
Sheet: 43

Hole: HP43





Curtins Consulting Ltd
17-19 Whitworth Street West, Manchester, M1 5WG
0161 236 2394 manchester@curtins.com www.curtins.com

Photographic Record: Capping Layer Depth Validation

Project: Gorton Lane.
Sheet: 44

Hole: HP44





Curtins Consulting Ltd
17-19 Whitworth Street West, Manchester, M1 5WG
0161 236 2394 manchester@curtins.com www.curtins.com

Photographic Record: Capping Layer Depth Validation

Project: Gorton Lane.
Sheet: 45

Hole: HP45





Curtins Consulting Ltd
17-19 Whitworth Street West, Manchester, M1 5WG
0161 236 2394 manchester@curtins.com www.curtins.com

Photographic Record: Capping Layer Depth Validation

Project: Gorton Lane.
Sheet: 46

Hole: HP46





Curtins Consulting Ltd
17-19 Whitworth Street West, Manchester, M1 5WG
0161 236 2394 manchester@curtins.com www.curtins.com

Photographic Record: Capping Layer Depth Validation

Project: Gorton Lane.
Sheet: 47

Hole: HP47





Curtins Consulting Ltd
17-19 Whitworth Street West, Manchester, M1 5WG
0161 236 2394 manchester@curtins.com www.curtins.com

Photographic Record: Capping Layer Depth Validation

Project: Gorton Lane, North, 'Site 1'.
Sheet: 48

Plot: Plot 6 (Front)
Hole: HP22A







Curtins Consulting Ltd
17-19 Whitworth Street West, Manchester, M1 5WG
0161 236 2394 manchester@curtins.com www.curtins.com

Appendix C – Imported Soils Analysis

Copyright © 2023 Curtins Consulting Ltd

TIM O'HARE ASSOCIATES
SOIL & LANDSCAPE CONSULTANCY

Mr Nathan Birchenall
Tarmac Topscape
Manchester Road
Congleton
Cheshire, CW12 2LU

1st July 2022
Our Ref: TOHA/22/7546/SS
Your Ref: PO 00509067

Tarmac Topscape

Dear Sirs

Topsoil Analysis Report: Topscape Topsoil (Crown Farm)

We have completed the analysis of the soil sample recently submitted, referenced *Topscape Topsoil (Crown Farm)*, and have pleasure reporting our findings.

The purpose of the analysis was to determine the suitability of the sample for general landscape purposes (trees, shrubs, amenity grass). In addition, this sample has been assessed to determine its compliance with the requirements of the British Standard for Topsoil *(BS3882:2015 – Specification for Topsoil - Table 1, Multipurpose Topsoil)*.

This report presents the results of analysis for the sample recently submitted to our office, and it should be considered 'indicative' of the topsoil source. The report and results should therefore not be used by third parties as a means of verification or validation testing or waste designation purposes, especially after the topsoil has left the Tarmac Topscape site.

SAMPLE EXAMINATION

The sample was described as a dark brown (Munsell Colour 10YR 3/3), slightly moist, friable, very slightly calcareous LOAMY SAND with a single grain structure*. The sample was slightly stony and contained a moderately high proportion of organic fines and occasional woody fragments. No unusual odours, deleterious materials, roots or rhizomes of pernicious weeds were observed

.*This appraisal of soil structure was made from examination of a disturbed sample(s). Structure is a key soil characteristic that may only be accurately assessed by examination in an in-situ state.

ANALYTICAL SCHEDULE

The sample was submitted to a UKAS and MCERTS accredited laboratory for a range of physical and chemical tests to confirm the composition and fertility of the soil, and the concentration of selected potential contaminants. The following parameters were determined:

- detailed particle size analysis (% 5 sands, silt, clay);
- stone content (2-20mm, 20-50mm, >50mm);
- pH and electrical conductivity values;
- exchangeable sodium percentage;
- major plant nutrients (N, P, K, Mg);
- organic matter content;
- C:N ratio;
- heavy metals (As, B, Cd, Cr, Cu, Pb, Hg, Ni, Se, Zn);
- total cyanide and total (mono) phenols;
- speciated PAHs (US EPA16 suite);
- aromatic and aliphatic TPH (C5-C35 banding);
- benzene, toluene, ethylbenzene, xylene (BTEX);
- asbestos screen.

The results are presented on the attached Certificate of Analysis and an interpretation of the results is given below.

RESULTS OF ANALYSIS

Detailed Particle Size Analysis and Stone Content

The sample fell into the *loamy sand* texture class, with a sand content that exceeded our maximum recommended value of 85%. However, further detailed particle size analysis revealed the sample to have a relatively narrow particle size distribution with a predominance of *fine sand* (0.15-0.25mm) and *medium sand* (0.25-0.50mm). This, along with the organic matter content of the soil, should offset the slightly high sand content and provide a suitable growing medium for general landscape applications.

The stone content of the sample was low and, as such, stones should not restrict the use of the soil for general landscape purposes.

pH and Electrical Conductivity Values

The sample was strongly alkaline in reaction (pH 8.4). This pH value would be considered suitable for general landscape purposes providing species with a wide pH tolerance or those known to prefer alkaline soils are selected for planting, turfing and seeding.

The electrical conductivity (salinity) value (water extract) was moderate, which indicates that soluble salts should not be present at levels that would be harmful to plants.

The electrical conductivity value by $CaSO_4$ extract (*BS3882* requirement) fell below the maximum specified value (3300 µS/cm) given in *BS3882:2015 – Table 1*.

Organic Matter and Fertility Status

The sample was well supplied with organic matter and all major plant nutrients.

The C:N ratio of the sample was acceptable for general landscape purposes.

Tarmac Topscape

Potential Contaminants

With reference to *BS3882:2015 - Table 1*: Notes 3 and 4, there is a recommendation to confirm levels of potential contaminants in relation to the topsoil's proposed end use. This includes human health, environmental protection and metals considered toxic to plants. In the absence of site-specific assessment criteria, the concentrations that affect human health have been compared with the *residential with home-grown produce* land use in the Suitable For Use Levels (S4ULs) presented in *The LQM/CIEH S4ULs for Human Health Risk Assessment* (2015) and the DEFRA SP1010: *Development of Category 4 Screening Levels* (C4SLs) *for Assessment of Land Affected by Contamination – Policy Companion Document* (2014).

Of the potential contaminants determined, none was found at levels that exceeded their guideline values.

Phytotoxic Contaminants

Of the phytotoxic (toxic to plants) contaminants determined (copper, nickel, zinc), none was found at levels that exceeded the maximum permissible levels specified in *BS3882:2015 – Table 1*.

CONCLUSION

The purpose of the analysis was to determine the suitability of the sample for general landscape purposes (trees, shrubs, amenity grass). In addition, this sample has been assessed to determine its compliance with the requirements of the British Standard for Topsoil *(BS3882:2015 – Specification for Topsoil - Table 1, Multipurpose Topsoil)*.

From the soil examination and subsequent laboratory analysis, the sample was described as a strongly alkaline, non-saline, very slightly calcareous loamy sand with a single grain structure and low stone content. The sample was well supplied with organic matter and all major plant nutrients. Of the potential contaminants determined, none exceeded their guideline values.

The organic matter level of the sample was found to be moderately high. This may not affect the growth of trees and shrubs; however, it may result in variable settlement across amenity grass areas. As organic matter decomposes, the topsoil volume reduces, leading to an uneven surface which may be undesirable in lawn areas.

To conclude, based on our findings, the topsoil represented by this sample would be considered suitable for general landscape purposes (trees, shrubs and amenity grass (low foot-traffic only)), provided species with a wide pH tolerance or those known to prefer alkaline soils are selected and the physical condition of the soil is satisfactory.

The sample was largely compliant with the requirements of the British Standard for Topsoil *(BS3882:2015 – Specification for Topsoil – Table 1, Multipurpose Topsoil)* with the exception of a high sand content.

Soil Handling Recommendations

It is important to maintain the physical condition of the soil and avoid structural damage during all phases of soil handling (e.g. stockpiling, respreading, cultivating, planting, seeding or turfing). As a consequence, soil handling operations should be carried out when soil is reasonably dry and non-plastic (friable) in consistency.

It is important to ensure that the soil is not unnecessarily compacted by trampling or trafficking by site machinery, and soil handling should be stopped during and after heavy rainfall and not continued until the soil is friable in consistency. If the soil is structurally damaged and compacted at any stage during the course of soiling or landscaping works, it should be cultivated appropriately to relieve the compaction and to restore the soil's structure prior to any planting, turfing or seeding.

Further details on soil handling are provided in Annex A of *BS3882:2015*.

Tarmac Topscape

We hope this report meets with your approval and provides the necessary information. Please do not hesitate to contact the undersigned if we can be of further assistance.

Yours faithfully

H.MacRae

Harriet MacRae
BSc MSc
Graduate Soil Scientist

Tim White
BSc MSc MISoilSci CSci
Senior Associate

For & on behalf of Tim O'Hare Associates LLP

Tarmac Topscape

TIM O'HARE ASSOCIATES
SOIL & LANDSCAPE CONSULTANCY

Client:	**Tarmac Topsport**
Project:	**Topscape Topsoil (Crown Farm)**
Job:	**Topsoil Analysis - BS3882:2015**
Date:	**01/07/2022**
Job Ref No:	**TOHA/22/7546/SS**

Sample Reference			**Topscape Topsoil (Crown Farm)**
		Accreditation	
Clay (<0.002mm)	%	UKAS	8
Silt (0.002-0.05mm)	%	UKAS	5
Very Fine Sand (0.05-0.15mm)	%	UKAS	19
Fine Sand (0.15-0.25mm)	%	UKAS	25
Medium Sand (0.25-0.50mm)	%	UKAS	38
Coarse Sand (0.50-1.0mm)	%	UKAS	4
Very Coarse Sand (1.0-2.0mm)	%	UKAS	1
Total Sand (0.05-2.0mm)	%	UKAS	87
Texture Class (UK Classification)	--	UKAS	LS
Stones (2-20mm)	% DW	GLP	4
Stones (20-50mm)	% DW	GLP	0
Stones (>50mm)	% DW	GLP	0

pH Value (1:2.5 water extract)	units	UKAS	8.4
Electrical Conductivity (1:2.5 water extract)	uS/cm	UKAS	846
Electrical Conductivity (1:2 $CaSO_4$ extract)	uS/cm	UKAS	2976
Exchangeable Sodium Percentage	%	UKAS	6.6
Organic Matter (LOI)	%	UKAS	10.9
Total Nitrogen (Dumas)	%	UKAS	0.50
C : N Ratio	ratio	UKAS	13
Extractable Phosphorus	mg/l	UKAS	58
Extractable Potassium	mg/l	UKAS	878
Extractable Magnesium	mg/l	UKAS	136

Total Arsenic (As)	mg/kg	MCERTS	4
Total Cadmium (Cd)	mg/kg	MCERTS	< 0.2
Total Chromium (Cr)	mg/kg	MCERTS	6.5
Hexavalent Chromium (Cr VI)	mg/kg	MCERTS	<MDL
Total Copper (Cu)	mg/kg	MCERTS	15
Total Lead (Pb)	mg/kg	MCERTS	19
Total Mercury (Hg)	mg/kg	MCERTS	< 0.3
Total Nickel (Ni)	mg/kg	MCERTS	6.1
Total Selenium (Se)	mg/kg	MCERTS	< 1.0
Total Zinc (Zn)	mg/kg	MCERTS	37
Water Soluble Boron (B)	mg/kg	MCERTS	1.4
Total Cyanide (CN)	mg/kg	MCERTS	< 1.0
Total (mono) Phenols	mg/kg	MCERTS	< 1.0

Naphthalene	mg/kg	MCERTS	< 0.05
Acenaphthylene	mg/kg	MCERTS	< 0.05
Acenaphthene	mg/kg	MCERTS	< 0.05
Fluorene	mg/kg	MCERTS	< 0.05
Phenanthrene	mg/kg	MCERTS	< 0.05
Anthracene	mg/kg	MCERTS	< 0.05
Fluoranthene	mg/kg	MCERTS	< 0.05
Pyrene	mg/kg	MCERTS	< 0.05
Benzo(a)anthracene	mg/kg	MCERTS	< 0.05
Chrysene	mg/kg	MCERTS	< 0.05
Benzo(b)fluoranthene	mg/kg	MCERTS	< 0.05
Benzo(k)fluoranthene	mg/kg	MCERTS	< 0.05
Benzo(a)pyrene	mg/kg	MCERTS	< 0.05
Indeno(1,2,3-cd)pyrene	mg/kg	MCERTS	< 0.05
Dibenzo(a,h)anthracene	mg/kg	MCERTS	< 0.05
Benzo(g,h,i)perylene	mg/kg	MCERTS	< 0.05
Total PAHs (sum USEPA16)	mg/kg	MCERTS	< 0.80

Aliphatic TPH >C5 - C6	mg/kg	MCERTS	< 0.001
Aliphatic TPH >C6 - C8	mg/kg	MCERTS	< 0.001
Aliphatic TPH >C8 - C10	mg/kg	MCERTS	< 0.001
Aliphatic TPH >C10 - C12	mg/kg	MCERTS	< 1.0
Aliphatic TPH >C12 - C16	mg/kg	MCERTS	< 2.0
Aliphatic TPH >C16 - C21	mg/kg	MCERTS	< 8.0
Aliphatic TPH >C21 - C35	mg/kg	MCERTS	< 8.0
Aliphatic TPH (C5 - C35)	mg/kg	MCERTS	< 10
Aromatic TPH >C5 - C7	mg/kg	MCERTS	< 0.001
Aromatic TPH >C7 - C8	mg/kg	MCERTS	< 0.001
Aromatic TPH >C8 - C10	mg/kg	MCERTS	< 0.001
Aromatic TPH >C10 - C12	mg/kg	MCERTS	< 1.0
Aromatic TPH >C12 - C16	mg/kg	MCERTS	< 2.0
Aromatic TPH >C16 - C21	mg/kg	MCERTS	< 10
Aromatic TPH >C21 - C35	mg/kg	MCERTS	< 10
Aromatic TPH (C5 - C35)	mg/kg	MCERTS	< 10

Benzene	mg/kg	MCERTS	< 0.001
Toluene	mg/kg	MCERTS	< 0.001
Ethylbenzene	mg/kg	MCERTS	< 0.001
o-xylene	mg/kg	MCERTS	< 0.001
MTBE (Methyl Tertiary Butyl Ether)	mg/kg	MCERTS	< 0.001

Asbestos	NDVD	ISO 17025	Not detected

LS = LOAMY SAND

Visual Examination

The sample was described as a dark brown (Munsell Colour 10YR 3/3), slightly moist, friable, very slightly calcareous LOAMY SAND with a single grain structure. The sample was slightly stony and contained a moderately high proportion of organic fines and occasional woody fragments. No unusual odours, deleterious materials, roots or rhizomes of pernicious weeds were observed.

H.MacRae

Harriet MacRae
BSc MSc
Graduate Soil Scientist

Results of analysis should be read in conjunction with the report they were issued with

The contents of this certificate shall not be reproduced without the express written permission of Tim O'Hare Associates LLP.

Certificate of Analysis

Originator:
SOIL

Lab ID: 35078 - 579898
Sample ID: SB-TOPSOIL
Sample Weight: 836g

Date Received: 21/09/2022
Date Reported: 30/09/2022

BS 3882 : 2015 SPECIFICATION FOR TOPSOIL
Multi Purpose Grade

					Compliant with range (Y/N)					
				Multi-P	Acid	Calc	Low-F	Low-F Acid	Low-F Calc
		Unit	Result						
Texture:	Clay	% w/w	11						
	Silt	% w/w	15		*See area of permitted soil textural*				
	Sand	% w/w	74		*classes in Fig. 1.*				
	Textural Class		Sandy Loam	Y	Y	Y	Y	Y	Y
Organic Matter:		% w/w	3.9	Y	Y	Y	Y	Y	Y
Coarse	>2 mm	% w/w	0.7	Y	Y	Y	Y	Y	Y
Fragment	>20 mm	% w/w	0.0	Y	Y	Y	Y	Y	Y
Content:	>50 mm	% w/w	0.0	Y	Y	Y	Y	Y	Y
Soil pH:			7.7	Y	N	Y	Y	N	Y
Carbonate:		% w/w	<1			N			N
Available	Nitrogen	% w/w	0.184	Y	Y	Y			
Plant	Phosphorus	mg/l	515.0 (1)*	Y	N	N	N	N	N
Nutrients:	Potassium	mg/l	635.6 (5)*	Y	Y	Y			
	Magnesium	mg/l	128.6 (3)*	Y	Y	Y			
Carbon:Nitrogen Ratio:		:1	12.3	Y	Y	Y	Y	Y	Y
Exchangeable Sodium Percentage:		%	9.8						
Phytotoxic	Total Zinc	mg/kg	42.4	Y	Y	Y	Y	Y	Y
Contaminants:	Total Copper	mg/kg	14.0	Y	Y	Y	Y	Y	Y
	Total Nickel	mg/kg	12.0	Y	Y	Y	Y	Y	Y
Visible	> 2mm	% w/w	0.01	Y	Y	Y	Y	Y	Y
Contaminants:	Plastics	% w/w	0.00	Y	Y	Y	Y	Y	Y
	Number of Sharps		0	Y	Y	Y	Y	Y	Y
Additional	Available Sodium	mg/l	200.6						
Analysis:	Available Calcium	mg/l	1073.1						
	Conductivity	uS/cm	2738	Y					
Compliancy:				**Y**	**N**	**N**	**N**	**N**	**N**

Results are expressed on a dry matter basis.
* Soil indices from RB209

Released by: *Myles Nicholson* **Date: 30/09/2022**

DECLARATION: I certify that this sample has been analysed by NRM in accordance with BS 3882 Specification for Topsoil (2015).

NRM Coopers Bridge, Braziers Lane, Bracknell, Berkshire RG42 6NS
Tel: +44 (0) 1344 886338 **Fax:** +44 (0) 1344 890972 **Email:** enquiries@nrm.uk.com **www**.nrm.uk.com


NRM Laboratories is a division of Cawood Scientific Ltd, Coopers Bridge, Braziers Lane, Bracknell, Berkshire RG42 6NS Registered Number: 05655711

Analytical Report

Lab ID: 35078 - 579898
Sample ID: SB-TOPSOIL
Sample Weight: 836g

Date Received: 21/09/2022
Date Reported: 30/09/2022

Fig. 1. Textural Class: Sandy Loam (compliant)



Key

Area within which texture of topsoil is required to fall.

NRM Coopers Bridge, Braziers Lane, Bracknell, Berkshire RG42 6NS
Tel: +44 (0) 1344 886338 **Fax:** +44 (0) 1344 890972 **Email:** enquiries@nrm.uk.com **www**.nrm.uk.com

NRM Laboratories is a division of Cawood Scientific Ltd, Coopers Bridge, Braziers Lane, Bracknell, Berkshire RG42 6NS Registered Number: 05655711

Certificate of Analysis

Client: (T283)
STUART BALDWIN
SED SERVICES LTD
LANDGATE FARM
LANDGATE LANE
BRYN
WIGAN WN4 0EJ

Originator:
TOPSOIL
SOIL

Lab ID: 51693 - 603032
Sample ID: TOPSOIL B
Sample Weight: 889g

Date Received: 11/01/2023
Date Reported: 25/01/2023

BS 3882 : 2015 SPECIFICATION FOR TOPSOIL
Multipurpose Grade

		Unit	Result		Compliant with range (Y/N) Multi-P	Acid	Calc	Low-F	Low-F Acid	Low-F Calc
Texture:	Clay	% w/w	8							
	Silt	% w/w	8			*See area of permitted soil textural*				
	Sand	% w/w	84			*classes in Fig. 1.*				
	Textural Class		Loamy Sand		Y	Y	Y	Y	Y	Y
Organic Matter:		% w/w	4.5		Y	Y	Y	Y	Y	Y
Coarse	>2 mm	% w/w	1.6		Y	Y	Y	Y	Y	Y
Fragment	>20 mm	% w/w	0.0		Y	Y	Y	Y	Y	Y
Content:	>50 mm	% w/w	0.0		Y	Y	Y	Y	Y	Y
Soil pH:			8.2		Y	N	Y	Y	N	Y
Carbonate:		% w/w	6.2				Y			Y
Available	Nitrogen	% w/w	0.305		Y	Y	Y			
Plant	Phosphorus	mg/l	45.4	(3)*	Y	Y	Y	N	N	N
Nutrients:	Potassium	mg/l	727.1	(5)*	Y	Y	Y			
	Magnesium	mg/l	123.8	(3)*	Y	Y	Y			
Carbon:Nitrogen Ratio:		:1	8.6		Y	Y	Y	Y	Y	Y
Exchangeable Sodium Percentage:		%	6.0							
Phytotoxic	Total Zinc	mg/kg	61.5		Y	Y	Y	Y	Y	Y
Contaminants:	Total Copper	mg/kg	16.7		Y	Y	Y	Y	Y	Y
	Total Nickel	mg/kg	<10		Y	Y	Y	Y	Y	Y
Visible	> 2mm	% w/w	0.03		Y	Y	Y	Y	Y	Y
Contaminants:	Plastics	% w/w	0.00		Y	Y	Y	Y	Y	Y
	Number of Sharps		0		Y	Y	Y	Y	Y	Y
Additional	Available Sodium	mg/l	142.0							
Analysis:	Available Calcium	mg/l	1345.3							
	Conductivity	uS/cm	2899		Y					
Compliancy:					**Y**	**N**	**Y**	**N**	**N**	**N**

Results are expressed on a dry matter basis.
* Soil indices from RB209

Released by: *Myles Nicholson* **Date: 25/01/2023**

DECLARATION: I certify that this sample has been analysed by NRM in accordance with BS 3882 Specification for Topsoil (2015).

NRM Coopers Bridge, Braziers Lane, Bracknell, Berkshire RG42 6NS
Tel: +44 (0) 1344 886338 **Fax:** +44 (0) 1344 890972 **Email:** enquiries@nrm.uk.com **www**.nrm.uk.com

NRM Laboratories is a division of Cawood Scientific Ltd, Coopers Bridge, Braziers Lane, Bracknell, Berkshire RG42 6NS Registered Number: 05655711

Analytical Report


Client: STUART BALDWIN
(T283) SED SERVICES LTD
LANDGATE FARM
LANDGATE LANE
BRYN
WIGAN WN4 0EJ

Originator: TOPSOIL
SOIL

Lab ID: 51693 - 603032
Sample ID: TOPSOIL B
Sample Weight: 889g

Date Received: 11/01/2023
Date Reported: 25/01/2023

Fig. 1. Textural Class: Loamy Sand (compliant)



Key

Area within which texture of topsoil is required to fall.

NRM Coopers Bridge, Braziers Lane, Bracknell, Berkshire RG42 6NS
Tel: +44 (0) 1344 886338 **Fax:** +44 (0) 1344 890972 **Email:** enquiries@nrm.uk.com **www**.nrm.uk.com

NRM Laboratories is a division of Cawood Scientific Ltd, Coopers Bridge, Braziers Lane, Bracknell, Berkshire RG42 6NS Registered Number: 05655711

envirolab
Units 7 & 8 Sandpits Business Park
Mottram Road, Hyde, Cheshire, SK14 3AR

FINAL ANALYTICAL TEST REPORT

Envirolab Job Number: 23/09259
Issue Number: 1 **Date:** 25 September, 2023

Client: Curtins Consulting (Manchester)
Merchant Exchange
17-19 Whitworth Street
Manchester
UK
M1 5WG

Project Manager: Jonathan Lord/Lucy Woods/Rebecca Baksh-Jones
Project Name: Gorton Lane
Project Ref: 067694
Order No: 9485
Date Samples Received: 18/09/23
Date Instructions Received: 19/09/23
Date Analysis Completed: 25/09/23

Approved by:



Gemma Berrisford
Deputy Client Services Supervisor

Envirolab Job Number: 23/09259

Client Project Name: Gorton Lane

Client Project Ref: 067694

Lab Sample ID	23/09259/1	23/09259/2	23/09259/3	23/09259/4	23/09259/5	23/09259/6		Units	Limit of Detection	Method ref
Client Sample No	T.S.	S.S.	T.S.	T.S.	S.S.	T.S.				
Client Sample ID	Plot 104 (back)1	Plot 108 (back)	Plot 105 (front)	Plot 8 (back)	Plots 2+3 (front)	Plot 5 (back)				
Depth to Top	0.10	0.30	0.10	0.00	0.25	0.10				
Depth To Bottom	0.20	0.40	0.20	0.10	0.35	0.15				
Date Sampled	15-Sep-23	15-Sep-23	15-Sep-23	15-Sep-23	15-Sep-23	15-Sep-23				
Sample Type	SOIL - ES	SOIL - ES	SOIL - ES	SOIL - ES	SOIL - ES	SOIL - ES				
Sample Matrix Code	4A	5A	4AE	4A	4A	4AE				
% Moisture at <40C$_A$	20.7	10.5	21.0	24.9	11.8	22.6		% w/w	0.1	A-T-044
% Stones >10mm$_A$	1.0	18.4	<0.1	<0.1	5.1	<0.1		% w/w	0.1	A-T-044
pH$_D$$^{M\#}$	7.73	8.32	7.80	8.16	7.92	7.76		pH	0.01	A-T-031s
Sulphate (water sol 2:1)$_D$$^{M\#}$	0.12	0.02	0.14	0.08	0.08	<0.01		g/l	0.01	A-T-026s
Cyanide (total)$_A$$^{M\#}$	<1	<1	<1	<1	<1	<1		mg/kg	1	A-T-042sTCN
Phenols - Total by HPLC$_A$	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2		mg/kg	0.2	A-T-050s
Organic Matter$_D$$^{M\#}$	5.8	0.3	5.7	9.5	1.2	8.6		% w/w	0.1	A-T-032s
Arsenic$_D$$^{M\#}$	4	2	3	2	2	3		mg/kg	1	A-T-024s
Boron (water soluble)$_D$$^{M\#}$	1.1	<1.0	1.6	1.5	<1.0	<1.0		mg/kg	1	A-T-027s
Cadmium$_D$$^{M\#}$	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5		mg/kg	0.5	A-T-024s
Copper$_D$$^{M\#}$	18	6	19	24	7	13		mg/kg	1	A-T-024s
Chromium$_D$$^{M\#}$	13	10	10	29	7	10		mg/kg	1	A-T-024s
Chromium (hexavalent)$_D$	<1	<1	<1	<1	<1	<1		mg/kg	1	A-T-040s
Lead$_D$$^{M\#}$	33	4	26	30	9	22		mg/kg	1	A-T-024s
Mercury$_D$	0.23	<0.17	<0.17	<0.17	<0.17	<0.17		mg/kg	0.17	A-T-024s
Nickel$_D$$^{M\#}$	9	11	6	12	6	8		mg/kg	1	A-T-024s
Selenium$_D$$^{M\#}$	<1	<1	<1	<1	<1	<1		mg/kg	1	A-T-024s
Zinc$_D$$^{M\#}$	42	13	51	49	13	31		mg/kg	5	A-T-024s

Envirolab Job Number: 23/09259

Client Project Name: Gorton Lane

Client Project Ref: 067694

Lab Sample ID	23/09259/1	23/09259/2	23/09259/3	23/09259/4	23/09259/5	23/09259/6		Units	Limit of Detection	Method ref
Client Sample No	T.S.	S.S.	T.S.	T.S.	S.S.	T.S.				
Client Sample ID	Plot 104 (back)1	Plot 108 (back)	Plot 105 (front)	Plot 8 (back)	Plots 2+3 (front)	Plot 5 (back)				
Depth to Top	0.10	0.30	0.10	0.00	0.25	0.10				
Depth To Bottom	0.20	0.40	0.20	0.10	0.35	0.15				
Date Sampled	15-Sep-23	15-Sep-23	15-Sep-23	15-Sep-23	15-Sep-23	15-Sep-23				
Sample Type	SOIL - ES	SOIL - ES	SOIL - ES	SOIL - ES	SOIL - ES	SOIL - ES				
Sample Matrix Code	4A	5A	4AE	4A	4A	4AE				
Asbestos in Soil (inc. matrix)										
Asbestos in soil$_{D}^{\#}$	NAD	NAD	NAD	NAD	NAD	NAD				A-T-045
Asbestos Matrix (visual)$_{D}$	-	-	-	-	-	-				A-T-045
Asbestos Matrix (microscope)$_{D}$	-	-	-	-	-	-				A-T-045
Asbestos ACM - Suitable for Water Absorption Test?$_{D}$	N/A	N/A	N/A	N/A	N/A	N/A				A-T-045

Envirolab Job Number: 23/09259

Client Project Name: Gorton Lane

Client Project Ref: 067694

Lab Sample ID	23/09259/1	23/09259/2	23/09259/3	23/09259/4	23/09259/5	23/09259/6		Units	Limit of Detection	Method ref
Client Sample No	T.S.	S.S.	T.S.	T.S.	S.S.	T.S.				
Client Sample ID	Plot 104 (back)1	Plot 108 (back)	Plot 105 (front)	Plot 8 (back)	Plots 2+3 (front)	Plot 5 (back)				
Depth to Top	0.10	0.30	0.10	0.00	0.25	0.10				
Depth To Bottom	0.20	0.40	0.20	0.10	0.35	0.15				
Date Sampled	15-Sep-23	15-Sep-23	15-Sep-23	15-Sep-23	15-Sep-23	15-Sep-23				
Sample Type	SOIL - ES	SOIL - ES	SOIL - ES	SOIL - ES	SOIL - ES	SOIL - ES				
Sample Matrix Code	4A	5A	4AE	4A	4A	4AE				
PAH-16MS										
Acenaphthene$_A^{M\#}$	0.02	<0.01	0.01	<0.01	<0.01	<0.01		mg/kg	0.01	A-T-019s
Acenaphthylene$_A^{M\#}$	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01		mg/kg	0.01	A-T-019s
Anthracene$_A^{M\#}$	0.05	<0.02	0.04	0.04	<0.02	<0.02		mg/kg	0.02	A-T-019s
Benzo(a)anthracene$_A^{M\#}$	0.36	<0.04	0.25	0.28	<0.04	0.17		mg/kg	0.04	A-T-019s
Benzo(a)pyrene$_A^{M\#}$	0.45	<0.04	0.32	0.32	<0.04	0.14		mg/kg	0.04	A-T-019s
Benzo(b)fluoranthene$_A^{M\#}$	0.52	<0.05	0.41	0.41	<0.05	0.21		mg/kg	0.05	A-T-019s
Benzo(ghi)perylene$_A^{M\#}$	0.34	<0.05	0.28	0.24	<0.05	0.12		mg/kg	0.05	A-T-019s
Benzo(k)fluoranthene$_A^{M\#}$	0.22	<0.07	0.16	0.17	<0.07	0.10		mg/kg	0.07	A-T-019s
Chrysene$_A^{M\#}$	0.42	<0.06	0.32	0.35	<0.06	0.18		mg/kg	0.06	A-T-019s
Dibenzo(ah)anthracene$_A$	0.06	<0.04	<0.04	<0.04	<0.04	<0.04		mg/kg	0.04	A-T-019s
Fluoranthene$_A^{M\#}$	0.57	<0.08	0.49	0.48	<0.08	0.21		mg/kg	0.08	A-T-019s
Fluorene$_A^{M\#}$	0.02	<0.01	0.01	<0.01	<0.01	<0.01		mg/kg	0.01	A-T-019s
Indeno(123-cd)pyrene$_A^{M\#}$	0.41	<0.03	0.34	0.29	<0.03	0.17		mg/kg	0.03	A-T-019s
Naphthalene $_A^{M\#}$	<0.03^U	<0.03^U	<0.03^U	<0.03^U	<0.03^U	<0.03^U		mg/kg	0.03	A-T-019s
Phenanthrene$_A^{M\#}$	0.20	<0.03	0.16	0.13	<0.03	0.08		mg/kg	0.03	A-T-019s
Pyrene$_A^{M\#}$	0.55	<0.07	0.44	0.43	<0.07	0.18		mg/kg	0.07	A-T-019s
Total PAH-16MS$_A$	4.19	<0.08	3.23	3.14	<0.08	1.56		mg/kg	0.01	A-T-019s

Envirolab Job Number: 23/09259

Client Project Name: Gorton Lane

Client Project Ref: 067694

Lab Sample ID	23/09259/1	23/09259/2	23/09259/3	23/09259/4	23/09259/5	23/09259/6		Units	Limit of Detection	Method ref
Client Sample No	T.S.	S.S.	T.S.	T.S.	S.S.	T.S.				
Client Sample ID	Plot 104 (back)1	Plot 108 (back)	Plot 105 (front)	Plot 8 (back)	Plots 2+3 (front)	Plot 5 (back)				
Depth to Top	0.10	0.30	0.10	0.00	0.25	0.10				
Depth To Bottom	0.20	0.40	0.20	0.10	0.35	0.15				
Date Sampled	15-Sep-23	15-Sep-23	15-Sep-23	15-Sep-23	15-Sep-23	15-Sep-23				
Sample Type	SOIL - ES	SOIL - ES	SOIL - ES	SOIL - ES	SOIL - ES	SOIL - ES				
Sample Matrix Code	4A	5A	4AE	4A	4A	4AE				
TPH CWG with Clean Up										
Ali >C5-C6$_A$	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01		mg/kg	0.01	A-T-022s
Ali >C6-C8$_A$	<0.01	<0.01	<0.01	0.01	<0.01	<0.01		mg/kg	0.01	A-T-022s
Ali >C8-C10$_A$	<1	<1	<1	<1	<1	<1		mg/kg	1	A-T-055s
Ali >C10-C12$_A^{M\#}$	<1	<1	<1	<1	<1	<1		mg/kg	1	A-T-055s
Ali >C12-C16$_A^{M\#}$	<1	<1	<1	<1	<1	<1		mg/kg	1	A-T-055s
Ali >C16-C21$_A^{M\#}$	4	<1	4	5	<1	4		mg/kg	1	A-T-055s
Ali >C21-C35$_A^{M\#}$	51	<1	38	41	6	43		mg/kg	1	A-T-055s
Total Aliphatics$_A$	55	<1	42	47	6	47		mg/kg	1	Calc-As Recd
Aro >C5-C7$_A^{\#}$	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01		mg/kg	0.01	A-T-022s
Aro >C7-C8$_A^{\#}$	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01		mg/kg	0.01	A-T-022s
Aro >C8-C10$_A$	<1	<1	3	<1	<1	<1		mg/kg	1	A-T-055s
Aro >C10-C12$_A$	<1	<1	<1	<1	<1	<1		mg/kg	1	A-T-055s
Aro >C12-C16$_A^{M\#}$	5	<1	3	3	<1	3		mg/kg	1	A-T-055s
Aro >C16-C21$_A^{M\#}$	27	<1	11	12	1	9		mg/kg	1	A-T-055s
Aro >C21-C35$_A^{M\#}$	75	2	38	36	5	23		mg/kg	1	A-T-055s
Total Aromatics$_A$	107	2	54	51	6	35		mg/kg	1	Calc-As Recd
TPH (Ali & Aro >C5-C35)$_A$	162	3	96	97	13	81		mg/kg	1	Calc-As Recd
BTEX - Benzene$_A^{\#}$	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01		mg/kg	0.01	A-T-022s
BTEX - Toluene$_A^{\#}$	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01		mg/kg	0.01	A-T-022s
BTEX - Ethyl Benzene$_A^{\#}$	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01		mg/kg	0.01	A-T-022s
BTEX - m & p Xylene$_A^{\#}$	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01		mg/kg	0.01	A-T-022s
BTEX - o Xylene$_A^{\#}$	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01		mg/kg	0.01	A-T-022s
MTBE$_A^{\#}$	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01		mg/kg	0.01	A-T-022s

Report Notes

General
This report shall not be reproduced, except in full, without written approval from Envirolab.
The results reported herein relate only to the material supplied to the laboratory.
The residue of any samples contained within this report, and any received within the same delivery, will be disposed of **six weeks** after the initial scheduling. For samples tested for Asbestos we will retain a portion of the dried sample for a minimum of **six months** after the initial Asbestos testing is completed.
Analytical results reflect the quality of the sample at the time of analysis only.
Opinions and Interpretations expressed are outside our scope of accreditation.
The client Sample No, Client Sample ID, Depth to top, Depth to Bottom and Date Sampled are all provided by the client.
A deviating sample report is appended and will indicate if samples or tests have been found to be deviating. Any test results affected may not be an accurate record of the concentration at the time of sampling and, as a result, may be invalid.

Key

Superscript "#"	Accredited to ISO 17025
Superscript "M"	Accredited to MCertS
Superscript "U"	Individual result not accredited
None of the above symbols	Analysis unaccredited
Subscript "A"	Analysis performed on as-received Sample
Subscript "D"	Analysis performed on the dried sample, crushed to pass 2mm sieve.
Subscript "^"	Analysis has dependant options against results. Details appear in the comments of your Sample receipt
IS	Insufficient Sample for analysis
US	Unsuitable Sample for analysis
NDP	No Determination Possible
NAD	No Asbestos Detected
N/A	Not applicable

Asbestos
Asbestos in soil analysis is performed on a dried aliquot of the submitted sample and cannot guarantee to identify asbestos if only present in small numbers as discrete fibres/fragments in the original sample.
Stones etc. are not removed from the sample prior to analysis
Quantification of asbestos is a 3 stage process including visual identification, hand picking and weighing, and fibre counting by sedimentation/phase contrast optical microscopy if required. If asbestos is identified as being present but is not in a form that is suitable for analysis by hand picking and weighing (normally if the asbestos is present as free fibres) quantification by sedimentation is performed. Where ACMs are found a percentage asbestos is assigned to each with reference to 'HSG264, Asbestos: The survey guide' and the calculated asbestos content is expressed as a percentage of the dried soil sample aliquot used.

Assigned Matrix Codes

1	SAND	6	CLAY/LOAM	A	Contains Stones
2	LOAM	7	OTHER	B	Contains Construction Rubble
3	CLAY	8	Asbestos Bulk (Only Asbestos ID accredited)	C	Contains visible hydrocarbons
4	LOAM/SAND	9	Incinerator Ash (some Metals accredited)	D	Contains glass / metal
5	SAND/CLAY			E	Contains roots / twigs
Note: 7,8,9 matrices are not covered by our ISO 17025 or MCertS accreditation, unless stated above.					

Soil Chemical Analysis:
All results are reported as dry weight (<40°C).
For samples with Matrix Codes 1 - 6 natural stones, brick and concrete fragments >10mm and any extraneous material (visible glass, metal or twigs) are removed and excluded from the sample prior to analysis and reported results corrected to a whole sample basis. This is reported as '% stones >10mm'.
For samples with Matrix Code 7 the whole sample is dried and crushed prior to analysis and this supersedes any "A" subscripts
All analysis is performed on the sample as received for soil samples which are positive for asbestos or the client has informed asbestos may be present and/or if they are from outside the European Union and this supersedes any "D" subscripts.

TPH by method A-T-007:
For waters, free and visible oils are excluded from the sample used for analysis, so the reported result represents the dissolved phase only.
Results "with Clean up" indicates samples cleaned up with Silica during extraction.

EPH CWG (method A-T-055) from TPH CWG:
EPH CWG results have humics mathematically subtracted through instrument calculation.
Where these humic substances have been identified in any IDs from "TPH CWG with clean up" please note that the concentration is **NOT** included in the quantified results but present in the ID for information.

Electrical Conductivity of water by method A-T-037:
Results greater than 12900µS/cm @ 25ºC / 11550µS/cm @ 20ºC fall outside the accreditation range and as such are unaccredited.

Please contact your client manager if you require any further information.

Envirolab Deviating Samples Report

Units 7&8 Sandpits Business Park, Mottram Road, Hyde, SK14 3AR
Tel. 0161 368 4921 email. ask@envlab.co.uk

Client: Curtins Consulting (Manchester), Merchant Exchange, 17-19 Whitworth Street , Manchester, UK, M1 5WG

Project: Gorton Lane

Clients Project No: 067694

Project No: 23/09259

Date Received: 19/09/2023 (am)

Cool Box Temperatures (°C): 15.4

NO DEVIATIONS IDENTIFIED

If, at any point before reaching the laboratory, the temperature of the samples has breached those set in published standards, e.g. BS-EN 5667-3, ISO 18400-102:2017, then the concentration of any affected analytes may differ from that at the time of sampling.

Envirolab Analysis Dates

Lab Sample ID	23/09259/1	23/09259/2	23/09259/3	23/09259/4	23/09259/5	23/09259/6
Client Sample No	T.S.	S.S.	T.S.	T.S.	S.S.	T.S.
Client Sample ID/Depth	Plot 104 (back)1 0.10-0.20m	Plot 108 (back) 0.30-0.40m	Plot 105 (front) 0.10-0.20m	Plot 8 (back) 0.00-0.10m	Plots 2+3 (front) 0.25-0.35m	Plot 5 (back) 0.10-0.15m
Date Sampled	15/09/23	15/09/23	15/09/23	15/09/23	15/09/23	15/09/23
A-T-019s	21/09/2023	21/09/2023	21/09/2023	21/09/2023	21/09/2023	21/09/2023
A-T-022s	22/09/2023	22/09/2023	22/09/2023	22/09/2023	22/09/2023	22/09/2023
A-T-024s	25/09/2023	25/09/2023	25/09/2023	25/09/2023	25/09/2023	25/09/2023
A-T-026s	22/09/2023	22/09/2023	22/09/2023	22/09/2023	22/09/2023	22/09/2023
A-T-027s	25/09/2023	25/09/2023	25/09/2023	25/09/2023	25/09/2023	25/09/2023
A-T-031s	22/09/2023	22/09/2023	22/09/2023	22/09/2023	22/09/2023	22/09/2023
A-T-032s	22/09/2023	22/09/2023	22/09/2023	22/09/2023	22/09/2023	22/09/2023
A-T-040s	22/09/2023	22/09/2023	22/09/2023	22/09/2023	22/09/2023	22/09/2023
A-T-042sTCN	21/09/2023	21/09/2023	21/09/2023	21/09/2023	21/09/2023	21/09/2023
A-T-044	21/09/2023	21/09/2023	21/09/2023	21/09/2023	21/09/2023	21/09/2023
A-T-045	20/09/2023	20/09/2023	20/09/2023	20/09/2023	20/09/2023	20/09/2023
A-T-050s	22/09/2023	22/09/2023	22/09/2023	22/09/2023	22/09/2023	22/09/2023
A-T-055s	22/09/2023	22/09/2023	22/09/2023	22/09/2023	22/09/2023	22/09/2023
Calc-As Recd	22/09/2023	22/09/2023	22/09/2023	22/09/2023	22/09/2023	22/09/2023

The above dates are the analysis completion dates, please note that these are not necessarily the date that the analysis was weighed/extracted.

End of Report

envirolab
Units 7 & 8 Sandpits Business Park
Mottram Road, Hyde, Cheshire, SK14 3AR

FINAL ANALYTICAL TEST REPORT

Envirolab Job Number: 23/11412
Issue Number: 1 **Date:** 27 November, 2023

Client:
Curtins Consulting (Manchester)
Merchant Exchange
17-19 Whitworth Street
Manchester
UK
M1 5WG

Project Manager: Jonathan Lord/Lucy Woods/Russell Taylor
Project Name: Gorton Lane, Manchester
Project Ref: 067694
Order No: 10971
Date Samples Received: 17/11/23
Date Instructions Received: 20/11/23
Date Analysis Completed: 27/11/23

Approved by:



Sophie France
Client Manager

Envirolab Job Number: 23/11412

Client Project Name: Gorton Lane, Manchester

Client Project Ref: 067694

Lab Sample ID	23/11412/1	23/11412/2						Units	Limit of Detection	Method ref
Client Sample No										
Client Sample ID	HP29	HP32								
Depth to Top	0.30	0.30								
Depth To Bottom	0.40	0.40								
Date Sampled	16-Nov-23	16-Nov-23								
Sample Type	SOIL - ES	SOIL - ES								
Sample Matrix Code	3A	1A								
% Moisture at <40C$_A$	13.6	16.1						% w/w	0.1	A-T-044
% Stones >10mm$_A$	<0.1	<0.1						% w/w	0.1	A-T-044
pH$_D$$^{M\#}$	8.42	8.60						pH	0.01	A-T-031s
Sulphate (water sol 2:1)$_D$$^{M\#}$	<0.01	<0.01						g/l	0.01	A-T-026s
Cyanide (total)$_A$$^{M\#}$	<1	<1						mg/kg	1	A-T-042sTCN
Phenols - Total by HPLC$_A$	<0.2	<0.2						mg/kg	0.2	A-T-050s
Organic Matter$_D$$^{M\#}$	0.2	0.1						% w/w	0.1	A-T-032s
Arsenic$_D$$^{M\#}$	1	1						mg/kg	1	A-T-024s
Boron (water soluble)$_D$$^{M\#}$	<1.0	<1.0						mg/kg	1	A-T-027s
Cadmium$_D$$^{M\#}$	<0.5	<0.5						mg/kg	0.5	A-T-024s
Copper$_D$$^{M\#}$	10	5						mg/kg	1	A-T-024s
Chromium$_D$$^{M\#}$	17	8						mg/kg	1	A-T-024s
Chromium (hexavalent)$_D$	<1	<1						mg/kg	1	A-T-040s
Lead$_D$$^{M\#}$	3	2						mg/kg	1	A-T-024s
Mercury$_D$	<0.17	<0.17						mg/kg	0.17	A-T-024s
Nickel$_D$$^{M\#}$	15	7						mg/kg	1	A-T-024s
Selenium$_D$$^{M\#}$	<1	<1						mg/kg	1	A-T-024s
Zinc$_D$$^{M\#}$	23	11						mg/kg	5	A-T-024s

Envirolab Job Number: 23/11412

Client Project Name: Gorton Lane, Manchester

Client Project Ref: 067694

Lab Sample ID	23/11412/1	23/11412/2						Units	Limit of Detection	Method ref
Client Sample No										
Client Sample ID	HP29	HP32								
Depth to Top	0.30	0.30								
Depth To Bottom	0.40	0.40								
Date Sampled	16-Nov-23	16-Nov-23								
Sample Type	SOIL - ES	SOIL - ES								
Sample Matrix Code	3A	1A								
Asbestos in Soil (inc. matrix)										
Asbestos in soil$_{D}^{\#}$	NAD	NAD								A-T-045
Asbestos Matrix (visual)$_{D}$	-	-								A-T-045
Asbestos Matrix (microscope)$_{D}$	-	-								A-T-045
Asbestos ACM - Suitable for Water Absorption Test?$_{D}$	N/A	N/A								A-T-045

Envirolab Job Number: 23/11412

Client Project Name: Gorton Lane, Manchester

Client Project Ref: 067694

Lab Sample ID	23/11412/1	23/11412/2						Units	Limit of Detection	Method ref
Client Sample No										
Client Sample ID	HP29	HP32								
Depth to Top	0.30	0.30								
Depth To Bottom	0.40	0.40								
Date Sampled	16-Nov-23	16-Nov-23								
Sample Type	SOIL - ES	SOIL - ES								
Sample Matrix Code	3A	1A								
PAH-16MS										
Acenaphthene$_{A}^{M\#}$	<0.01	<0.01						mg/kg	0.01	A-T-019s
Acenaphthylene$_{A}^{M\#}$	<0.01	<0.01						mg/kg	0.01	A-T-019s
Anthracene$_{A}^{M\#}$	<0.02	<0.02						mg/kg	0.02	A-T-019s
Benzo(a)anthracene$_{A}^{M\#}$	<0.04	<0.04						mg/kg	0.04	A-T-019s
Benzo(a)pyrene$_{A}^{M\#}$	<0.04	<0.04						mg/kg	0.04	A-T-019s
Benzo(b)fluoranthene$_{A}^{M\#}$	<0.05	<0.05						mg/kg	0.05	A-T-019s
Benzo(ghi)perylene$_{A}^{M\#}$	<0.05	<0.05						mg/kg	0.05	A-T-019s
Benzo(k)fluoranthene$_{A}^{M\#}$	<0.07	<0.07						mg/kg	0.07	A-T-019s
Chrysene$_{A}^{M\#}$	<0.06	<0.06						mg/kg	0.06	A-T-019s
Dibenzo(ah)anthracene$_{A}$	<0.04	<0.04						mg/kg	0.04	A-T-019s
Fluoranthene$_{A}^{M\#}$	<0.08	<0.08						mg/kg	0.08	A-T-019s
Fluorene$_{A}^{M\#}$	<0.01	<0.01						mg/kg	0.01	A-T-019s
Indeno(123-cd)pyrene$_{A}^{M\#}$	<0.03	<0.03						mg/kg	0.03	A-T-019s
Naphthalene $_{A}^{M\#}$	<0.03	<0.03						mg/kg	0.03	A-T-019s
Phenanthrene$_{A}^{M\#}$	<0.03	<0.03						mg/kg	0.03	A-T-019s
Pyrene$_{A}^{M\#}$	<0.07	<0.07						mg/kg	0.07	A-T-019s
Total PAH-16MS$_{A}$	<0.08	<0.08						mg/kg	0.01	A-T-019s

Envirolab Job Number: 23/11412

Client Project Name: Gorton Lane, Manchester

Client Project Ref: 067694

Lab Sample ID	23/11412/1	23/11412/2						Units	Limit of Detection	Method ref
Client Sample No										
Client Sample ID	HP29	HP32								
Depth to Top	0.30	0.30								
Depth To Bottom	0.40	0.40								
Date Sampled	16-Nov-23	16-Nov-23								
Sample Type	SOIL - ES	SOIL - ES								
Sample Matrix Code	3A	1A								
TPH CWG with Clean Up										
Ali >C5-C6$_A$	<0.01	<0.01						mg/kg	0.01	A-T-022s
Ali >C6-C8$_A$	<0.01	<0.01						mg/kg	0.01	A-T-022s
Ali >C8-C10$_A$	<1	<1						mg/kg	1	A-T-055s
Ali >C10-C12$_A^{M\#}$	<1	<1						mg/kg	1	A-T-055s
Ali >C12-C16$_A^{M\#}$	<1	<1						mg/kg	1	A-T-055s
Ali >C16-C21$_A^{M\#}$	<1	<1						mg/kg	1	A-T-055s
Ali >C21-C35$_A^{M\#}$	<1	<1						mg/kg	1	A-T-055s
Total Aliphatics$_A$	<1	<1						mg/kg	1	Calc-As Recd
Aro >C5-C7$_A^{\#}$	<0.01	<0.01						mg/kg	0.01	A-T-022s
Aro >C7-C8$_A^{\#}$	<0.01	<0.01						mg/kg	0.01	A-T-022s
Aro >C8-C10$_A$	<1	<1						mg/kg	1	A-T-055s
Aro >C10-C12$_A$	<1	<1						mg/kg	1	A-T-055s
Aro >C12-C16$_A$	<1	<1						mg/kg	1	A-T-055s
Aro >C16-C21$_A^{M\#}$	<1	<1						mg/kg	1	A-T-055s
Aro >C21-C35$_A^{M\#}$	<1	<1						mg/kg	1	A-T-055s
Total Aromatics$_A$	<1	<1						mg/kg	1	Calc-As Recd
TPH (Ali & Aro >C5-C35)$_A$	<1	<1						mg/kg	1	Calc-As Recd
BTEX - Benzene$_A^{\#}$	<0.01	<0.01						mg/kg	0.01	A-T-022s
BTEX - Toluene$_A^{\#}$	<0.01	<0.01						mg/kg	0.01	A-T-022s
BTEX - Ethyl Benzene$_A^{\#}$	<0.01	<0.01						mg/kg	0.01	A-T-022s
BTEX - m & p Xylene$_A^{\#}$	<0.01	<0.01						mg/kg	0.01	A-T-022s
BTEX - o Xylene$_A^{\#}$	<0.01	<0.01						mg/kg	0.01	A-T-022s
MTBE$_A^{\#}$	<0.01	<0.01						mg/kg	0.01	A-T-022s

Report Notes

General
This report shall not be reproduced, except in full, without written approval from Envirolab.
The results reported herein relate only to the material supplied to the laboratory.
The residue of any samples contained within this report, and any received within the same delivery, will be disposed of **six weeks** after the initial scheduling. For samples tested for Asbestos we will retain a portion of the dried sample for a minimum of **six months** after the initial Asbestos testing is completed.
Analytical results reflect the quality of the sample at the time of analysis only.
Opinions and Interpretations expressed are outside our scope of accreditation.
The client Sample No, Client Sample ID, Depth to top, Depth to Bottom and Date Sampled are all provided by the client.
A deviating sample report is appended and will indicate if samples or tests have been found to be deviating. Any test results affected may not be an accurate record of the concentration at the time of sampling and, as a result, may be invalid.

Key

Superscript "#"	Accredited to ISO 17025
Superscript "M"	Accredited to MCertS
Superscript "U"	Individual result not accredited
None of the above symbols	Analysis unaccredited
Subscript "A"	Analysis performed on as-received Sample
Subscript "D"	Analysis performed on the dried sample, crushed to pass 2mm sieve.
Subscript "^"	Analysis has dependant options against results. Details appear in the comments of your Sample receipt
IS	Insufficient Sample for analysis
US	Unsuitable Sample for analysis
NDP	No Determination Possible
NAD	No Asbestos Detected
N/A	Not applicable

Asbestos
Asbestos in soil analysis is performed on a dried aliquot of the submitted sample and cannot guarantee to identify asbestos if only present in small numbers as discrete fibres/fragments in the original sample.
Stones etc. are not removed from the sample prior to analysis
Quantification of asbestos is a 3 stage process including visual identification, hand picking and weighing, and fibre counting by sedimentation/phase contrast optical microscopy if required. If asbestos is identified as being present but is not in a form that is suitable for analysis by hand picking and weighing (normally if the asbestos is present as free fibres) quantification by sedimentation is performed. Where ACMs are found a percentage asbestos is assigned to each with reference to 'HSG264, Asbestos: The survey guide' and the calculated asbestos content is expressed as a percentage of the dried soil sample aliquot used.

Assigned Matrix Codes

1	SAND	6	CLAY/LOAM	A	Contains Stones
2	LOAM	7	OTHER	B	Contains Construction Rubble
3	CLAY	8	Asbestos Bulk (Only Asbestos ID accredited)	C	Contains visible hydrocarbons
4	LOAM/SAND	9	Incinerator Ash (some Metals accredited)	D	Contains glass / metal
5	SAND/CLAY			E	Contains roots / twigs
Note: 7,8,9 matrices are not covered by our ISO 17025 or MCertS accreditation, unless stated above.					

Soil Chemical Analysis:
All results are reported as dry weight (<40°C).
For samples with Matrix Codes 1 - 6 natural stones, brick and concrete fragments >10mm and any extraneous material (visible glass, metal or twigs) are removed and excluded from the sample prior to analysis and reported results corrected to a whole sample basis. This is reported as '% stones >10mm'.
For samples with Matrix Code 7 the whole sample is dried and crushed prior to analysis and this supersedes any "A" subscripts
All analysis is performed on the sample as received for soil samples which are positive for asbestos or the client has informed asbestos may be present and/or if they are from outside the European Union and this supersedes any "D" subscripts.

TPH by method A-T-007:
For waters, free and visible oils are excluded from the sample used for analysis, so the reported result represents the dissolved phase only.
Results "with Clean up" indicates samples cleaned up with Silica during extraction.

EPH CWG (method A-T-055) from TPH CWG:
EPH CWG results have humics mathematically subtracted through instrument calculation.
Where these humic substances have been identified in any IDs from "TPH CWG with clean up" please note that the concentration is **NOT** included in the quantified results but present in the ID for information.

Electrical Conductivity of water by method A-T-037:
Results greater than 12900µS/cm @ 25ºC / 11550µS/cm @ 20ºC fall outside the accreditation range and as such are unaccredited.

Please contact your client manager if you require any further information.

Envirolab Deviating Samples Report

Units 7&8 Sandpits Business Park, Mottram Road, Hyde, SK14 3AR
Tel. 0161 368 4921 email. ask@envlab.co.uk

Client: Curtins Consulting (Manchester), Merchant Exchange, 17-19 Whitworth Street , Manchester, UK, M1 5WG

Project: Gorton Lane, Manchester

Clients Project No: 067694

Project No: 23/11412

Date Received: 20/11/2023 (am)

Cool Box Temperatures (°C): 12.9

NO DEVIATIONS IDENTIFIED

If, at any point before reaching the laboratory, the temperature of the samples has breached those set in published standards, e.g. BS-EN 5667-3, ISO 18400-102:2017, then the concentration of any affected analytes may differ from that at the time of sampling.

Envirolab Analysis Dates

Lab Sample ID	23/11412/1	23/11412/2
Client Sample No		
Client Sample ID/Depth	HP29 0.30-0.40m	HP32 0.30-0.40m
Date Sampled	16/11/23	16/11/23
A-T-019s	22/11/2023	22/11/2023
A-T-022s	22/11/2023	22/11/2023
A-T-024s	24/11/2023	24/11/2023
A-T-026s	23/11/2023	23/11/2023
A-T-027s	27/11/2023	27/11/2023
A-T-031s	23/11/2023	23/11/2023
A-T-032s	23/11/2023	23/11/2023
A-T-040s	23/11/2023	23/11/2023
A-T-042sTCN	22/11/2023	22/11/2023
A-T-044	23/11/2023	23/11/2023
A-T-045	21/11/2023	21/11/2023
A-T-050s	23/11/2023	23/11/2023
A-T-055s	22/11/2023	22/11/2023
Calc-As Recd	22/11/2023	22/11/2023

The above dates are the analysis completion dates, please note that these are not necessarily the date that the analysis was weighed/extracted.

End of Report

Appendix D – Generic Assessment Criteria

Copyright © 2023 Curtins Consulting Ltd

Adopted Soil Generic Assessment Criteria
Sandy loam with 6% SOM

curtins

Contaminants	Residential with home grown produce	Residential without home grown produce	Allotments	Commercial	Public open space near residential housing POS_{resi}	Public park POS_{park}
Metals						
Beryllium	*1.7*	*1.7*	*35*	*12*	*2.2*	*63*
Boron	*290*	*11,000*	*45*	*240,000*	*21,000*	*46,000*
Cadmium	**10**[13] 22	**85**[13] 150	**1.8** 3.9	**230** 410	*120* 220	*560* 880
Chromium III	*910*	*910*	*18,000*	*8,600*	*1,500*	*33,000*
Chromium VI	*6* 21	*6* 21	*1.8* 170	*33* 49	*7.7* 21	*220* 250
Lead	200	310	80	2,300	630	1,300
Mercury *(elemental)*	**1**	**1**	**26**	**26**	*16*	**26**[8] [*30*]
Mercury (inorganic)	**170**	**240**	**80**	**3600**	*120*	*240*
Nickel	*130*[10]	*180*[10]	*53*[11]	*980*[10]	*230*	*800*
Vanadium	*410*	*1200*	*91*	*9000*	*2000*	*5000*
Copper	*2400*	*7100*	*520*	*68000*	*12000*	*44000*
Zinc	*3700*	*40000*	*620*	*730000*	*81000*	*170000*
Semi-Metals and non-metals						
Arsenic	**32**[12] 37	**35**[12] 40	**43**[12] 49	**640**[12] 640	*79* 79	*170* 170
Antimony		***550***		***7500***	***1500***	***3300***
Selenium	**350**	**600**	**120**	**13000**	*1100*	*1800*
Inorganic chemicals						
Cyanide	34	34	34	34	34	34
Organic contaminants						
Aliphatic risk banded hydrocarbons - TPHCWG method						
$EC_{>5}$ - EC_6	*160*	*160*	*3900*	*12000*	*600000*	*180000*
$EC_{>6}$ - EC_8	*530*	*530*	*13000*	*40000*	*620000*	*320000*
$EC_{>8}$ - EC_{10}	*150*	*150*	*1700*	*11000*	*13000*	*21000*
EC_{10}-EC_{12}	*760*	*770*	*7300*	*47000*	*13000*	*24000*
EC_{12}-EC_{16}	*4300*	*4400*	*13000*	*90000*	*13000*	*26000*
$EC_{>16}$ - EC_{35}	*110000*	*110000*	*270000*	*1800000*	*250000*	*490000*
$EC>_{35}$ - EC_{44}	*110000*	*110000*	*270000*	*1800000*	*250000*	*490000*
Aromatic risk banded hydrocarbons - TPHCWG method						
$EC>_5$ - EC_7	*300*	*1400*	*57*	*86000*	*56000*	*92000*
$EC>_7$ - EC_8	*660*	*3900*	*120*	*180000*	*56000*	*100000*
$EC_{>8}$ - EC_{10}	*190*	*270*	*51*	*17000*	*5000*	*9300*
EC_{10} - EC_{12}	*380*	*1200*	*74*	*34000*	*5000*	*10000*
EC_{12} - EC_{16}	*660*	*2500*	*130*	*38000*	*5000*	*10000*
$EC_{>16}$ - EC_{21}	*930*	*1900*	*260*	*28000*	*3800*	*7800*
$EC_{>21}$ - EC_{35}	*1700*	*1900*	*1600*	*28000*	*3800*	*7900*
$EC>_{35}$ - EC_{44}	*1700*	*1900*	*1600*	*28000*	*3800*	*7900*
Aliph + Arom EC >44-70	*1900*	*1900*	*3000*	*28000*	3800	7900
Aromatic						
Benzene	**0.33** 0.87	**1.0** 3.3	**0.07** 0.18	**95** 98	*73* 140	*110* 230
Ethyl benzene	**350**	**840**	**90**	**2800**[8] [66000]	**2800**[8] [*25000*]	**2800**[8] [*27000*]
Toluene	**610**	**2700**	**120**	**4400**[8] [190000]	**4400**[8] [*56000*]	**4400**[8] [*100000*]
Xylene[9]	**230**	**290**	**160**	**2600**[8] [32000]	**2600**[8] [*43000*]	**2600**[8] [*31000*]
Phenol	**420**	**520**	**280**	**3200**[14] (38000)	**3200**[14] (*10000*)	**3200**[14] (*9300*)
Polycyclic Aromatic Hydrocarbons (PAH)						
Naphthalene	*13*	*13*	*24*	*1100*	*4900*	*3000*
Acenaphthylene	*920*	*6000*	*160*	*100000*	*15000*	*30000*
Acenaphthene	*1100*	*6000*	*200*	*100000*	*15000*	*30000*
Fluorene	*860*	*4500*	*160*	*71000*	*9900*	*20000*
Phenanthrene	*440*	*1500*	*90*	*23000*	*3100*	*6300*
Anthracene	*11000*	*37000*	*2200*	*540000*	*74000*	*150000*
Fluoranthene	*890*	*1600*	*290*	*23000*	*3100*	*6400*
Pyrene	*2000*	*3800*	*620*	*54000*	*7400*	*15000*
Benz(a)anthracene	*13*	*15*	*13*	*180*	*29*	*62*
Chrysene	*27*	*32*	*19*	*350*	*57*	*120*
Benzo(b)fluoranthene	*3.7*	*4.0*	*3.9*	*45*	*7.2*	*16.0*
Benzo(k)fluoranthene	*100*	*110*	*130*	*1200*	*190*	*440*
Benzo(a)pyrene	*3.0* 5.0	*3.2* 5.3	*3.5* 5.7	*36* 77	*5.7* 10	*13* 21
Indeno(123cd)pyrene	*41*	*46*	*39*	*510*	*82*	*180*
Dibenzo(ah)anthracene	*0.3*	*0.32*	*0.43*	*3.6*	*0.58*	*1.4*
Benzo(ghi)perylene	*350*	*360*	*640*	*4000*	*640*	*1600*
Chlorinated Aliphatic Hydrocarbons						
Vinyl chloride	*0.0014*	*0.0015*	*0.0018*	*0.12*	*3.5*	*5.4*
Trichloroethene (TCE)	*0.075*	*0.08*	*0.21*	*5.7*	*120*	*120*
1,1,1,2 Tetrachlorethane	*6.4*	*8.2*	*4.4*	*560*	*1400*	*2100*
Tetrachlorethene (PCE)	*0.90*	*0.92*	*3.6*	*95*	*1400*	*1500*
1,1,1 Trichlorethane	*39*	*40*	*240*	*3000*	*140000*	*100000*

Notes

1. All values above are in mg/kg
2. **Numbers in bold are SGVs or GAC that are derived based on SGV report input parameters**, *numbers in italics are S4ULs*, ***numbers in bold-italics are based on EIC/AGS/CL:AIRE numbers & input parameters*** and underlined numbers are C4SLs
3. Soil organic matter (SOM) is assumed to be 6% - DEFAULT VALUE
4. Soil type is assumed to be sandy loam - DEFAULT SOIL TYPE
5. For residential, the building type is conservatively assumed to be a small terrace house where the development includes bungalows change to more conservative bungalow setting in computer model
6. For commercial, the building type is conservatively assumed to be a pre 1970s office building, where the proposed development comprises houses, flat with living spaces changes setting in model accordingly
7. For classrooms consider increasing the dust loading fator in the 'Soil and Building Data' of the CLEA 1.04 model from 50 to 100µg m^{-3}
8. Based on vapour saturation limt as suggested by EA / [ ] model value
9. Lowest of o-, m- and p-xylene
10. Based on comparison of inhalation exposure with inhalation TDI
11. Based on comparison of oral, dermal, and inhalation exposure with the oral TDI
12. Based on a comparison of oral and dermal soil exposure with oral Index Dose only
13. Averaged over and based on lifetime exposure
14. Based on critical concentration for skin irritation in humans arising from contact with phenol in aqueous solution (number in brackets based on health effects following long term exposure for illustration)
15. NA: Not applicable

Adopted Soil Generic Assessment Criteria
Sandy loam with 2.5% SOM

curtins

Contaminants	Residential with home grown produce	Residential without home grown produce	Allotments	Commercial	Public open space near residential housing POS_{resi}	Public park POS_{park}
Metals						
Beryllium	*1.7*	*1.7*	*35*	*12*	*2.2*	*63*
Boron	*290*	*11,000*	*45*	*240,000*	*21,000*	*46,000*
Cadmium	**10**[13] 22	**85**[13] 150	**1.8** 3.9	**230** 410	*120* 220	*560* 880
Chromium III	*910*	*910*	*18,000*	*8,600*	*1,500*	*33,000*
Chromium VI	*6* 21	*6* 21	*1.8* 170	*33* 49	*7.7* 21	*220* 250
Lead	200	310	80	2,300	630	1,300
Mercury *(elemental)*	**1**	**1**	**26**	**26**	*16*	**26**[8] [*30*]
Mercury (inorganic)	**170**	**240**	**80**	**3600**	*120*	*240*
Nickel	*130*[10]	*180*[10]	*53*[11]	*980*[10]	*230*	*800*
Vanadium	*410*	*1200*	*91*	*9000*	*2000*	*5000*
Copper	*2400*	*7100*	*520*	*68000*	*12000*	*44000*
Zinc	*3700*	*40000*	*620*	*730000*	*81000*	*170000*
Semi-Metals and non-metals						
Arsenic	**32**[12] 37	**35**[12] 40	**43**[12] 49	**640**[12] 640	*79* 79	*170* 170
Antimony		***550***		***7500***	***1500***	***3300***
Selenium	**350**	**600**	**120**	**13000**	*1100*	*1800*
Inorganic chemicals						
Cyanide	34	34	34	34	34	34
Organic contaminants						
Aliphatic risk banded hydrocarbons - TPHCWG method						
$EC_{>5}$ - EC_6	*78*	*78*	*1700*	*5900*	*590000*	*130000*
$EC_{>6}$ - EC_8	*230*	*230*	*5600*	*17000*	*610000*	*220000*
$EC_{>8}$ - EC_{10}	*65*	*65*	*770*	*4800*	*13000*	*18000*
EC_{10}-EC_{12}	*330*	*330*	*4400*	*23000*	*13000*	*23000*
EC_{12}-EC_{16}	*2400*	*2400*	*13000*	*82000*	*13000*	*25000*
$EC_{>16}$ - EC_{35}	*92000*	*92000*	*270000*	*1700000*	*250000*	*480000*
$EC>_{35}$ - EC_{44}	*92000*	*92000*	*270000*	*1700000*	*250000*	*480000*
Aromatic risk banded hydrocarbons - TPHCWG method						
$EC>_5$ - EC_7	*140*	*690*	*27*	*46000*	*56000*	*84000*
$EC>_7$ - EC_8	*290*	*1800*	*51*	*110000*	*56000*	*95000*
$EC_{>8}$ - EC_{10}	*83*	*110*	*21*	*8100*	*5000*	*8500*
EC_{10} - EC_{12}	*180*	*590*	*31*	*28000*	*5000*	*9700*
EC_{12} - EC_{16}	*330*	*2300*	*57*	*37000*	*5100*	*10000*
$EC_{>16}$ - EC_{21}	*540*	*1900*	*110*	*28000*	*3800*	*7700*
$EC_{>21}$ - EC_{35}	*1500*	*1900*	*820*	*28000*	*3800*	*7800*
$EC>_{35}$ - EC_{44}	*1500*	*1900*	*820*	*28000*	*3800*	*7800*
Aliph + Arom EC >44-70	*1800*	*1900*	*2100*	*28000*	3800	7800
Aromatic						
Benzene	**0.16**	**0.49**	**0.035**	**50**	*72*	*100*
Ethyl benzene	**150**	**380**	**39**	**1200**[8] [35000]	**1200**[8] [*24000*]	**1200**[8] [*22000*]
Toluene	**270**	**1300**	**51**	**1900**[8] [110000]	**1900**[8] [*56000*]	**1900**[8] [*95000*]
Xylene[9]	**98**	**120**	**70**	**1200**[8] [14000]	**1200**[8] [*42000*]	**1200**[8] [*23000*]
Phenol	**290**	**420**	**140**	**1500**[14] (35000)	**1500**[14] (*10000*)	**1500**[14] (*8300*)
Polycyclic Aromatic Hydrocarbons (PAH)						
Naphthalene	*5.6*	*5.6*	*10*	*460*	*4900*	*1900*
Acenaphthylene	*420*	*4600*	*69*	*97000*	*15000*	*30000*
Acenaphthene	*510*	*4700*	*85*	*97000*	*15000*	*30000*
Fluorene	*400*	*3800*	*67*	*68000*	*9900*	*20000*
Phenanthrene	*220*	*1500*	*38*	*22000*	*3100*	*6200*
Anthracene	*5400*	*35000*	*950*	*540000*	*74000*	*150000*
Fluoranthene	*560*	*1600*	*130*	*23000*	*3100*	*6300*
Pyrene	*1200*	*3800*	*270*	*54000*	*7400*	*15000*
Benz(a)anthracene	*11*	*14*	*6.5*	*170*	*29*	*56*
Chrysene	*22*	*31*	*9.4*	*350*	*57*	*110*
Benzo(b)fluoranthene	*3.3*	*4.0*	*2.1*	*44*	*7.2*	*15*
Benzo(k)fluoranthene	*93*	*110*	*75*	*1200*	*190*	*410*
Benzo(a)pyrene	*2.7*	*3.2*	*2*	*35*	*5.7*	*12*
Indeno(123cd)pyrene	*36*	*46*	*21*	*510*	*82*	*170*
Dibenzo(ah)anthracene	*0.28*	*0.32*	*0.27*	*3.6*	*0.57*	*1.3*
Benzo(ghi)perylene	*340*	*360*	*470*	*4000*	*640*	*1500*
Chlorinated Aliphatic Hydrocarbons						
Vinyl chloride	*0.00087*	*0.001*	*0.001*	*0.077*	*3.5*	*5*
Trichloroethene (TCE)	*0.034*	*0.036*	*0.091*	*2.6*	*120*	*91*
1,1,1,2 Tetrachlorethane	*2.8*	*3.5*	*1.9*	*250*	*1400*	*1800*
Tetrachlorethene (PCE)	*0.39*	*0.4*	*1.5*	*42*	*1400*	*1100*
1,1,1 Trichlorethane	*18*	*18*	*110*	*1300*	*140000*	*76000*

Notes

1. All values above are in mg/kg
2. **Numbers in bold are SGVs or GAC that are derived based on SGV report input parameters**, *numbers in italics are S4ULs*, ***numbers in bold-italics are based on EIC/AGS/CL:AIRE numbers & input parameters*** and underlined numbers are C4SLs
3. Soil organic matter (SOM) is assumed to be 2.5% - DEFAULT VALUE
4. Soil type is assumed to be sandy loam - DEFAULT SOIL TYPE
5. For residential, the building type is conservatively assumed to be a small terrace house where the development includes bungalows change to more conservative bungalow setting in computer model
6. For commercial, the building type is conservatively assumed to be a pre 1970s office building, where the proposed development comprises houses, flat with living spaces changes setting in model accordingly
7. For classrooms consider increasing the dust loading fator in the 'Soil and Building Data' of the CLEA 1.04 model from 50 to 100µg m^{-3}
8. Based on vapour saturation limt as suggested by EA / [ ] model value
9. Lowest of o-, m- and p-xylene
10. Based on comparison of inhalation exposure with inhalation TDI
11. Based on comparison of oral, dermal, and inhalation exposure with the oral TDI
12. Based on a comparison of oral and dermal soil exposure with oral Index Dose only
13. Averaged over and based on lifetime exposure
14. Based on critical concentration for skin irritation in humans arising from contact with phenol in aqueous solution (number in brackets based on health effects following long term exposure for illustration)
15. NA: Not applicable

Adopted Soil Generic Assessment Criteria
Sandy loam with 1% SOM

curtins

Contaminants	Residential with home grown produce	Residential without home grown produce	Allotments	Commercial	Public open space near residential housing POS_{resi}	Public park POS_{park}
Metals						
Beryllium	*1.7*	*1.7*	*35*	*12*	*2.2*	*63*
Boron	*290*	*11,000*	*45*	*240,000*	*21,000*	*46,000*
Cadmium	**10**[13] 22	**85**[13] 150	**1.8** 3.9	**230** 410	*120* 220	*560* 880
Chromium III	*910*	*910*	*18,000*	*8,600*	*1,500*	*33,000*
Chromium VI	*6* 21	*6* 21	*1.8* 170	*33* 49	*7.7* 21	*220* 250
Lead	200	310	80	2,300	630	1,300
Mercury *(elemental)*	**1**	**1**	**26**	**26**	*16*	**26**[8] *[30]*
Mercury (inorganic)	**170**	**240**	**80**	**3600**	*120*	*240*
Nickel	*130*[10]	*180*[10]	*53*[11]	*980*[10]	*230*	*800*
Vanadium	*410*	*1200*	*91*	*9000*	*2000*	*5000*
Copper	*2400*	*7100*	*520*	*68000*	*12000*	*44000*
Zinc	*3700*	*40000*	*620*	*730000*	*81000*	*170000*
Semi-Metals and non-metals						
Arsenic	**32**[12] 37	**35**[12] 40	**43**[12] 49	**640**[12] 640	*79* 79	*170* 170
Antimony		***550***		***7500***	***1500***	***3300***
Selenium	**350**	**600**	**120**	**13000**	*1100*	*1800*
Inorganic chemicals						
Cyanide	34	34	34	34	34	34
Organic contaminants						
Aliphatic risk banded hydrocarbons - TPHCWG method						
$EC_{>5}$ - EC_6	*42*	*42*	*730*	*3200*	*570000*	*95000*
$EC_{>6}$ - EC_8	*100*	*100*	*2300*	*7800*	*600000*	*150000*
$EC_{>8}$ - EC_{10}	*27*	*27*	*320*	*2000*	*13000*	*14000*
EC_{10}-EC_{12}	*130*	*130*	*2200*	*9700*	*13000*	*21000*
EC_{12}-EC_{16}	*1100*	*1100*	*11000*	*59000*	*13000*	*25000*
$EC_{>16}$ - EC_{35}	*65000*	*65000*	*260000*	*1600000*	*250000*	*450000*
$EC_{>35}$ - EC_{44}	*65000*	*65000*	*260000*	*1600000*	*250000*	*450000*
Aromatic risk banded hydrocarbons - TPHCWG method						
$EC_{>5}$ - EC_7	*70*	*370*	*13*	*26000*	*56000*	*76000*
$EC_{>7}$ - EC_8	*130*	*860*	*22*	*56000*	*56000*	*87000*
$EC_{>8}$ - EC_{10}	*34*	*47*	*8.6*	*3500*	*5000*	*7200*
EC_{10} - EC_{12}	*74*	*250*	*13*	*16000*	*5000*	*9200*
EC_{12} - EC_{16}	*140*	*1800*	*23*	*36000*	*5100*	*10000*
$EC_{>16}$ - EC_{21}	*260*	*1900*	*46*	*28000*	*3800*	*7600*
$EC_{>21}$ - EC_{35}	*1100*	*1900*	*370*	*28000*	*3800*	*7800*
$EC_{>35}$ - EC_{44}	*1100*	*1900*	*370*	*28000*	*3800*	*7800*
Aliph + Arom EC >44-70	*1600*	*1900*	*1200*	*28000*	3800	7800
Aromatic						
Benzene	**0.08**	**0.3**	**0.017**	**28**	*72*	*90*
Ethyl benzene	**65**	**170**	**16**	**520**[8] [17000]	**520**[8] *[24000]*	**520**[8] *[17000]*
Toluene	**120**	**610**	**22**	**860**[8] [59000]	**860**[8] *[56000]*	**860**[8] *[87000]*
Xylene[9]	**41**	**53**	**28**	**480**[8] [69000]	**480**[8] *[41000]*	**480**[8] *[17000]*
Phenol	**180**	**310**	**66**	**760**[14] (31000)	**760**[14] *(10000)*	**760**[14] *(7600)*
Polycyclic Aromatic Hydrocarbons (PAH)						
Naphthalene	*2.3*	*2.3*	*4.1*	*190*	*4900*	*1200*
Acenaphthylene	*170*	*2900*	*28*	*83000*	*15000*	*29000*
Acenaphthene	*210*	*3000*	*34*	*84000*	*15000*	*29000*
Fluorene	*170*	*2800*	*27*	*63000*	*9900*	*20000*
Phenanthrene	*95*	*1300*	*15*	*22000*	*3100*	*6200*
Anthracene	*2400*	*31000*	*380*	*520000*	*74000*	*150000*
Fluoranthene	*280*	*1500*	*52*	*23000*	*3100*	*6300*
Pyrene	*620*	*3700*	*110*	*54000*	*7400*	*15000*
Benz(a)anthracene	*7.2*	*11*	*2.9*	*170*	*29*	*49*
Chrysene	*15*	*30*	*4.1*	*350*	*57*	*93*
Benzo(b)fluoranthene	*2.6*	*3.9*	*0.99*	*44*	*7.1*	*13*
Benzo(k)fluoranthene	*77*	*110*	*37*	*1200*	*190*	*370*
Benzo(a)pyrene	*2.2*	*3.2*	*0.97*	*35*	*5.7*	*11*
Indeno(123cd)pyrene	*27*	*45*	*9.5*	*500*	*82*	*150*
Dibenzo(ah)anthracene	*0.24*	*0.31*	*0.14*	*3.5*	*0.57*	*1.1*
Benzo(ghi)perylene	*320*	*360*	*290*	*3900*	*640*	*1400*
Chlorinated Aliphatic Hydrocarbons						
Vinyl chloride	*0.00064*	*0.00077*	*0.00055*	*0.059*	*3.5*	*4.8*
Trichloroethene (TCE)	*0.016*	*0.017*	*0.041*	*1.2*	*120*	*70*
1,1,1,2 Tetrachlorethane	*1.2*	*1.5*	*0.79*	*110*	*1400*	*1500*
Tetrachlorethene (PCE)	*0.18*	*0.18*	*0.65*	*19*	*1400*	*810*
1,1,1 Trichlorethane	*8.8*	*9*	*48*	*660*	*140000*	*57000*

Notes

1. All values above are in mg/kg
2. **Numbers in bold are SGVs or GAC that are derived based on SGV report input parameters**, *numbers in italics are S4ULs*, ***numbers in bold-italics are based on EIC/AGS/CL:AIRE numbers & input parameters*** and underlined numbers are C4SLs
3. Soil organic matter (SOM) is assumed to be 1% - DEFAULT VALUE
4. Soil type is assumed to be sandy loam - DEFAULT SOIL TYPE
5. For residential, the building type is conservatively assumed to be a small terrace house where the development includes bungalows change to more conservative bungalow setting in computer model
6. For commercial, the building type is conservatively assumed to be a pre 1970s office building, where the proposed development comprises houses, flat with living spaces changes setting in model accordingly
7. For classrooms consider increasing the dust loading fator in the 'Soil and Building Data' of the CLEA 1.04 model from 50 to 100µg m^{-3}
8. Based on vapour saturation limt as suggested by EA / [ ] model value
9. Lowest of o-, m- and p-xylene
10. Based on comparison of inhalation exposure with inhalation TDI
11. Based on comparison of oral, dermal, and inhalation exposure with the oral TDI
12. Based on a comparison of oral and dermal soil exposure with oral Index Dose only
13. Averaged over and based on lifetime exposure
14. Based on critical concentration for skin irritation in humans arising from contact with phenol in aqueous solution (number in brackets based on health effects following long term exposure for illustration)
15. NA: Not applicable

Appendix E – Geotextile Specification

Copyright © 2023 Curtins Consulting Ltd

Specification guide

WREKIN PRODUCTS

FASTRACK Orange

Standard Grade (SG) woven geotextile


Based on our popular 609 geotextile, FASTRACK Orange prevents the intermixing of contaminated and uncontaminated soils and its bright colour also alerts users and future users to the potential danger of further excavation. It is designed and manufactured to conform to the old Department of Transport & Highways specification for road and earthworks separation.


Applications for FASTRACK Orange:


- Highly visible 'Warning layer'
- Separating/Strengthening - layer under access roads and areas of hard standing
- Separation – layers under stone foundations for new buildings
- Separation – layers under new roads, car parks & industrial areas
- Separation – granular fill from sub soils and other fill types

Mechanical properties	Test	Units	FASTRACK Orange
Tensile strength - MD	EN ISO 10319	kN/m	16
Tensile strength - XD	EN ISO 10319	kN/m	11.5
Elongation at break - MD	EN ISO 10319	%	18.5
Elongation at break - XD	EN ISO 10319	%	18.5
CBR puncture resistance	EN ISO 12236	N	1500
Hydraulic properties			
Water flow normal to the plane	EN ISO 11058	l/m²/s	17
Characteristic opening (pore) size	EN ISO 12956	µm	250
Physical properties			
Thickness under 2 kPa	EN ISO 9863-1	mm	0.4
Weight	EN ISO 9864	g/m²	75
Roll width		cm	450
Roll length		m	100

WREKIN FASTRACK







Link-up Registered

UK

CE

1. Wrekin Products Ltd reserves the right to alter product specifications without prior notice.
2. It is the responsibility of all users to satisfy themselves that the above data is current.
3. The above figures are average values obtained in testing to current EN geotextiles test standards. Although not guaranteed these results do, to the best of our knowledge, offer a true and accurate record of the product's performance.
4. Polypropylene is the constituent polymer used in the production of Fastrack Orange.
5. Wrekin cannot be held responsible for the performance of these products as conditions of use are beyond our control.
6. Installation details are available on request.

52-1312A

Other grades of geotextiles within the Wrekin range include:
High Flow and High Strength woven fabrics and Thermal-bonded & Needle Punched non-wovens.

WREKIN PRODUCTS LIMITED Europa Way, Britannia Enterprise Park, Lichfield, WS14 9TZ
www.wrekinproducts.com
T: 01543 440440
F: 01543 440444
E: sales@wrekinproducts.com

Appendix F – E-mail Correspondence

Copyright © 2023 Curtins Consulting Ltd

RE: [External] Gorton Lane - Garden Plot Validation

robert.lynch@equans.com <robert.lynch@equans.com>

Thu 16/11/23 12:22

To:Jonathan Lord <Jonathan.Lord@curtins.com>;Lucy Woods <Lucy.Woods@curtins.com>
Cc:oliver.bennison@equans.com <oliver.bennison@equans.com>;kenzo.iluobe@equans.com <kenzo.iluobe@equans.com>;rachel.eatson@equans.com <rachel.eatson@equans.com>; lee.jones@equans.com <lee.jones@equans.com>;Jordan.SLATTERY@equans.com <Jordan.SLATTERY@equans.com>;Russell Taylor <Russell.Taylor@curtins.com>;Niall Farnworth <Niall.Farnworth@curtins.com>

Good Afternoon Jonathan

Just to clarify the following;

'Whilst the ground works were being carried out that there was no further contamination was found during the works'.

Can you please confirm what further/outstanding information you require for Remediation/Validation?

1st soil validation visit was carried to site 2 today.
Final visit booked for 23/11/23.

Kind Regards

Rob

EQUANS

ROB LYNCH MCIOB
Operations Manager
Places and Communities

UK & IRELAND

M 07583 097 722
THE Lighthouse,Salford Quays
Salford.M50 3BF

www.equans.co.uk

Please consider the environment before printing this message

From: Jonathan Lord <Jonathan.Lord@curtins.com>
Sent: Friday, November 10, 2023 9:53 AM
To: LYNCH Robert (EQUANS UK) <robert.lynch@equans.com>; Lucy Woods <Lucy.Woods@curtins.com>
Cc: BENNISON Oliver (EQUANS UK) <oliver.bennison@equans.com>; ILUOBE Kenzo (EQUANS UK) <kenzo.iluobe@equans.com>; EATSON Rachel (EQUANS UK) <rachel.eatson@equans.com>; JONES Lee (EQUANS UK) <lee.jones@equans.com>; SLATTERY Jordan (EQUANS UK) <Jordan.SLATTERY@equans.com>; Russell Taylor <Russell.Taylor@curtins.com>; Niall Farnworth <Niall.Farnworth@curtins.com>
Subject: RE: [External] Gorton Lane - Garden Plot Validation

RE: [External] Gorton Lane - Garden Plot Validation

robert.lynch@equans.com <robert.lynch@equans.com>

Thu 23/11/23 11:40

To:Jonathan Lord <Jonathan.Lord@curtins.com>;Lucy Woods <Lucy.Woods@curtins.com>
Cc:oliver.bennison@equans.com <oliver.bennison@equans.com>;lee.jones@equans.com <lee.jones@equans.com>

2 attachments (1 MB)

Asbestos Management Process.pdf; Asbestos Management Plan.docx;

Good Morning Jonathan

Further to previous emails and correspondence with regards Asbestos Management etc.

- Besides asbestos that was noted in the SI report, and remediated accordingly(evidence provided previously),no further or additional asbestos was discovered during the ground works and piling works.
- I have attached for your information a copy of our generic Asbestos Management Process and Asbestos Management Plan which would utilised should any additional asbestos be discovered during the works.
- All Equans Site Management receive regular Asbestos Awareness training as part of Company policy and procedure, this is to ensure that they recognise asbestos if discovered and what to actions to be taken if this is the case.
- On this site, due to asbestos being noted in the SI report-the Site Management team also received specific Asbestos in soils training.
- All operatives who attended site during the Groundworks phase, were also made aware as part of the induction process that there was potential asbestos on site and what they must do should they discover asbestos or suspected asbestos(i.e. Stop work immediately, cordon off the area and report to their site supervisor who would then notify Equans Management -who would then implement asbestos management process and plan -in conjunction with in house SHEQ team.
- Groundworkers supervisor and staff also receive asbestos awareness training to ensure that they know what to do in the event of discovering asbestos(as noted above).

I hope that this is sufficient for you to close out this item, please advise if you require further.

Kind Regards
Rob

EQUANS

ROB LYNCH MCIOB
Operations Manager
Places and Communities

From: Jonathan Lord <Jonathan.Lord@curtins.com>
Sent: Thursday, October 26, 2023 11:02 AM

From: robert.lynch@equans.com
Sent: 12 March 2024 08:58
To: Niall Farnworth; oliver.bennison@equans.com; Matthew Holroyd
Cc: hannah.k@omiarchitects.com; Lucy Woods
Subject: RE: [External] CDN/24/0030 - Lane Bounded By Pottery Lane, Gorton Lane, Belle Vue Street And Poleworth Close

Good Morning Matt

Following our telephone conversation just to confirm that topsoil has been installed to Plots no 6 (12 Gorton Lane),to a level of 450mm.
This is in line with the topsoil placement to all other front gardens of 450mm.

Kind Regards
Rob

EQUANS
ROB LYNCH MCIOB


EQUANS Mail Disclaimer: https://www.equans.com/disclaimer/disclaimer-mail/en

Appendix G – Documentation

Copyright © 2023 Curtins Consulting Ltd

Asbestos Management Plan

Site Plan



These areas contain or may contain asbestos.

- Roof
- Downpipes
- Van brakes
- Plant Room – boiler, flue, steam pipe insulation, electric switch-box
- Work Room – steam pipe insulation, oven insulation, heat-proof gloves
- Store – floor tiles, ceiling tiles
- Office 1 – fire door
- Office 2 – board screwed to fire door

Asbestos Management Plan

Asbestos Register

Insert Asbestos Register here

Asbestos Management Plan

Asbestos Action Plan

Where	Product	Action	By When	By Whom

Responsible Person		Date		Monitoring Date	

Asbestos Management Plan

Communication Plan

1 Stickers

2 Staff

3 Maintenance

4 Contractors

5 Others


All Asbestos works must be undertaken by an asbestos competent contractor. Under no circumstances should this work be carried out by EQUANS employees as we are not insured for this type of work.

Feedback

EQUANS

Asbestos Management Process

Process



Outputs

Guidance

Asbestos Management Process Guidance

Process

Feedback

EQUANS

No	Process Step	Guidance Notes	Who	Deliverables
1	Review scope and asbestos information.	• Review if built or refurbished before 2000 – assume asbestos present • Review Asbestos Register • Review Asbestos Survey – management or R&D or archetype (10% minimum) is permitted where there has been samples taken. • If post 2000 we just need a statement in the H&S file to confirm this.	Responsible Person	
2	Is available asbestos information adequate ?	• Where available information is inadequate commission further surveys to meet the scope of works. Ensure the scope of the asbestos survey is clearly outlined to the asbestos surveyor. Ensure it is agreed with the Client who is responsible for payment of surveys.	Responsible Person	
3	Will asbestos impact on works or work impact on asbestos ?	• If no : ensure asbestos is clearly identified and communicated to the workforce. • If yes : follow yes arrow.	Responsible Person	
4	Possibility of asbestos in soil ?	• Ensure asbestos surveyor undertakes preliminary risk assessment and outlines soil sampling requirements and asbestos risks and appropriate control measures.	Responsible Person	
5	Follow Asbestos Licensable Work Process.	• Where there is known potential of asbestos exposure refer to the Asbestos Licensable Work Process. • For example Loose or damaged Asbestos Insulation Board	Responsible Person	
6	Follow Notifiable Non-Licensable Work Process.	• Ensure that Notifiable Non-Licensable Work Process is followed. • For example short duration works on Asbestos Insulation Board	Responsible Person	
7	Follow Non-notifiable Non-licensable Work Process.	• Ensure that the Non-notifiable Non-licensable Work Asbestos Process is followed. • For example maintenance works, low fibre release, good condition asbestos cement	Responsible Person	

UNCONTROLLED COPY IF PRINTED OR DOWNLOADED

RISK ASSESSMENT

Workplace	[LOCATION]	**Assessment Number**	X 2617
Task / Activity	Contaminated land		

Date Conducted:	04.01.21	**Review by Date:**	On commencement	**Date Reviewed**	
Assessment Team	M.Mcstravik -Kellys Groundworks Contracts Manager -Risk Assessment for hazardous/contaminated ground				

1 Hazard (something with the potential to cause harm, how will it be realised and what is the potential injury?)	**2 At Risk**	**Risk** 3 Severity	4 Probability	5 Risk	**6 Control Measures**	**Risk** 7 Severity	8 Probability	9 Risk
Unknown contaminant, Unsafe access/Egress and Inadequate hygiene facilities, major/minor illness or fatality	A	5	3	15	• Contamination report • Must have safe access and egress for plant • Adequate hygiene facilities must be provided			
Untrained operatives, Inadequate PPE, mobile plane and waste disposal. Serious injuries or illness	A	4	3	12	• Trained and competent operatives • Banksman for plant reversing • Waste disposal notes in place • Licensed tip used • Correct PPE provided and worn			
Disposal of waste Waste contaminating land	A	5	3	15	• Waste must be disposed of in bins/skips whilst on site • Waste is to be segregated before being placed into skips on site • The skips must be taken to a licenced waste disposal site by a licenced contractor • Any waste taken back to our depot must be done so by a licenced carrier • Any waste taken back to our depot must be then disposed of responsibly • When transferring waste consignment notices must be collected and kept on file • Any employees found fly-tipping will be reported to the police	5	1	5
Purchase of materials Causing unnecessary pollution	A	5	3	15	• Materials must always be purchased from suppliers who can prove that their products are environmentally friendly • Suppliers must be chosen with regard to their environmental credentials • Suppliers must inform us of any changes in their recycling policy	5	1	5
Further Actions	(Further control measures that could be implemented to improve safety)					**Action by who & date**		

At Risk (column 2)	**Severity** (column 3 and 7)		**Probability** (column 4 and 8)		**Risk Rating** (column 5 and 9)		
E - Employees	1	No Injury, property damage	1	Very Unlikely	Severity X Probability = **1 to 5**	**Low**	**Y** – acceptable risk, work can start
C - Contractors	2	Minor Injury	2	Unlikely			
V - Visitors	3	+7 Day Absence	3	Likely	Severity X Probability = **6 to 14**	**Med**	**Y or N** – may need further consideration
P - Public	4	Specified Injury	4	Very Likely			
A - All	5	Death	5	Virtually Certain	Severity X Probability = **15 to 25**	**High**	**N** – Unacceptable risk Do not start work

RISK ASSESSMENT

Workplace	[LOCATION]	**Assessment Number**	X 2617
Task / Activity	Contaminated land		

Additional Comments	(Actions identified by personnel on site to make the task safer)	
Authorised by The Responsible Manager	**Name:** **D.Summers** **Position:Project Manager** **Signature:**	**Dated:**

At Risk (column 2)	**Severity** (column 3 and 7)		**Probability** (column 4 and 8)	**Risk Rating** (column 5 and 9)		
E - Employees	**1**	No Injury, property damage	**1**	Very Unlikely	Severity X Probability = **1 to 5**	**Low**	**Y** – acceptable risk, work can start
C - Contractors	**2**	Minor Injury	**2**	Unlikely			
V - Visitors	**3**	+7 Day Absence	**3**	Likely	Severity X Probability = **6 to 14**	**Med**	**Y or N** – may need further consideration
P - Public	**4**	Specified Injury	**4**	Very Likely			
A - All	**5**	Death	**5**	Virtually Certain	Severity X Probability = **15 to 25**	**High**	**N** – Unacceptable risk Do not start work

FNW|369832

Supplied by : Bolton C&L
A Trading Brand of Huws Gray Limited

Tel: 01204 862222

ADVICE/DELIVERY NOTE
COPY

Invoice To:
KELLY CONTRACTING LIMITED
Alvanley Industrial Estate
Stockport Road East
Bredbury
STOCKPORT
SK6 2DJ
Phone:0161 406 6228

Deliver To:
KELLY CONTRACTING LIMITED
Gorton Lane
Gorton
Manchester
Lee 07818595731
M12 5HD
Mobile:0161 406 6228

Order No :FNW/369832/ 2
Page : 1
Doc Date :15/06/2023 10:18
Deliver On :16/06/2023
Driver :
Vehicle Reg :
Type Of Sale:Credit Delivered
Customer Acc:OLL0063/ 0

Oper Customer Ref 1/2
TH12 293/AM

Special Message/Comment

ORDERED	PRODUCT NO	DESCRIPTION	THIS DELIVERY	BALANCE TO FOLLOW
25	2310042	ACO RAINDRAIN & GALV STEEL GRATING A15 1.M 47000	25	0
6	2394502	MATRIX UU SPEC BOUNDARY BOX 25MM E8951	6	0
12	2394062	PROTECTA-LINE 25MM X 3/4IN M/I END CONN 44151608	12	0
1	2340257	POLYGUARD 25MM END CAP PGF40925	1	0
2	3410146	PROSOLVE PETRO TAPE 75MMX10M	2	0
2	P027179	POLYGUARD PIPE 25MM X 50M COIL PGP2550	2	0

Goods Received By

Printed:

Signed:

IT IS THE CUSTOMER'S RESPONSIBILITY TO OBTAIN ANY PERMITS AND SUPPLY ANY RELEVANT EQUIPMENT REQUIRED TO ENABLE MATERIALS TO BE LEFT ON THE HIGHWAY.TERMS AND CONDITIONS AVAILABLE AT WWW.HUWSGRAY.CO.UK/TERMSANDCONDITIONS

Supplied by : Bolton C&L Tel: 01204 862222
A Trading Brand of Huws Gray Limited

ADVICE/DELIVERY NOTE

Invoice To:
KELLY CONTRACTING LIMITED
Alvanley Industrial Estate
Stockport Road East
Bredbury
STOCKPORT
SK6 2DJ
Phone:0161 406 6228

Deliver To:
KELLY CONTRACTING LIMITED
Gorton Lane
Gorton
Manchester
Lee 07818595731
M12 5HD
Mobile:0161 406 6228

Order No :FNW/370142/ 1
Page : 1
Doc Date :20/06/2023 14:39
Deliver On :21/06/2023
Driver :
Vehicle Reg :
Type Of Sale:Credit Delivered
Customer Acc:OLL0063/ 0

Special Message/Comment

Oper Customer Ref 1 2
TH12 293 AM

ORDERED	PRODUCT NO	DESCRIPTION	THIS DELIVERY	BALANCE TO FOLLOW
6	4908229	TELE BARRIER M.BOX 1/4T MATRIX LID 3/4 MBB1100FC	6	0

Goods Received By

Printed: Lauren Brown

Signed:

IT IS THE CUSTOMER'S RESPONSIBILITY TO OBTAIN ANY PERMITS AND SUPPLY ANY RELEVANT EQUIPMENT REQUIRED TO ENABLE MATERIALS TO BE LEFT ON THE HIGHWAY.TERMS AND CONDITIONS AVAILABLE AT WWW.HUWSGRAY.CO.UK/TERMSANDCONDITIONS

OFFICE COPY

WIAPS
WATER INDUSTRY APPROVED PLUMBERS' SCHEME

CERTIFICATE OF COMPLIANCE

WIAPS
WATER INDUSTRY APPROVED PLUMBERS' SCHEME

White copy: Customer **Blue copy:** Water Company **Green copy:** retain for records

NEW SUPPLY Yes ☑ No ☐ Internal ☑ External ☑

Water Company Application/Reference Number:

Member's Name: ANDREW MITCHELL

Membership No: CW 6253

Company Name: KELLY CONTRACTING LTD

Membership Expiry Date: 03/07/23.

Telephone Number: 07973 164397

Email address: ANDY@KELLYCONTRACTING.CO.UK

Address where work carried out (please include plot numbers where applicable):

EQUANS - SITE 2 - GORTON LANE M12 5HD

Plot No:	Plot No:	Plot No:	Plot No:	Plot No:	Plot No:
104	109				

Name and address of the person who commissioned the work (the customer):

EQUANS NEWCASTLE UPON TYNE NE12 8BU

Telephone Number: 07989 214 733

Email address: SORORA.SLATTERY@EQUANS.COM

Please give a brief description of the work completed and its location within the premises:

NEW 25mm BARRIER PIPE LAID FROM UNDER KITCHEN SINK TO EXTERNAL APLAS BOX THEN TO REAR OF FOOT PATH (INSULATED UNDER FLOOR 750mm COVER TO PIPE.

I confirm that the work carried out complies with the Water Supply (Water Fittings) Regulations 1999, Water Supply (Water Fittings) (Scotland) Byelaws 2014 or Water Supply (Water Fittings) Regulations (Northern Ireland) 2009.

Signed: [signature]

Date: 26/6/23.

Print: A MITCHELL

Certificate No: P 360154

WIAPS
WATER INDUSTRY APPROVED PLUMBERS' SCHEME

CERTIFICATE OF COMPLIANCE

WIAPS
WATER INDUSTRY APPROVED PLUMBERS' SCHEME

White copy: Customer **Blue copy:** Water Company **Green copy:** retain for records

NEW SUPPLY Yes ☑ No ☐ Internal ☑ External ☑

Water Company Application/Reference Number:

Member's Name: ANDREW MITCHELL

Membership No: CU 6253

Company Name: KELLY CONTRACTING LTD

Membership Expiry Date: 31/7/24

Telephone Number: 07973 164 397

Email address: ANDY@KELLYCONTRACTING-CO.UK

Address where work carried out (please include plot numbers where applicable):

EQUANS SITE 2 FOLLESWORTH CLOSE GORTON M12 5HD

Plot No:	Plot No:	Plot No:	Plot No:	Plot No:	Plot No:
105	106	107	108		

Name and address of the person who commissioned the work (the customer):

EQUANS NEWCASTLE UPON TYNE NE12 8BU

Telephone Number: 07989 214 733

Email address: GORDON.SUTTON@EQUANS.COM

Please give a brief description of the work completed and its location within the premises:

NBLD 25mm BARRIER PIPE LAID FROM UNDER SINK TO EXTERNAL APLUS BOX THEN TO REAR OF FOOTPATH (INSULATED UNDER FLOOR) 750mm COVER.

I confirm that the work carried out complies with the Water Supply (Water Fittings) Regulations 1999, Water Supply (Water Fittings) (Scotland) Byelaws 2014 or Water Supply (Water Fittings) Regulations (Northern Ireland) 2009.

Signed: [signature]

Date: 7/8/23.

Print: A MITCHELL

Certificate No: P 360157

CERTIFICATE OF COMPLIANCE

White copy: Customer **Blue copy:** Water Company **Green copy:** retain for records

NEW SUPPLY Yes [✓] No [ ] Internal [✓] External [✓]

Water Company Application/Reference Number:

Member's Name: ANDREW MITCHELL Membership No: GW 6283

Company Name: KELLY CONTRACTING LTD Membership Expiry Date: 03/07/23.

Telephone Number: 07973 164 397 Email address: ANDY@KELLYCONTRACTING.CO.UK.

Address where work carried out (please include plot numbers where applicable):

EQUANS - SITE 1 - GORTON LANE M12 5DF

Plot No:	Plot No:	Plot No:	Plot No:	Plot No:	Plot No:
7	8	9	10	11	12

Name and address of the person who commissioned the work (the customer):

EQUANS NEWCASTLE UPON TYNE NE12 8BU

Telephone Number: 07984 214 733 Email address: GORDON.SLATTERY@EQUANS.COM

Please give a brief description of the work completed and its location within the premises:

NEW 25mm BARRIER PIPE LAID FROM UNDER KITCHEN SINK TO EXTERNAL APLIS BOX THEN TO REAR OF FOOTPATH - INSULATED UNDER FLOOR. 750mm COVER TO PIPES.

I confirm that the work carried out complies with the Water Supply (Water Fittings) Regulations 1999, Water Supply (Water Fittings) (Scotland) Byelaws 2014 or Water Supply (Water Fittings) Regulations (Northern Ireland) 2009.

Signed: [signature] Date: 5/6/23.

Print: A MITCHELL Certificate No: P 360153

CERTIFICATE OF COMPLIANCE

White copy: Customer **Blue copy:** Water Company **Green copy:** retain for records

NEW SUPPLY Yes [✓] No [ ] Internal [✓] External [✓]

Water Company Application/Reference Number:

Member's Name: ANDREW MITCHELL Membership No: 6253 GW

Company Name: KELLY CONTRACTING LTD Membership Expiry Date: 03/07/23.

Telephone Number: 07973 164 397 Email address: ANDY@KELLYCONTRACTING.CO.UK

Address where work carried out (please include plot numbers where applicable):

EQUANS - SITE 1 GORTON LANE M12 5DF

Plot No:	Plot No:	Plot No:	Plot No:	Plot No:	Plot No:
1	2	3	4	5	6

Name and address of the person who commissioned the work (the customer):

EQUANS NEWCASTLE UPON TYNE NE12 8BU

Telephone Number: 07984 214 733 Email address: GORDON.SLATTERY@EQUANS.COM

Please give a brief description of the work completed and its location within the premises:

NEW 25mm BARRIER PIPE LAID FROM UNDER KITCHEN SINK TO EXTERNAL APLIS BOX THEN TO REAR OF FOOTPATH ON GORTON LANE. INSULATED UNDER FLOOR 750mm COVER TO P.I.S.

I confirm that the work carried out complies with the Water Supply (Water Fittings) Regulations 1999, Water Supply (Water Fittings) (Scotland) Byelaws 2014 or Water Supply (Water Fittings) Regulations (Northern Ireland) 2009.

Signed: [signature] Date: 5/6/23.

Print: A MITCHELL Certificate No: P 360152

Appendix H –Waste Consignment Tickets

Copyright © 2023 Curtins Consulting Ltd

VEOLIA

SITE TRANSACTION TICKET
CONTROLLED WASTE TRANSFER NOTE

Veolia ES (UK) Ltd
210 Pentonville Road
London, N1 9JY
Tel: 020 7812 5000 Fax: 020 7812 5001

OUR ORDER NO : WMLON88148
CUSTOMER ORDER NO :

Consignor confirms that the waste hierarchy has been applied.

Whitemoss Landfill Site, White Moss Road South, , , WN8 9TH. 01695 559948
DP3639LM

VAT Registration No: GB 530 0088 93

Ticket No. WBWML27352 — SIC Code : 43.12

Con. No.	Date	Time	First Weight
I:0047046	09/04/2021	11:26	29.300 t
Con. No.	**Date**	**Time**	**Second Weight**
I:0047051	09/04/2021	11:38	13.600 t
Cust Ref:			Net Weight
Cust Account No. 0237WM			15.700 t

Material:Soil - Haz

A tallyroll copy of this transaction is available for inspection for six months.

Load Date : 09/04/2021 11:26 Checked by: BRIAN MCGONIGLE
Customer : W.Maher & Sons Ltd.
Vehicle : MK21BXZ
Address : W.Maher & Sons Ltd. Soapstone Way Off Fairhills Road Irlam Manchester M44 6RA — Kelly Contracting Ltd Gorton Lane Manchester M12 5WF
Carrier : W.Maher & Sons Ltd. CBDU90617

EWC Code: 170605
EWC Description: HAZ construction materials containing asbestos

Weighed By: DAVE ROUTLEDGE Changed By: DAVE ROUTLEDGE

Driver's Name (Block Capitals) and Signature
Sean Davenport

Weighbridge Operator's Name and Signature
DAVE ROUTLEDGE
D Routledge

VES242 10/14

Maher

CN 221823

W. MAHER & SONS LTD.
Rixton Old Hall, Manchester Road, Rixton, Warrington WA3 6EW
T: 0161 776 2200 E: enquiries@wmaherandsons.com

Bulk Excavation & Disposal • Ground Remediation
Quarried & Recycled Aggregates • Site Preparation

CONSIGNMENT NOTE

Customer: Keltbray	Date: 9 4 21
Loaded at: Carrington	
Delivered to: Warrington West Station	
Driver: Tom	Veh. Reg. [illegible]

Tick		Material
☐	1 x 8 wh. load: Off Site	Made Ground
☐	1 x 8 wh. load: Delivered	

Daywork / Sitework	Hours Worked		Travel Time		Total Hours	
Foreman or Agent's Signature		T. Wade				

CONDITIONS OF SALE: It is essential that all written particulars entered above should be carefully checked by the consignee since this delivery note, once signed by the consignee, represents formal acceptance of the material in good order and condition and subsequent complaints cannot be accepted.
All complaints whether in respect of material or circumstances of delivery must be made to the driver of the vehicle and be confirmed in writing direct to the company immediately.
All materials and title to same remain the property of supplier until paid in full.

THIS IS NOT A WASTE TRANSFER NOTE | Form MAH/OD/16 V.06 04/19

Maher
W.Maher & Sons Ltd.
Civil Engineering Contractors

W. MAHER & SONS LTD.
Rixton Old Hall, Manchester Road, Rixton, Warrington WA3 6EW
T : 0161 776 2200 F: 0161 848 7357
E : enquiries@wmaherandsons.com
W : www.wmaherandsons.com

Waste Transfer Note

SECTION A - DESCRIPTION OF WASTE (To be completed by Holder/Producer of the waste)

EWC Code (*Tick one box only*)

	17:01:01	Concrete	✓	17:05:04	Naturally occurring sub-soil and crushed stone
	17:01:02	Bricks		17:09:04	Mixed construction and demolition waste
	17:01:07	Concrete, brick and tile			Other: Insert EWC and describe below
					Acn < 0.001%

How is the waste Contained

8 Wheel Tipper ☑

SECTION B - HOLDER / PRODUCER OF THE WASTE

SIC

Holder / Producer: _____

Location/address of the Collection Point: _____

Declaration (by Holder)
I have fulfilled my duty to apply the waste hierarchy as required by Regulation 12 of the Waste (England & Wales) Regulations 2011.

Name: | Signature:

SECTION C - PERSON COLLECTING THE WASTE (CARRIER)

SIC 4 9 4 1 0

Carrier: W Maher & Sons Ltd

Carrier Address: Rixton Old Hall, Manchester Road, Rixton, Warrington WA3 6EW

Carrier Registration No.: CBDU90617 Expiry Date: 25/03/2022 Issued by: Environment Agency

Date of Transfer: 25-3-22 (for multiple consignments state duration, max 12 months)

Name: M. Fouchol | Signature:

SECTION D - DISPOSAL / RECOVERY FACILITY (Indicate facility used)

Facility Operator: Churchill Enviro Ltd

Facility Address: ☑ Fletcher Bank, Ramsbottom, BL0 0HD ☐ Hutchbank, Haslingden, BB4 4PB

Facility Permit No.: EPR/GP3733 FE EPR/BB 3702 HL

Date of Transfer: 25-3-23 (for multiple consignments, state duration, max 12 months)

Name: M. M ALONE | Signature:

IF WASTE IS SENT DIRECTLY TO LANDFILL SITE IN ENGLAND OR WALES THE FOLLOWING DECLARATION MUST BE SIGNED (BY CARRIER).

I/We confirm that the waste delivered by the above named company has been treated as highlighted below.


The material has gone through a physical, thermal, chemical or biological process including: sorting characteristics of the waste have been changed/volume has been reduced/ hazardous nature has been reduced/handling has been facilitated/recovery has been enhanced. (Delete as required)

Name: | Signature:

DISTRIBUTION:	WHITE-HOLDER	YELLOW-OFFICE	BLUE-FACILITY OPERATOR

THIS DOCUMENT MUST BE RETAINED UNTIL 2 YEARS AFTER LAST TRANSFER DATE SHOWN IN SECTION D

SITE 1 CP1



SITE 2

VEOLIA

SITE TRANSACTION TICKET
CONTROLLED WASTE TRANSFER NOTE

Veolia ES (UK) Ltd
210 Pentonville Road
London, N1 9JY
Tel: 020 7812 5000 Fax: 020 7812 5001

OUR ORDER NO : WMLON88148
CUSTOMER ORDER NO :

Consignor confirms that the waste hierarchy has been applied.

Whitemoss Landfill Site, White Moss Road South, , , WN8 9TH. 01695 559948
DP3639LM

VAT Registration No: GB 530 0088 93

SIC Code : 43.12

Ticket No.			
			WBWM 27352
Con. No.	Date	Time	First Weight
I:0047046	09/04/2021	11:26	29.300 t
Con. No.	Date	Time	Second Weight
I:0047051	09/04/2021	11:38	13.600 t
Cust Ref:			Net Weight
Cust Account No.	0237MM		15.700 t

Load Date : 09/04/2021 11:26 Checked by: BRIAN MCSONIGLE
Customer : W.Maher & Sons Ltd.
Vehicle : MK21BXZ
Address : W.Maher & Sons Ltd. Kelly Contracting Ltd
: Soapstone Way Gorton Lane
: Off Fairhills Road
: Irlam
: Manchester Manchester
:
: M44 6RQ M12 5WF
Carrier : W.Maher & Sons Ltd. CBDU90617

Material:Soil - Haz

A tallyroll copy of this transaction is available for inspection for six months.

EWC Code: 170605
EWC Description: HAZ construction materials containing asbestos

Weighed By: DAVE ROUTLEDGE Changed By: DAVE ROUTLEDGE

Driver's Name (Block Capitals) and Signature
Sean Davenport

Weighbridge Operator's Name and Signature
DAVE ROUTLEDGE D Routledge

VES342 10/14

Maher

CN 221823

W. MAHER & SONS LTD.
Rixton Old Hall, Manchester Road, Rixton, Warrington WA3 6EW
T: 0161 776 2200 E: enquiries@wmaherandsons.com

Bulk Excavation & Disposal • Ground Remediation
Quarried & Recycled Aggregates • Site Preparation

CONSIGNMENT NOTE

Customer: Kelly	Date: 9 4 21
Loaded at: Carr L	
Delivered to: Whitemoss Stor	
Driver: Tony	Veh. Reg. [illegible]
Tick ☐ 1 x 8 wh. load: Off Site	Material Rock Limestone
Tick ☐ 1 x 8 wh. load: Delivered	Material

Daywork / Sitework	Hours Worked		Travel Time		Total Hours	
Foreman or Agent's Signature		[illegible]				

CONDITIONS OF SALE: It is essential that all written particulars entered above should be carefully checked by the consignee since this delivery note, once signed by the consignee, represents formal acceptance of the material in good order and condition and subsequent complaints cannot be accepted.
All complaints whether in respect of material or circumstances of delivery must be made to the driver of the vehicle and be confirmed in writing direct to the company immediately.
All materials and title to same remain the property of supplier until paid in full.

THIS IS NOT A WASTE TRANSFER NOTE