Window Schedule - East				
Mark	Height (mm)	Width (mm)	Required	Description
Level 02				
02-001	2366	1041	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Electrical Window Actuators required / Blinds
02-002	2366	1041	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Electrical Window Actuators required / Blinds
02-003	2366	1041	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Electrical Window Actuators required / Blinds
02-004B	2085	1010	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
02-005B	2085	1010	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
02-006A	1260	1010	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Electrical Window Actuators required / Blinds
02-006B	2085	1010	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
02-007A	1260	1010	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Electrical Window Actuators required / Blinds
02-007B	2085	1010	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
02-008A	1260	1010	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Electrical Window Actuators required / Blinds
02-008B	2085	1010	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
02-009A	1260	1010	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Electrical Window Actuators required / Blinds
02-009B	2085	1010	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
02-010A	1260	1010	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Electrical Window Actuators required / Blinds
02-010B	2085	1010	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
02-011A	1260	1010	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Electrical Window Actuators required / Blinds
02-011B	2085	1010	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds

1 Proposed Window Glazing Alterations_East Elevation

1 : 100

Notes:
- This drawing is copyright.
- Do not scale dimensions from this drawing.
- This drawing is to be read in conjunction with all other relevant drawings.
- All discrepancies on this drawing are to be reported to the architect.
- Do not modify any element of this drawing.
- Use drawing only for purpose(s) issued.
- This drawing may contain colour.

North Point

Scale Bar

0 1m 3m 5m

Scale: 1:100

Key Plan

The following external model files are included within this drawing.

Rev	Date	Revision Notes	Drawn	Review
P6	2023/12/01	Listed Building Consent Submission.	AB	RM
P5	2023/11/24	Stage 4 Issue for Costing	MC	RM
P4	2023/10/06	Stage 4 Issue for Costing	AB	RM
P3	2023/08/04	Drawings issued for LBC Application	AB	RM
P2	2023/07/21	Preliminary Issue to Heritage Consultant	AB	RM
P1	2023/06/02	Stage 3 Preliminary Issue for costing	AB	RM

The University of Manchester

ARCADIS

Project
Rutherford Building

Drawing Title
Window + External Door Schedule_East Elevation

Job Number	Date	Security Classification	Drawn By
141532	FEB'23		MTW
Scale@A1	Purpose		Reviewed By
1 : 100	LISTED BUILDING CONSENT		RM

Drawing Number: 3210-RBUM-ARC-XX-ZZ-SH-A-3210

Revision: P6