

EWG-Q-F-101 Inspection Report Form

VISQUEEN GAS-MEMBRANE TO UNDER-SLAB

Form Reference	F1.1521628
Owned By	Michael Looby (EW Construction)
Date	02/09/2022 13:21:22
Status	Completed and signed off
Project Name	210005 Ancoats Dispensary
Project Reference	210005
Location	210005 Ancoats Dispensary
Sub-Contractor	North Star Estates
Work Package	Groundworks
Drawing/ Schedule Reference	210005-BA-XX-XX-DR-A-160003 210005-BA-XX-XX-DR-A-160004 210005-BA-XX-XX-DR-A-160006 210005-BA-XX-XX-DR-A-160007 210005-BA-XX-XX-DR-A-160009 210005-BA-XX-XX-DR-A-160010 210005-BA-XX-XX-DR-A-160011 210005-BA-XX-XX-DR-A-160013 210005-BA-XX-XX-DR-A-160015 210005-BA-XX-XX-DR-A-160014
Location of Works	210005 Ancoats Dispensary
For any issues found during inspection, please raise an appropriate task.	
Title of Works Inspection	VISQUEEN GAS-MEMBRANE TO UNDER-SLAB
Works Inspected	
Gas-membrane installed below the ground floor slab and lapping up the existing facade. Geoseal, HP DPM, Gas Barrier & Treadguard all to be checked in line with attached drawings. All laps to be 150mm and joined by heat welding. All services to be sealed using pro double sided jointing tape and foiled lap tape	
Actions to be taken	
Membrane to be patched where any holes are poor welds are highlighted. SEL issued snag list by EWC. All snags to be closed out before bricklayer starts sub-structure works w/c 21/11/22	
Date to be completed	09/09/2022
Proposed date for next inspection	16/11/2022
Can works proceed?	Yes
Actions completed?	Yes

Site Manager Sign Off

Michael Looby (EW Construction)

13/09/2022 09:12:19

Sub-Contractor Sign Off



Jonathan Crompton (North Star
Estates)

13/09/2022 09:20:29

Nothing in this document relieves the subcontractor of the responsibilities under the terms and conditions of the Subcontract Agreement

Images



[02/09/2022 13:23:38](#)



[02/09/2022 13:23:51](#)



[02/09/2022 13:24:06](#)



[02/09/2022 13:24:22](#)



[05/09/2022 10:43:20](#)



[06/09/2022 08:34:53](#)



[06/09/2022 08:35:21](#)



[07/09/2022 07:41:12](#)



[07/09/2022 07:41:29](#)



[07/09/2022 07:41:45](#)



[07/09/2022 07:42:18](#)



[07/09/2022 07:42:33](#)



[07/09/2022 07:42:48](#)



[07/09/2022 07:43:24](#)



[07/09/2022 07:44:15](#)



[13/09/2022 09:01:57](#)



[13/09/2022 09:03:10](#)



[13/09/2022 09:10:49](#)



[13/09/2022 09:10:51](#)



[13/09/2022 09:10:52](#)



[13/09/2022 09:10:53](#)



[13/09/2022 09:10:54](#)



[13/09/2022 09:10:55](#)



[13/09/2022 09:10:56](#)



[13/09/2022 09:10:57](#)



[13/09/2022 09:10:57](#)



[13/09/2022 09:10:58](#)



[13/09/2022 09:10:59](#)



[13/09/2022 09:11:00](#)




[13/09/2022 09:11:01](#)



[13/09/2022 09:11:03](#)



[13/09/2022 09:11:03](#)



[13/09/2022 09:11:05](#)



[13/09/2022 09:11:06](#)



[13/09/2022 09:11:07](#)



[13/09/2022 09:11:08](#)



[13/09/2022 09:11:09](#)



[13/09/2022 09:11:10](#)



[13/09/2022 09:11:11](#)



[13/09/2022 09:11:12](#)



[13/09/2022 09:11:13](#)



[13/09/2022 09:11:14](#)



[13/09/2022 09:11:15](#)



[13/09/2022 09:11:17](#)



[13/09/2022 09:11:18](#)



[13/09/2022 09:11:20](#)



[13/09/2022 09:11:21](#)



[13/09/2022 09:11:22](#)



[13/09/2022 09:11:23](#)



[13/09/2022 09:11:25](#)



[13/09/2022 09:11:26](#)



[17/11/2022 14:50:04](#)



[17/11/2022 14:50:05](#)



[17/11/2022 14:50:07](#)



[17/11/2022 14:50:08](#)



[17/11/2022 14:50:09](#)



[17/11/2022 14:50:10](#)



[17/11/2022 14:50:11](#)



[17/11/2022 14:50:12](#)



[17/11/2022 14:50:13](#)



[17/11/2022 14:50:14](#)



[17/11/2022 14:50:15](#)



[17/11/2022 14:50:16](#)



[17/11/2022 14:50:18](#)



[17/11/2022 14:50:19](#)



[17/11/2022 14:50:20](#)



[17/11/2022 14:50:21](#)



[17/11/2022 14:50:22](#)



[17/11/2022 14:50:23](#)



[17/11/2022 14:50:25](#)



[17/11/2022 14:50:26](#)



[17/11/2022 14:50:27](#)



[17/11/2022 14:50:28](#)



[17/11/2022 14:50:30](#)



[17/11/2022 14:50:31](#)



17/11/2022 14:50:32

Document Name	Type	Created By	Date
Visqueen Treadguard 1500.pdf	Pdf	Michael Looby (EW Construction)	06/09/2022 08:04:46
Visqueen Gas Barrier datasheet (1).pdf	Pdf	Michael Looby (EW Construction)	06/09/2022 08:04:48
Visqueen Gas Resistant Self Adhesive Membrane datasheet.pdf	Pdf	Michael Looby (EW Construction)	06/09/2022 08:04:51
Visqueen HP Tanking Primer- 5L datasheet (3).pdf	Pdf	Michael Looby (EW Construction)	06/09/2022 08:04:53
Visqueen Ultimate GeoSeal datasheet.pdf	Pdf	Michael Looby (EW Construction)	06/09/2022 08:04:55
2220578. QA Ancoates Dispensary.pdf	Pdf	Michael Looby (EW Construction)	12/09/2022 14:27:16
SEL Snag List - 03-11-2022.pdf	Pdf	Michael Looby (EW Construction)	17/11/2022 14:52:30