



RUTHERFORD BUILDING REFURBISHMENT





Photographic Survey

Submitted by Arcadis

July 2023







Office
G.058

KEY PLAN



Office
G.058




KEY PLAN





Reception G.057




KEY PLAN





Corridor G.C02/G.C03




KEY PLAN










Corridor G.C02/G.C03

KEY PLAN







Foyer
G.C01

KEY PLAN




Corridor
G.C01

KEY PLAN



Corridor
G.C01


KEY PLAN





Rutherford G.055









KEY PLAN





Stair S1.G





KEY PLAN





Store
G.056

KEY PLAN
















Stair S1.1

KEY PLAN



Kitchen 1.053






KEY PLAN













Office 1.057

KEY PLAN



Office
1.051












KEY PLAN












Office 1.052

KEY PLAN











Office
1.058

KEY PLAN






Corridor
1.C01

KEY PLAN












Corridor
1.C01

KEY PLAN



Male WC
1.054




KEY PLAN








WC & Store 1.055/1.056

KEY PLAN










Stair S1.2

KEY PLAN










Office
2.053

KEY PLAN





Office
2.059

KEY PLAN




Office
2.052

KEY PLAN




Office
M.2002

KEY PLAN










Office
2.051

KEY PLAN



Office
M2.001




KEY PLAN









Office & WC

KEY PLAN



Meeting
2.058















KEY PLAN





2.054 & 2.055

KEY PLAN





CONTACT US

Dantzic Building
Fourth Floor
Dantzic Street
Manchester M4 2AL

Tel: +44 161 696 4980
www.ibigroup.com