Donald Insall Associates
Chartered Architects and Historic Building Consultants

Manchester Studio
0161 359 4326
manchester@insall-architects.co.uk
www.donaldinsallassociates.co.uk

Discharge of Conditions










Reference	MAN.JRL.02
Project	Rylands and Beyer Building
Title	Cleaning of Stonework and Localised Repointing Works
Date	09.01.2024

Compiled by:

Donald Insall Associates







Donald Insall Associates
Chartered Architects and Historic Building Consultants

Manchester Studio
0161 359 4326
manchester@insall-architects.co.uk
www.donaldinsallassociates.co.uk

No.	Before	After	Extract from Drawing	Drawing Ref
1				2100
2 3				2100
4				2100
5				2100
6				2100
7				2100
8		No photo available		2100








Donald Insall Associates
Chartered Architects and Historic Building Consultants

Manchester Studio
0161 359 4326
manchester@insall-architects.co.uk
www.donaldinsallassociates.co.uk

9				**2100**
10				**2100**
11	 			**2100**
12		 		**2100**
13 **14**	**No photo available**	**No photo available**		**2100**
15				**2100**







Donald Insall Associates
Chartered Architects and Historic Building Consultants

Manchester Studio
0161 359 4326
manchester@insall-architects.co.uk
www.donaldinsallassociates.co.uk

16				**2100**
17	**No photo available**			**2100**
18				**2100**
19				**2100**
20	**No photo available**			**2100**
21 **22**	 			**2100**
23				**2100**







Donald Insall Associates
Chartered Architects and Historic Building Consultants

Manchester Studio
0161 359 4326
manchester@insall-architects.co.uk
www.donaldinsallassociates.co.uk

24				**2100**
25				**2100**
26	**No photo available**			**2100**
27	**No photo available**	**No photo available**		**2100**
28 29	**No photo available**			**2100**
30	**No photo available**	 		**2100**








Donald Insall Associates
Chartered Architects and Historic Building Consultants

Manchester Studio
0161 359 4326
manchester@insall-architects.co.uk
www.donaldinsallassociates.co.uk

31 **32**		**No photo available**		**2100**
33				**2100**
34	**No photo available**			**2100**
35	**No photo available**			**2100**
36 **37**				**2100**
38	**No photo available**			**2100**







Donald Insall Associates
Chartered Architects and Historic Building Consultants

Manchester Studio
0161 359 4326
manchester@insall-architects.co.uk
www.donaldinsallassociates.co.uk

39	**No photo available**			**2100**
40	**No photo available**			**2100**
41	**No photo available**			**2100**
42				
43	**No photo available**			**2100**
1				**2220**
2				**2220**







Donald Insall Associates
Chartered Architects and Historic Building Consultants

Manchester Studio
0161 359 4326
manchester@insall-architects.co.uk
www.donaldinsallassociates.co.uk

3	 	No photo available		2220
4				2220
5	No photo available			2220
6				2220
7 8				2220

Donald Insall Associates
Chartered Architects and Historic Building Consultants

Manchester Studio
0161 359 4326
manchester@insall-architects.co.uk
www.donaldinsallassociates.co.uk

9				2220
		No photo available		2220
10		No photo available		2220
11				2220
12		No photo available		2220
13		No photo available		2220