

Form detail

#172: Concrete Retaining-Lift Pit-Pit Wall Checklist



Form details

Location	
Form date	Jun 21, 2022
Description	Sub station base
Submitted by	John Carroll
Status	Submitted
Last update	Jul 8, 2022, 8:33 AM BST
Last updated by	John Carroll
Included references	Assets Documents Form details Issues Photos

1. Pre-Pour Items


1.1 Project Name
Mal external substation slab works

1.2 Date
Jun 19, 2022

1.3 Location / Area / GL Ref
Sub station

1.4 Specification / Drawing Reference
Na


Photos (2)



[20220621_112809_photo](#)

Added on Jun 21, 2022, 11:28 AM BST

Added by John Carroll



[20220621_112759_photo](#)

Added on Jun 21, 2022, 11:28 AM BST

Added by John Carroll

1.5 Starter bars installed corrected and have the required cover to reinforcement



Yes



No



N/A

Photos (3)



[20220623_075916_photo](#)

Added on Jun 24, 2022, 11:20 AM BST

Added by John Carroll



[20220621_133558_photo](#)

Added on Jun 21, 2022, 1:37 PM BST

Added by John Carroll



[20220621_133546_photo](#)

Added on Jun 21, 2022, 1:37 PM BST

Added by John Carroll

1.6 Kicker cast as required to correct line and level

☐

Yes

☐

No

☒

N/A

1.7 Kicker scabbled / jet washed to form suitable key

☐

Yes

☐

No

☒

N/A

1.8 Shutter to one side installed to correct alignment and level

☒

Yes

☐

No

☐

N/A

Photos (4)

[20220624_091649_photo](#)

Added on Jun 24, 2022, 11:20 AM BST

Added by John Carroll

[20220624_091436_photo](#)

Added on Jun 24, 2022, 11:20 AM BST

Added by John Carroll

[20220624_084608_photo](#)

Added on Jun 24, 2022, 11:20 AM BST

Added by John Carroll

[20220624_084547_photo](#)

Added on Jun 24, 2022, 11:20 AM BST

Added by John Carroll

1.9 Reinforcement installed as specified



Yes



No



N/A

Photos (3)



[20220621_100339_photo](#)

Added on Jun 21, 2022, 11:12 AM BST

Added by John Carroll



[20220621_093244_photo](#)

Added on Jun 21, 2022, 11:11 AM BST

Added by John Carroll



[20220621_093130_photo](#)

Added on Jun 21, 2022, 11:11 AM BST

Added by John Carroll

1.10 Waterbar/Hydrophilic Strips installed to required locations (Kickers, all stop ends) as required

☐

Yes

☐

No

☒

N/A

1.11 Waterbar/Hydrophilic Strips installed around diwydag sleeve if required

☐

Yes

☐

No

☒

N/A

1.12 Area cleaned of all debris

☐

Yes

☐

No

☒

N/A

1.13 HOLD POINT: Signoff by Client to Pour (Insert Name)

Kate Miller

HOLD POINT: Signoff by Client to Pour (Insert Signature)

**Name**

Kate miller

Date

June 30, 2022

2. Post Pour Items

2.1 All Diwydag holes plugged with specified mix and X-Plug Installed where required

☐

Yes

☐

No

☒

N/A

2.2 Any making good completed to wall as required

☒

Yes

☐

No

☐

N/A

2.3 Waterproofing installed to Wall prior to backfill

☐

Yes

☐

No

☒

N/A

2.4 Cavity Drain installed where required prior to backfill

☐

Yes

☐

No

☒

N/A

2.5 Drainage filter medium installed behind wall if required

☐

Yes

☐

No

☒

N/A

2.6 Wall Backfilled in stages and compacted every 150mm lifts

☒

Yes

☐

No

☐

N/A