


Revision C:
Drop ceiling has been reduced to only bathroom areas.
Suspended cable trays replaced drop ceilings in
corridor and communal areas for power distribution and
corridor lighting


2nd FFL +52.95

Section B-B - Second-Floor Corridor



NOTE* - Please ensure that an updated asbestos survey and inspection report is available before commencing with any investigation, repair, refurbishment or new works

2nd Floor Proposed Ceiling Plan



- Restored ceiling cornice**
- Area of lowered suspended ceiling for service containment - Plasterboard & Skim to 60min FR
- Area of replicated ceiling Gyproc plasterboard & skim finish to 60min FR
- Area of Vaulted Masonry - Cleaned and made good
- Area of exposed concrete - Cleaned and made good
- Area underside of stairs with any existing intrusive modern paintwork applied to existing surface to be stripped off and pointing made good. Methodology & paint specification to be agreed with planning conservation officer. *

**Note-Areas are only an approximate indication and will require a more detailed survey prior to tender

the spacestudio[™]
architects & designers

0161 275 1234
0161 275 1235
0161 275 1236
0161 275 1237
0161 275 1238
0161 275 1239
0161 275 1240
0161 275 1241
0161 275 1242
0161 275 1243
0161 275 1244
0161 275 1245
0161 275 1246
0161 275 1247
0161 275 1248
0161 275 1249
0161 275 1250
0161 275 1251
0161 275 1252
0161 275 1253
0161 275 1254
0161 275 1255
0161 275 1256
0161 275 1257
0161 275 1258
0161 275 1259
0161 275 1260
0161 275 1261
0161 275 1262
0161 275 1263
0161 275 1264
0161 275 1265
0161 275 1266
0161 275 1267
0161 275 1268
0161 275 1269
0161 275 1270
0161 275 1271
0161 275 1272
0161 275 1273
0161 275 1274
0161 275 1275
0161 275 1276
0161 275 1277
0161 275 1278
0161 275 1279
0161 275 1280
0161 275 1281
0161 275 1282
0161 275 1283
0161 275 1284
0161 275 1285
0161 275 1286
0161 275 1287
0161 275 1288
0161 275 1289
0161 275 1290
0161 275 1291
0161 275 1292
0161 275 1293
0161 275 1294
0161 275 1295
0161 275 1296
0161 275 1297
0161 275 1298
0161 275 1299
0161 275 1300

REVISIONS

A-1	Minor changes to layout	19-12-2022
A-2	Updated ceiling treatment	
B-1	Existing ceiling finish retained	24-04-2023
B-2	Hatch rotation revised	
C-1	Suspended ceiling area reduced	04-07-2023
C-2	Connection revised	

project and code

Fraser House
36 Charlotte Street,
Manchester M1 4FD
2022-1008M

drawing title

Proposed GA Second Floor
Ceiling Plan

PLANNING ISSUE

drawing number / revision

2022-1008M - 045 C

scale

1:50 @ A1

04.07.2023

drawn / checked

CT / KS

0 0.5 1 2
Metres