





GEOSHIELD Verification Report



OVERVIEW PHOTOGRAPHS



Overview photograph of the area verified during installation






GEOSHIELD Verification Report



OVERVIEW PHOTOGRAPHS



Overview photograph of the area verified during installation





GEOSHIELD


Verification Report



LIMITATIONS

SURVEY AREA: Upper Raft Slab Termination

RESTRICTIONS AND LIMITATIONS: During the site visit an issue was found with the termination of the Upper Raft Slab and the Visqueen Standard Gas Barrier applied vertically from the basement slab. The drawing below shows the original design detail. However during the pour the tail which was due to be terminated to has been covered





GEOSHIELD Verification Report



LIMITATIONS

SURVEY AREA: Upper Raft Termination

RESTRICTIONS AND LIMITATIONS: Below is the correspondence from

Laing O'Rourke to Visqueen regarding the proposed remediation strategy given above.

From: Cameron Vauvelle-Don
To: [Laing O'Rourke](#)
Cc: [Stephenson, Robert](#); [Scott, Michael T](#); [Thomas, Oliver](#); [Abraham Moss Library](#); and [Leisure Centre](#)
Subject: RE: Abraham Moss - Proposed Gas Termination detail
Date: 17 February 2022 14:12:40
Attachments: [mossdetail.dwg](#)

CAUTION - This email was sent from outside Laing O'Rourke

Phil,
Many thanks for the email.
I have just looked at your proposal and Visqueen is happy that the solution will give us the best possible method of sealing from the Gas Barrier to the retaining wall and then onto the underside of the upper slab.
It is a workable solution.
If you need anything else then please let me know.
Kind regards,
Cameron
Cameron Vauvelle-Don (CS9W)
Technical Support Manager
Phone: +44 (0) 333 202 6800
Mobile: +44 (0) 7471 49288
Email: cvaudeveldon@visqueen.com

VISQUEEN
Part of RSC Ltd group

We're rolling out something big
Available to order now

VISQUEEN To discover the Visqueen difference visit www.visqueen.com or call us on +44 (0) 333 202 6800

VISQUEEN ZEDEX
NON-COMBUSTIBLE DPC
Visqueen Zedex Non-Combustible Damp Proof Course
A2 - s1, d0 to BS EN 13501-1:2018

Visqueen, Hoarwood Gate,
Road, Heston, Derbyshire,
DE75 7RG United Kingdom
Website: www.visqueen.com

From: Davies, Philip <P.Davies@laingorourke.com>
Sent: 17 February 2022 13:54
To: Cameron Vauvelle-Don <CameronVauvelle-Don@berrysglobal.com>
Cc: Stephenson, Robert <RStephenson@laingorourke.com>; Scott, Michael T <MTScott@laingorourke.com>; Thomas, Oliver <OThomas@laingorourke.com>; Abraham Moss Library, and Leisure Centre <AbrahamMoss@laingorourke.com>
Subject: Abraham Moss - Proposed Gas Termination detail
Importance: High

External Email: Please do not click links or open attachments unless you trust the sender and know the content is safe. If in doubt, contact the IT help Desk.

Hi Cameron,
I hope you are well and out of isolation now. We have come across a bit of an issue which we need your assistance with at Abraham Moss. As outlined within the attached sketches we have a section of our basement wall to ground floor slab interface where some of the gas barrier has been lost.
We are proposing to remediate this by lapping the ground floor slab gas barrier onto the top of the basement wall using GR 5mm or the 500mm detailing strip with HP tanking primer. Is this something you would be able to advise on/ provide an updated sketch for to confirm acceptance?
I will give you a call to discuss this further. This is quite an urgent matter on site so if you could respond as soon as possible it would be greatly appreciated.
Thanks,
Phil Davies
Senior Engineer
Laing O'Rourke
Abraham Moss Leisure Centre
Crescent Road
Charnock
Manchester
M8 5LF
www.laingorourke.com
mobile: +44 (0) 7471 49288

This message (including attachments) is intended only for the use of the individual or entity to which it is addressed and contains information that is confidential, legally privileged and/or proprietary to Laing O'Rourke. If you have received this message in error, please notify the sender immediately by replying to the message to indicate the error and delete the message (and destroy any copies) without further disclosure or use. Messages sent to/from Laing O'Rourke may be monitored and Laing O'Rourke accepts no liability for personal content of the sender which is unrelated to Laing O'Rourke's business. References to "Laing O'Rourke" include Laing O'Rourke Corporation Ltd and its affiliates - visit www.laingorourke.com for more information.

Disclaimer
This E-mail (including attachments) is confidential and the property of Berry Global, Inc. and its subsidiaries (collectively, "Berry"). If you are not the intended recipient, reading, copying, disclosure or any action or forbearance based on the E-mail is prohibited. Berry retains all copyright and other intellectual property rights and objects to misuse. IF YOU HAVE RECEIVED THIS E-MAIL IN ERROR, IMMEDIATELY CONTACT THE SENDER TO SO ADVISE OF THE ERROR AND PERMANENTLY DELETE THIS E-MAIL.