


RISK ASSESSMENT

Risk Assessment Reference: 029 WEATHER CONDITIONS					Assessor: Andy Palmer		Area/Location: Site Work		
Persons Exposed:		No of Employees: 10+		No of Contractors: 0		No of Public/Visitors: 0		Total No exposed: 10+	
Hazard	Risk	Risk Rating			Control Measures to Reduce Risk	Residual Risk			
		Probability	Severity	Risk		Probability	Severity	Risk	
Wet and windy weather conditions.	Slips, trips, falls.	3	3	9	Weather forecast checked prior to works starting. Safety footwear with good grips worn. Waterproof jackets available and worn. Postpone any lifting operations in high winds.	1	3	3	
Cold weather conditions.	Loss of dexterity to fingers. Lack of concentration.	3	2	6	Warm clothing to be worn by operatives. Regular breaks taken in warm area.	1	2	2	
Hot and sunny weather conditions.	Heat exhaustion. Dehydration. Sun burn.	3	3	9	Operatives to wear long sleeve tops and long trousers to form a barrier to the sun's harmful rays. Stay in the shade wherever possible, during breaks and especially at lunch time. Use a high factor sunscreen of at least SPF15 on any exposed skin. Apply as directed on the product. Drink plenty of water to avoid dehydration. Your body will lose approximately 2.5 litres of fluid per day, and you should try to take in more fluid than you are losing. Check your skin regularly for any unusual moles or spots. See a doctor promptly if you find anything that is changing in shape, size or colour, itching or bleeding.	1	3	3	
Signed by: 					Date carried out: 31-01-2022				
Additional control measures to reduce risks to lowest level possible					Action Plan		Completed		
					By	Date	By	Date	