

LOCATION 2.



NEW ACCESS
HATCH LOCATION.

NEW TIMBER
RAFTER.

CURRENT ACCESS ONTO
VALLEY. NOT FIT FOR
PURPOSE AND TOO LOW
SO ENCLOSING ON
WILLEY DETAIL.