



Lifts - Briefing Note

Project Manchester Art Gallery

Purpose Briefing document

1.1.0 4 – ATRIUM SCENIC LIFT

1.1.1 Current Issue:

1.1.2 The Atrium glass scenic lifts are difficult to maintain, and the hydraulic plant continuously overheats.

1.1.3 Proposal:

1.1.4 The small works team at MCC have ordered replacement parts for the whole lift mechanisms to allow for a major refurbishment of the existing lift.

1.1.5 Alternative:

1.1.6 To ensure that the lifts work for the future, an alternative solution, where the lifts are replaced with new lift cars and a new mechanism is being developed with Sheridan lifts.

1.2.0 13 – GOODS LIFT | EMERGENCY PHONE

1.2.1 Current Issue:

The Goods lift currently dials to the security lodge. Where the call to a maintenance engineer is dialled manually. This is dealt with by a specialist good lift company.

1.2.2 Proposal:

The Lift call will be reprogrammed to call Arona as the service engineer for the rest of the building.

1.3.0 19 - KITCHEN LIFT | EMERGENCY PHONE

1.3.1 Current Issue:

The Kitchen lift emergency Call dials out, but does not connect to Arona Lift maintenance.

1.3.2 Proposal:

The lift emergency call button is reprogrammed to call Arona.