

Photo 1




Photo 5

Photo 2



Solid timber planks shown fixed to existing floor boards.




Existing original timber staircase.



Photo 6

Photo 3



Solid timber planks fixed to existing floor boards. Assumed for strengthening floor below heavy machinery.

Further solid timber planks shown fixed to existing floor boards.



Photo 7

Photo 3



Existing original floorboards shown.
No significant damp or decay was detected in the floor structure.



revision: date: note:
P01 20221223 preliminary first issue
P02 20230210 general planning update

	Existing non-original concrete slab dishes towards central low point and floor gulley
	Existing brick and stone steps down to lower ground floor level
	Existing non-original floorboards replaced following basement fire
	Existing original floorboards
	Existing original timber staircase

	Original timber panel boxing out to lower ground floor entrance head room
	Non-original chipboard panels fixed to existing floor along high traffic routes
	Non-original timber capping on top of original timber stair treads
	Non-original chipboard panels fixed to existing floor with contemporary carpet tiles
	Non-original chipboard panels fixed to existing floor with timber effect linoleum

	Solid timber planks fixed to existing floor boards. Assumed for strengthening floor below heavy machinery
--	---



project
51-53 richmond st, manchester
job no.
7593
title
Warehouse Existing Second Floor Finish Plan
scale
1:100 @ A3
drawing no.
al(05)0083

stephenson hamilton risley
STUDIO

3 riverside mews
4 commercial street
manchester, M15 4RQ
www.shr.studio
email@shr.studio
0161 832 0244