


On site investigation works to attempt to locate the believed route of Cheetham hill culvert

Following the receipt of the below information of the possible route of the Cheetham Hill Culvert across the development site investigation works were undertaken to locate and plot the position.


As can be seen on the enclosed drawing and photographs an existing drainage system was identified across the site which eventually connected to the UU combined drainage system in Hargreaves Street.

Historical Information

The below drawing was initially provided in an aid to the location of the Culvert. Surveys of existing drainage system to locate any connections to the culvert were undertaken without success.



Identified drainage system across development area



Photographs of investigation works undertaken


A. Headwall uncovered




B. Clay pipe work of culverted section of drain



C. Area where water emerges from existing ground



D. Identified areas of culvert/drain construction



E. Manhole chamber



F. Manhole Chamber





Located alignment of Culvert

Following investigations and research on previous works undertaken in the wider area it has been discovered that the Cheetham hill culvert does not enter the Victoria North site area.

It was identified that the culvert now runs through the Packaging products site and outfalls into the river irk as shown below upstream of the Victoria North site area.





Head wall (original photos taken)



Outfall present day overgrown



Photos taken 2022 Showing route of culvert to river outfall



Google Earth screen shots showing location of Cheetham hill Culvert entering River Irk

