

Great Northern Warehouse, Manchester.

Window Condition Survey

Elevation Ref

Deansgate Mews

WINDOW NUMBER	FLOOR NUMBER	DESIGN TYPE	MATERIAL TYPE	Condition				Nr missing items	DESCRIPTION OF MISSING/FAULTY ITEMS	Glass		COMMENTS
				Good	Fair	Poor	Replace			GLAZING SEALS	Panes of glass to replace	
1	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
2	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
3	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
4	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
5	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
6	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
7	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
8	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
9	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
10	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
11	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
12	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
13	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
14	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
15	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
16	3	Sash	Timber		X			2	Lifters	Beads	0	Redecoration/New Mastic Seals
17	3	Sash	Timber		X			1	Lifters	Beads	0	Redecoration/New Mastic Seals
18	3	Sash	Timber		X			1	Lifters	Beads	0	Redecoration/New Mastic Seals
19	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
20	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
21	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
22	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
23	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
24	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
25	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
26	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
27	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
28	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
29	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
30	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
31	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
32	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
33	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
34	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals

TOTALS

4

TOTALS

0

Great Northern Warehouse, Manchester.

Window Condition Survey

Elevation Ref

East Elevation

WINDOW NUMBER	FLOOR NUMBER	DESIGN TYPE	MATERIAL TYPE	Condition				Nr missing items	DESCRIPTION OF MISSING/FAULTY ITEMS	Glass		COMMENTS
				Good	Fair	Poor	Replace			GLAZING SEALS	Panes of glass to replace	
1	1	Iron Frame	Metal			X				Putty	9	Missing Glass
2	1		Brick				X		Bricked Up	0	0	
3	1	Iron Frame	Metal			X				Putty	20	No Glass
4	1	Iron Frame	Metal			X				Putty	20	No Glass
5	1	Iron Frame	Metal			X				Putty	20	No Glass
6	1	Iron Frame	Metal			X				Putty	20	No Glass
7	1	Iron Frame	Metal			X				Putty	20	No Glass
8	1	Iron Frame	Metal			X				Putty	20	No Glass
9	1	Iron Frame	Metal			X				Putty	20	No Glass
10	1	Iron Frame	Metal			X				Putty	20	No Glass
11	1	Iron Frame	Metal			X				Putty	0	Full Glass
12	1	Iron Frame	Metal			X				Putty	0	Full Glass
13	1	Iron Frame	Metal			X				Putty	0	Full Glass
14	1	Iron Frame	Metal			X				Putty	0	Full Glass
15	1	Iron Frame	Metal			X				Putty	0	Full Glass
16	1	Iron Frame	Metal			X				Putty	20	No Glass
17	1	Iron Frame	Metal			X				Putty	20	No Glass
18	1	Iron Frame	Metal			X				Putty	20	No Glass
19	1	Iron Frame	Metal			X				Putty	20	No Glass
20	1	Iron Frame	Metal			X				Putty	20	No Glass
21	1	Iron Frame	Metal			X				Putty	0	Full Glass
22	1	Iron Frame	Metal			X				Putty	0	Full Glass
23	1	Iron Frame	Metal			X				Putty	20	No Glass
24	1	Iron Frame	Metal			X				Putty	20	No Glass
25	1	Iron Frame	Metal			X				Putty	20	No Glass
26	1		Brick				X		Bricked Up	0	0	
27	1	Iron Frame	Metal			X				Putty	8	Missing Glass
28	2	Iron Frame	Metal			X				Putty	5	Missing Glass
29	2		Brick				X		Bricked Up	0	0	
30	2	Iron Frame	Metal			X				Putty	20	No Glass
31	2	Iron Frame	Metal			X				Putty	20	No Glass
32	2	Iron Frame	Metal			X				Putty	20	No Glass
33	2	Iron Frame	Metal			X				Putty	20	No Glass

34	2	Iron Frame	Metal			X				Putty	20	No Glass
35	2	Iron Frame	Metal			X				Putty	20	No Glass
36	2	Iron Frame	Metal			X				Putty	20	No Glass
37	2	Iron Frame	Metal			X				Putty	20	No Glass
38	2	Iron Frame	Metal			X				Putty	20	No Glass
39	2	Iron Frame	Metal			X				Putty	20	No Glass
40	2	Iron Frame	Metal			X				Putty	20	No Glass
41	2	Iron Frame	Metal			X				Putty	20	No Glass
42	2	Iron Frame	Metal			X				Putty	20	No Glass/ Small Rusting
43	2	Iron Frame	Metal			X				Putty	20	No Glass/ Small Rusting
44	2	Iron Frame	Metal			X				Putty	20	No Glass/ Small Rusting
45	2	Iron Frame	Metal			X				Putty	20	No Glass
46	2	Iron Frame	Metal			X				Putty	20	No Glass/ Small Rusting
47	2	Iron Frame	Metal			X				Putty	20	No Glass
48	2	Bricked up					X			0	20	Bricked up
49	2	Iron Frame	Metal			X				Putty	4	4 Panes Missing
50	2	Iron Frame	Metal			X				Putty	1	1 Pane Broken
51	2	Iron Frame	Metal			X				Putty	20	No Glass/Small Rusting
52	2	Iron Frame	Metal			X				Putty	20	No Glass/Small Rusting
53	2	Iron Frame	Metal			X				Putty	20	No Glass/Small Rusting
54	3	Iron Frame	Metal			X				Putty	3	Missing Glass
55	3	Iron Frame	Metal			X				Putty	0	No Glass/ Small Rusting
56	3	Brick					X		Bricked Up	0	0	
57	3	Iron Frame	Metal			X				Putty	20	No Glass/ Small Rusting
58	3	Iron Frame	Metal			X				Putty	20	No Glass/ Small Rusting
59	3	Iron Frame	Metal			X				Putty	20	No Glass/ Small Rusting
60	3	Iron Frame	Metal			X			Glazing Bar Missing	Putty	20	No Glass/ Small Rusting
61	3	Iron Frame	Metal			X				Putty	20	No Glass/ Small Rusting
62	3	Iron Frame	Metal			X				Putty	20	No Glass/ Small Rusting
63	3	Iron Frame	Metal			X				Putty	20	No Glass/ Small Rusting
64	3	Iron Frame	Metal			X				Putty	20	No Glass/ Small Rusting
65	3	Iron Frame	Metal			X				Putty	20	No Glass/ Small Rusting
66	3	Iron Frame	Metal			X				Putty	20	No Glass/ Small Rusting
67	3	Iron Frame	Metal			X				Putty	20	No Glass/ Small Rusting
68	3	Iron Frame	Metal			X				Putty	20	No Glass/ Small Rusting
69	3	Iron Frame	Metal			X				Putty	20	No Glass/ Small Rusting
70	3	Iron Frame	Metal			X				Putty	20	No Glass/ Small Rusting
71	3	Iron Frame	Metal			X				Putty	20	No Glass/ Small Rusting
72	3	Iron Frame	Metal			X				Putty	20	No Glass/ Small Rusting

73	3	Iron Frame	Metal			X			Putty	20	No Glass/ Small Rusting
74	3	Iron Frame	Metal			X			Putty	20	No Glass/ Small Rusting
75	3	Iron Frame	Metal			X			Putty	20	No Glass/ Small Rusting
76	3	Iron Frame	Metal			X			Putty	20	No Glass/ Small Rusting
77	3	Iron Frame	Metal			X			Putty	20	No Glass/ Small Rusting
78	3	Iron Frame	Metal			X			Putty	20	No Glass/ Small Rusting
79	3	Iron Frame	Metal			X			Putty	20	No Glass/ Small Rusting
80	3	Bricked Up	Bricked Up			X			0	0	Bricked up
81	3	Iron Frame	Metal			X			Putty	4	Missing Glass
82	4	Iron Frame	Metal			X			Putty	20	No Glass/ Hole in bird netting/ Rusting
83	4	Iron Frame	Metal				X	Bricked Up	0	0	
84	4	Iron Frame	Metal			X			Putty	20	No Glass/ Hole in bird netting/ Rusting
85	4	Iron Frame	Metal			X			Putty	20	No Glass/Rusting
86	4	Iron Frame	Metal			X			Putty	20	No Glass/Rusting
87	4	Iron Frame	Metal			X			Putty	20	No Glass/ Hole In Bird Netting/ Rusting
88	4	Iron Frame	Metal			X			Putty	20	No Glass/ Bird Netting Totally Off/ Rusting
89	4	Iron Frame	Metal			X			Putty	20	No Glass
90	4	Iron Frame	Metal			X			Putty	20	No Glass/ Hole In Bird Netting/ Rusting
91	4	Iron Frame	Metal			X			Putty	20	No Glass/Rusting
92	4	Iron Frame	Metal			X			Putty	20	No Glass/ Small Hole In Bird Netting
93	4	Iron Frame	Metal			X			Putty	20	No Glass
94	4	Iron Frame	Metal			X			Putty	20	No Glass/ Small Hole In Bird Netting
95	4	Iron Frame	Metal			X			Putty	20	No Glass/ Small Hole In Bird Netting
96	4	Iron Frame	Metal			X			Putty	20	No Glass
97	4	Iron Frame	Metal			X			Putty	20	No Glass/Small Rusting
98	4	Iron Frame	Metal			X			Putty	20	No Glass
99	4	Iron Frame	Metal			X			Putty	20	No Glass/Small Rusting
100	4	Iron Frame	Metal			X			Putty	20	No Glass/Small Rusting
101	4	Iron Frame	Metal			X			Putty	20	No Glass/Small Rusting
102	4	Iron Frame	Metal			X			Putty	20	No Glass/Small Rusting
103	4	Iron Frame	Metal			X			Putty	20	No Glass/Small Rusting
104	4	Iron Frame	Metal			X			Putty	20	No Glass/Small Rusting
105	4	Iron Frame	Metal			X			Putty	20	No Glass/ Damaged Frame
106	4	Iron Frame	Metal			X			Putty	4	Missing Glass/ Rusting
107	4	Iron Frame	Metal			X			Putty	0	Full Glass
108	4	Iron Frame	Metal			X			Putty	20	No Glass

TOTALS

TOTALS

Great Northern Warehouse, Manchester.

Window Condition Survey

Elevation Ref

North Elevation

WINDOW NUMBER	FLOOR NUMBER	DESIGN TYPE	MATERIAL TYPE	Condition				Nr missing items	DESCRIPTION OF MISSING/FAULTY ITEMS	Glass		COMMENTS
				Good	Fair	Poor	Replace			GLAZING SEALS	Panes of Glass to replace	
109	1	Iron Frame	Metal		X					Putty	0	
110	1	Iron Frame	Metal			X				Putty	30	No Glass
111	1	Iron Frame	Metal		X					Putty	30	No Glass
112	1	Iron Frame	Metal		X					Putty	0	
113	1	Iron Frame	Metal		X					Putty	0	
114	1	Iron Frame	Metal		X					Putty	0	
115	1	Iron Frame	Metal		X					Putty	0	
116	1	Iron Frame	Metal		X					Putty	0	
117	1	Iron Frame	Metal		X					Putty	0	
118	1	Iron Frame	Metal		X					Putty	0	
119	1	Iron Frame	Metal		X					Putty	0	
120	1	Iron Frame	Metal		X					Putty	0	
121	1	Iron Frame	Metal			X				Putty	30	No Glass
122	1	Iron Frame	Metal			X				Putty	30	No Glass
123	1	Iron Frame	Metal			X				Putty	30	No Glass
124	1	Iron Frame	Metal			X				Putty	30	No Glass
125	1	Iron Frame	Metal			X				Putty	30	Missing Glass
126	2	Iron Frame	Metal			X				Putty	4	Missing Glass
127	2	Iron Frame	Metal			X				Putty	20	No Glass
128	2	Iron Frame	Metal			X				Putty	20	No Glass
129	2	Iron Frame	Metal			X				Putty	20	No Glass
130	2	Iron Frame	Metal			X				Putty	20	No Glass/Small Rust
131	2	Iron Frame	Metal			X				Putty	20	No Glass
132	2	Iron Frame	Metal			X				Putty	20	No Glass/Small Rust
133	2	Iron Frame	Metal			X				Putty	20	No Glass
134	2	Iron Frame	Metal			X				Putty	20	No Glass
135	2	Iron Frame	Metal			X				Putty	20	No Glass
136	2	Iron Frame	Metal			X				Putty	20	No Glass
137	2	Iron Frame	Metal			X				Putty	20	Boarded Up
138	2	Iron Frame	Metal			X				Putty	20	Boarded Up
139	2	Iron Frame	Metal			X				Putty	20	Boarded Up
140	2	Iron Frame	Metal			X				Putty	20	Boarded Up

141	2	Iron Frame	Metal		X			Putty	20	Boarded Up
142	2	Iron Frame	Metal		X			Putty	20	No Glass
143	3	Iron Frame	Metal		X			Putty	4	Missing Glass
144	3	Iron Frame	Metal		X			Putty	20	No Glass/Small Rust
145	3	Iron Frame	Metal	X				Putty	20	
146	3	Iron Frame	Metal		X			Putty	20	No Glass/Small Rust
147	3	Iron Frame	Metal	X				Putty	20	
148	3	Iron Frame	Metal	X				Putty	20	
149	3	Iron Frame	Metal		X			Putty	20	No Glass/Small Rust
150	3	Iron Frame	Metal	X				Putty	20	
151	3	Iron Frame	Metal		X			Putty	20	No Glass/Small Rust
152	3	Iron Frame	Metal		X			Putty	20	No Glass/Small Rust
153	3	Iron Frame	Metal	X				Putty	20	
154	3	Iron Frame	Metal	X				Putty	20	
155	3	Iron Frame	Metal		X			Putty	20	No Glass/Small Rust
156	3	Iron Frame	Metal		X			Putty	20	No Glass/Small Rust
157	3	Iron Frame	Metal		X			Putty	20	No Glass/Small Rust
158	3	Iron Frame	Metal		X			Putty	20	No Glass/Small Rust
159	3	Iron Frame	Metal		X			Putty	4	Missing Glass/Opening Casement
160	4	Iron Frame	Metal		X			Putty	20	No Glass
161	4	Iron Frame	Metal		X			Putty	20	No GlassSmall Rusting
162	4	Iron Frame	Metal		X			Putty	20	No GlassSmall Rusting
163	4	Iron Frame	Metal		X			Putty	20	No Glass, Hole In Bird Netting
164	4	Iron Frame	Metal		X			Putty	20	No Glass
165	4	Iron Frame	Metal		X			Putty	20	No Glass, hole in bird netting, Small Rusting
166	4	Iron Frame	Metal		X			Putty	20	No Glass
167	4	Iron Frame	Metal		X			Putty	20	No Glass
168	4	Iron Frame	Metal		X			Putty	20	No Glass, Hole In Bird Netting
169	4	Iron Frame	Metal		X			Putty	20	No Glass/ Small Rusting
170	4	Iron Frame	Metal		X			Putty	20	No Glass/Small Rusting
171	4	Iron Frame	Metal		X			Putty	20	No Glass/Small Rusting
172	4	Iron Frame	Metal		X			Putty	20	No Glass/ Hole In Bird Netting/ Rusting
173	4	Iron Frame	Metal		X			Putty	20	No Glass/Small Rusting
174	4	Iron Frame	Metal		X			Putty	20	No Glass/ Hole In Bird Netting/ Rusting
175	4	Iron Frame	Metal	X				Putty	0	
176	4	Iron Frame	Metal		X			Putty	6	Missing Glass

TOTALS

TOTALS

Great Northern Warehouse, Manchester.

Window Condition Survey

Elevation Ref

West Elevation

WINDOW NUMBER	FLOOR NUMBER	DESIGN TYPE	MATERIAL TYPE	Condition				Nr missing items	DESCRIPTION OF MISSING/FAULTY ITEMS	Glass		COMMENTS
				Good	Fair	Poor	Replace			GLAZING SEALS	Panes of glass to replace	
177	1	Iron Frame	Metal				X			Putty	7	Missing Glass
178	1		Brick				X		Bricked Up	Putty	0	
179	1	Iron Frame	Metal			X				Putty	0	
180	1	Iron Frame	Metal			X				Putty	0	
181	1		Brick				X		Bricked Up	0	0	
182	1		Brick				X		Bricked Up	0	0	
183	1		Brick				X		Bricked Up	0	0	
184	1		Brick				X		Bricked Up	0	0	
185	1		Brick				X		Bricked Up	0	0	
186	1		Brick				X		Bricked Up	0	0	
187	1		Brick				X		Bricked Up	0	0	
188	1		Brick				X		Bricked Up	0	0	
189	1		Brick				X		Bricked Up	0	0	
190	1		Brick				X		Bricked Up	0	0	
191	1		Brick				X		Bricked Up	0	0	
192	1		Brick				X		Bricked Up	0	0	
193	1		Brick				X		Bricked Up	0	0	
194	1		Brick				X		Bricked Up	0	0	
195	1		Brick				X		Bricked Up	0	0	
196	1		Brick				X		Bricked Up	0	0	
197	1	Iron Frame	Metal			X				Putty	6	Missing Glass
198	2	Iron Frame	Metal			X				Putty	0	
199	2		Brick				X		Bricked Up	Putty	0	
200	2	Iron Frame	Metal			X				Putty	0	
201	2	Iron Frame	Metal			X				Putty	0	Small Rusting
202	2	Iron Frame	Metal			X				Putty	0	Small Rusting
203	2	Iron Frame	Metal			X			No Middle Casement	Putty	0	Rusting
204	2	Iron Frame	Metal			X				Putty	1	Cracked Bottom Panel x1
205	2	Iron Frame	Metal			X				Putty	0	
206	2	Iron Frame	Metal			X				Putty	0	
207	2	Bricked Up	Brick				X			Putty	0	
208	2	Iron Frame	Metal			X				Putty	0	
209	2	Iron Frame	Metal			X				Putty	20	Rusting
210	2	Iron Frame	Metal				X		Bricked Up	Putty	0	
211	2	Iron Frame	Metal				X		Bricked Up	Putty	0	
212	2	Iron Frame	Metal			X				Putty	0	
213	2	Iron Frame	Metal			X				Putty	0	
214	2		Brick				X		Bricked Up	Putty	0	
215	2		Brick				X		Bricked Up	Putty	0	

216	2	Iron Frame	Metal			X			Putty	4	Missing Glass
217	3	Iron Frame	Metal			X			Putty	4	Missing Glass
218	3		Brick				X	Bricked Up	Putty	0	
219	3	Iron Frame	Metal			X			Putty	0	
220	3	Iron Frame	Metal			X			Putty	0	Glass Has Been Previously Replaced And Not Sealed
221	3	Iron Frame	Metal			X			Putty	0	Glass Has Been Previously Replaced And Not Sealed
222	3	Iron Frame	Metal			X			Putty	0	Glass Has Been Previously Replaced And Not Sealed
223	3	Iron Frame	Metal			X			Putty	0	Glass Has Been Previously Replaced And Not Sealed
224	3	Iron Frame	Metal			X			Putty	0	Glass Has Been Previously Replaced And Not Sealed
225	3	Iron Frame	Metal			X			Putty	4	Missing Glass
226	3		Brick				X	Bricked Up	Putty		
227	3	Iron Frame	Metal			X			Putty	0	
228	3	Iron Frame	Metal			X			Putty	20	No Glass
229	3	Iron Frame	Metal				X		Putty	0	
230	3	Iron Frame	Metal				X	Bricked Up	Putty	0	
231	3	Iron Frame	Metal			X			Putty	0	
232	3	Iron Frame	Metal			X			Putty	0	
233	3		Brick				X	Bricked Up	Putty	0	
234	3		Brick				X	Bricked Up	Putty	0	
235	3	Iron Frame	Metal		X				Putty	0	
236	4	Iron Frame	Metal			X			Putty	4	Missing Glass
237	4		Brick				X	Bricked up	Putty	0	
238	4	Iron Frame	Metal			X			Putty	15	Missing Glass
239	4	Iron Frame	Metal			X			Putty	20	No Glass
240	4	Iron Frame	Metal			X			Putty	4	Missing Glass
241	4	Iron Frame	Metal			X			Putty	4	Missing Glass
242	4	Iron Frame	Metal			X			Putty	4	Missing Glass
243	4	Iron Frame	Metal			X			Putty	0	
244	4	Iron Frame	Metal			X			Putty	4	Missing Glass
245	4		Brick				X	Bricked Up	0	0	
246	4	Iron Frame	Metal			X			Putty	20	No Glass
247	4	Iron Frame	Metal			X			Putty	20	No Glass
248	4		Brick				X	Bricked up	0	0	
249	4	Iron Frame	Metal			X			Putty	20	No Glass/ Hole In Bird Netting/ Rusting
250	4	Iron Frame	Metal			X			Putty	20	No Glass/ Hole In Bird Netting/ Rusting
251	4		Brick				X	Bricked Up	0	0	
252	4	Iron Frame	Metal			X			Putty	20	No Glass
253	4	Iron Frame	Metal				X		Putty	20	No Glass
254	4	Iron Frame	Metal			X			Putty	20	No Glass
255	4	Iron Frame	Metal			X			Putty	20	No Glass
256	4		Brick				X	Bricked Up	0	0	
257	4		Brick				X	Bricked Up	0	0	
258	4	Iron Frame	Metal			X			Putty	4	Missing Glass

TOTALS

TOTALS

Great Northern Warehouse, Manchester.

Window Condition Survey

Elevation Ref

South Elevation

WINDOW NUMBER	FLOOR NUMBER	DESIGN TYPE	MATERIAL TYPE	Condition				Nr missing items	DESCRIPTION OF MISSING/FAULTY ITEMS	Glass		COMMENTS
				Good	Fair	Poor	Replace			GLAZING SEALS	Panes of glass to replace	
258	1	Iron Frame	Metal			X				Putty	0	
259	1	Iron Frame	Metal			X				Putty	0	
260	1	Iron Frame	Metal			X				Putty	30	Missing Glass
261	1	Iron Frame	Metal			X				Putty	30	Missing Glass
262	1	Iron Frame	Metal			X			1 Glazing Bar	Putty	30	Missing Glass
263	2	Iron Frame	Metal			X				Putty	20	Missing Glass
264	2	Iron Frame	Metal			X				Putty	0	
265	2	Iron Frame	Metal			X				Putty	20	No Glass
266	2	Iron Frame	Metal			X				Putty	8	Missing Glass
267	3	Iron Frame	Metal			X				Putty	4	Missing Glass
268	3	Iron Frame	Metal			X				Putty	0	
269	3	Iron Frame	Metal			X				Putty	0	
270	3	Iron Frame	Metal			X				Putty	4	Missing Glass
271	4	Iron Frame	Metal			X				Putty	4	Missing Glass
272	4	Iron Frame	Metal			X				Putty	20	No Glass
273	4	Iron Frame	Metal			X				Putty	20	No Glass
274	4	Iron Frame	Metal			X				Putty	20	No Glass
275	4	Iron Frame	Metal						Unreachable	Putty	0	
276	4	Iron Frame	Metal						Unreachable	Putty	0	
277	4	Iron Frame	Metal						Unreachable	Putty	0	
278	4	Iron Frame	Metal						Unreachable	Putty	0	
279	4	Iron Frame	Metal						Unreachable	Putty	0	
280	4	Iron Frame	Metal						Unreachable	Putty	0	
281	4	Iron Frame	Metal			X				Putty	20	No Glass, Rusting
282	4	Iron Frame	Metal			X				Putty	20	No Glass, Rusting
283	4	Iron Frame	Metal			X				Putty	20	No Glass, Small Holes In Bird Netting, Rusting
284	4	Iron Frame	Metal			X				Putty	20	No Glass, Rusting
285	4	Iron Frame	Metal			X				Putty	20	No Glass, Rusting
286	4	Iron Frame	Metal			X				Putty	20	No Glass, Frame Broken In Several Places
287	4	Iron Frame	Metal			X				Putty	4	Missing Glass

TOTALS

TOTALS

Great Northern Warehouse, Manchester.

Window Condition Survey

Elevation Ref

Deansgate Elevation

WINDOW NUMBER	FLOOR NUMBER	DESIGN TYPE	MATERIAL TYPE	Condition				Ironmongery		Glass		COMMENTS
				Good	Fair	Poor	Replace	Nr missing items	DESCRIPTION OF MISSING/FAULTY ITEMS	GLAZING SEALS	Panes of glass to replace	
1	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals/Top Sash Dropped
2	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
3	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
4	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
5	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
6	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
7	1	Sash	Timber		X			2	Finger Pulls	Beads	0	Redecoration/New Mastic Seals
8	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
9	1	Sash	Timber		X			2	Finger Pulls	Beads	0	Redecoration/New Mastic Seals/Window Catches
10	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals/Window Catches
11	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals/Window Catches
12	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
13	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
14	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
15	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
16	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
17	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
18	1	Sash	Timber		X			1	Cord/ Pulley	Beads	0	Redecoration/New Mastic Seals
19	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
20	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
21	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
22	1	Sash	Timber		X			2	Latch	Beads	0	Redecoration/New Mastic Seals
23	1	Sash	Timber		X			2	Latch	Beads	0	Redecoration/New Mastic Seals
24	1	Sash	Timber		X			2	Latch	Beads	0	Redecoration/New Mastic Seals

TOTALS

11

TOTALS

0

Great Northern Warehouse, Manchester.

Window Condition Survey

Elevation Ref

Deansgate Elevation

WINDOW NUMBER	FLOOR NUMBER	DESIGN TYPE	MATERIAL TYPE	Condition				Ironmongery		Glass		COMMENTS
				Good	Fair	Poor	Replace	Nr missing items	DESCRIPTION OF MISSING/FAULTY ITEMS	GLAZING SEALS	Panes of glass to replace	
25	1	Sash	Timber	X				2	Latch	Beads	0	Redecoration/New Mastic Seals
26	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
27	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
28	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
29	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
30	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
31	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
32	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
33	1	Sash	Timber	X				1	Finger Pull	Beads	0	Redecoration/New Mastic Seals
34	1	Sash	Timber	X				1	Pully Snapped	Beads	0	Redecoration/New Mastic Seals/Non Operational
35	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
36	1	Sash	Timber	X				1	Latch	Beads	0	Redecoration/New Mastic Seals
37	1	Sash	Timber	X				2	Latch	Beads	0	Redecoration/New Mastic Seals
38	1	Sash	Timber	X				2	Latch	Beads	0	Redecoration/New Mastic Seals
39	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
40	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals/Screwed Shut
41	1	Sash	Timber	X				1	Finger Pull	Beads	0	Redecoration/New Mastic Seals/Screwed Shut
42	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals/Screwed Shut
43	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals/Screwed Shut
44	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
45	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
46	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
47	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
48	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals

TOTALS

10

TOTALS

0

Great Northern Warehouse, Manchester.

Window Condition Survey

Elevation Ref

Deansgate Elevation

WINDOW NUMBER	FLOOR NUMBER	DESIGN TYPE	MATERIAL TYPE	Condition				Ironmongery		Glass		COMMENTS
				Good	Fair	Poor	Replace	Nr missing items	DESCRIPTION OF MISSING/FAULTY ITEMS	GLAZING SEALS	Panes of glass to replace	
49	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
50	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
51	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
52	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
53	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
54	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
55	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals/ Top Sash Dropped
56	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals/ Top Sash Dropped
57	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
58	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals/Top Sash Dropped
59	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
60	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
61	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
62	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
63	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
64	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
65	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
66	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
67	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
68	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
69	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
70	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
71	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
72	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals

TOTALS

0

TOTALS

0

Great Northern Warehouse, Manchester.

Window Condition Survey

Elevation Ref

Deansgate Elevation

WINDOW NUMBER	FLOOR NUMBER	DESIGN TYPE	MATERIAL TYPE	Condition				Nr missing items	DESCRIPTION OF MISSING/FAULTY ITEMS	Glass		COMMENTS
				Good	Fair	Poor	Replace			GLAZING SEALS	Panes of glass to replace	
73	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
74	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
75	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
76	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
77	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
78	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
79	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
80	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
81	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
82	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals/Bottom Sash Dropped
83	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals/Bottom Sash Dropped
84	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals/Bottom Sash Dropped
85	1	Sash	Timber	X				2	Finger Pulls	Beads	0	Redecoration/New Mastic Seals/Bottom Sash Dropped
86	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals/Top Sash Dropped
87	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals/Top Sash Dropped
88	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals/Top Sash Dropped
89	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals/Top Sash Dropped
90	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
91	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals/Top Sash Dropped
92	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
93	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
94	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
95	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
96	1	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals

TOTALS

2

TOTALS

0

Great Northern Warehouse, Manchester.

Window Condition Survey

Elevation Ref

Deansgate Elevation

WINDOW NUMBER	FLOOR NUMBER	DESIGN TYPE	MATERIAL TYPE	Condition				Nr missing items	DESCRIPTION OF MISSING/FAULTY ITEMS	Glass		COMMENTS
				Good	Fair	Poor	Replace			GLAZING SEALS	Panes of glass to replace	
97	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
98	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
99	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
100	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
101	1	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals/Painted Shut
102	2	Sash	Timber		X			1	Catch	Beads	0	Redecoration/New Mastic Seals/Draught strip
103	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
104	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
105	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals/Top Sash Dropped
106	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
107	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
108	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
109	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
110	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
111	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
112	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
113	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
114	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
115	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
116	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
117	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
118	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals/Top Sash Dropped
119	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals/Window Jammed
120	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals

TOTALS

0

TOTALS

0

Great Northern Warehouse, Manchester.

Window Condition Survey

Elevation Ref

Deansgate Elevation

WINDOW NUMBER	FLOOR NUMBER	DESIGN TYPE	MATERIAL TYPE	Condition				Nr missing items	DESCRIPTION OF MISSING/FAULTY ITEMS	Glass		COMMENTS
				Good	Fair	Poor	Replace			GLAZING SEALS	Panes of glass to replace	
121	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals/Top Sash Dropped
122	2	Sash	Timber		X			1	Rubber Seal Perished	Beads	0	Redecoration/New Mastic Seals
123	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
124	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
125	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
126	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
127	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
128	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
129	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
130	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
131	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals/Stoppers Fitted/Sealed Open
132	2	Sash	Timber	X				1	Cord	Beads	0	Redecoration/New Mastic Seals/Sealed Open
133	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
134	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
135	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
136	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
137	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
138	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
139	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
140	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
141	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
142	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
143	2	Sash	Timber		X			2	Lifters	Beads	0	Redecoration/New Mastic Seals
144	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals

TOTALS

4

TOTALS

0

Great Northern Warehouse, Manchester.

Window Condition Survey

Elevation Ref

Deansgate Elevation

WINDOW NUMBER	FLOOR NUMBER	DESIGN TYPE	MATERIAL TYPE	Condition				Ironmongery		Glass		COMMENTS
				Good	Fair	Poor	Replace	Nr missing items	DESCRIPTION OF MISSING/FAULTY ITEMS	GLAZING SEALS	Panes of glass to replace	
145	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
146	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
147	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
148	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
149	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
150	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
151	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
152	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
153	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
154	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
155	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
156	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
157	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
158	2	Sash	Timber	X				1	Latch Broken	Beads	0	Redecoration/New Mastic Seals
159	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
160	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
161	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
162	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
163	2	Sash	Timber	X				0		Beads	0	Redecoration/New Mastic Seals
164	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
165	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
166	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
167	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
168	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals

TOTALS

1

TOTALS

0

Great Northern Warehouse, Manchester.

Window Condition Survey

Elevation Ref

Deansgate Elevation

WINDOW NUMBER	FLOOR NUMBER	DESIGN TYPE	MATERIAL TYPE	Condition				Ironmongery		Glass		COMMENTS
				Good	Fair	Poor	Replace	Nr missing items	DESCRIPTION OF MISSING/FAULTY ITEMS	GLAZING SEALS	Panes of glass to replace	
169	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
170	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
171	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
172	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
173	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
174	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
175	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
176	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
177	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
178	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
179	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
180	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
181	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
182	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
183	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
184	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
185	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
186	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
187	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
188	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
189	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
190	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
191	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
192	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals

TOTALS

0

TOTALS

0

Great Northern Warehouse, Manchester.

Window Condition Survey

Elevation Ref

Deansgate Elevation

WINDOW NUMBER	FLOOR NUMBER	DESIGN TYPE	MATERIAL TYPE	Condition				Nr missing items	DESCRIPTION OF MISSING/FAULTY ITEMS	Glass		COMMENTS
				Good	Fair	Poor	Replace			GLAZING SEALS	Panes of glass to replace	
193	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
194	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
195	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
196	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
197	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
198	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
199	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
200	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
201	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
202	2	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
203	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
204	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
205	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals/Decay to Cill
206	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
207	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
208	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals/Stoppers Fitted
209	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals/LHS Weight Trapped
210	3	Sash	Timber		X			1	Cord	Beads	0	Redecoration/New Mastic Seals
211	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
212	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
213	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals/Top Sash Dropped
214	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals/Top Sash Dropped
215	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals/Top Sash Dropped
216	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals/Top Sash Dropped

TOTALS

1

TOTALS

0

Great Northern Warehouse, Manchester.

Window Condition Survey

Elevation Ref

Deansgate Elevation

WINDOW NUMBER	FLOOR NUMBER	DESIGN TYPE	MATERIAL TYPE	Condition				Ironmongery		Glass		COMMENTS
				Good	Fair	Poor	Replace	Nr missing items	DESCRIPTION OF MISSING/FAULTY ITEMS	GLAZING SEALS	Panes of glass to replace	
217	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
218	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
219	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
220	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
221	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
222	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
223	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
224	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
225	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
226	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
227	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
228	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
229	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
230	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
231	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
232	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
233	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
234	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
235	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
236	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
237	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
238	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
239	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
240	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals

TOTALS

0

TOTALS

0

Great Northern Warehouse, Manchester.

Window Condition Survey

Elevation Ref

Deansgate Elevation

WINDOW NUMBER	FLOOR NUMBER	DESIGN TYPE	MATERIAL TYPE	Condition				Ironmongery		Glass		COMMENTS
				Good	Fair	Poor	Replace	Nr missing items	DESCRIPTION OF MISSING/FAULTY ITEMS	GLAZING SEALS	Panes of glass to replace	
241	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
242	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
243	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
244	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
245	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
246	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
247	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
248	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
249	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
250	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
251	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
252	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
253	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
254	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
255	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
256	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals
257	3	Sash	Timber		X			0		Beads	0	Redecoration/New Mastic Seals

TOTALS

0

TOTALS

0