



National Football Museum- Application number: 131037/VO/2021

Document

Issue date

Revision

Planning Condition 4 -Discharge Information

7th July 2022

0

Condition 4

Before the Heat Rejection Units are installed details of how the existing CCTV coverage would be amended to cover the area where the units are located shall be submitted to and approved in writing by the City Council as Local Planning Authority.

Discharge Response

The National Football Museum operations team have confirmed locations of the current CCTV cameras and the extent coverage to the external ramp area where the new dry cooler units and enclosure are to be located. Details are contained in the following images.




Figure 1-Ariel view showing location of CCTV cameras

The adjacent plan identifies the existing location of 2 no CCTV cameras.

CCTV Camera 1 is located at high level and is a column mounted camera and has coverage of the North East frontage of the building for the length of the ramped approach where the new external dry coolers are proposed. (See figures 2 and 3 below)

CCTV Camera 2 is located on the building façade and has coverage within and along the full length of the ramp adjacent the building where the new external dry coolers are proposed. (See figures 4 and 5 below)



Figure 2- Column Mounted CCTV Camera 1 location



Figure 3- CCTV Camera 1 viewed from external ramp location.



National Football Museum- Application number: 131037/VO/2021



Figure 4- Building Mounted CCTV Camera 2 location



Figure 5- CCTV Camera 2 view along length of external ramp.

Following review, the National Football Museum operation team have confirmed the existing CCTV camera coverage identified above is sufficient for them to monitor the location where the external dry coolers are to be located and no additional fittings are required.