



Atelier MB
Urban Architects



Science and Industry Museum Manchester

Project Ref: 2002

Door Methodologies

1830s Warehouse

Date: March 2023
Issue –

Relates to:
1830s Warehouse

AtelierMB Limited
Suite 2A, Amazon House, Brazil Street,
Manchester M1 3PJ
T 0616 236 0051
admin@ateliermb.co.uk
www.ateliermb.co.uk



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_025
Instances	4
Doors referenced	0009:08 0011:08 0002:08 0005:08
Description	Make adjustments to door to ensure correct spacing. Fix new fire door signage. Self-adhesive signs on glass.
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Metal doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_026
Instances	1
Doors referenced	MAN-000183
Description	Make intrusive inspection at perimeter of frame to verify no gaps between frame and surrounding wall. Replace hinges and screws, rehang door to correct spacing all round. Fix new fire door signage Install certified door closer(s) Make good door and surround decorations
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Timber doors



Building	Station Building
Methodology Ref:	DOOR_MET_041
Instances	2
Doors referenced	0007:08 0010:08
Description	Install new dropdown seal. Fix new fire door signage. Self-adhesive signs on glass.
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Metal doors



Building	Station Building
Methodology Ref:	DOOR_MET_049
Instances	1
Doors referenced	0012:08
Description	Install new dropdown seal. Replace hinges and screws, rehang door to correct spacing all round.
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Metal doors



Building	Station Building
Methodology Ref:	DOOR_MET_057
Instances	1
Doors referenced	0023:08
Description	Install new dropdown seal. Replace hinges and screws, rehang door to correct spacing all round. Fix new fire door signage. Self-adhesive signs on glass.
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Metal doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_057
Instances	1
Doors referenced	0018:08
Description	Install new dropdown seal. Inspect hinges and screws, rehang door to correct spacing all round. Fix new fire door signage. Self-adhesive signs on glass..
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Metal doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_073
Instances	3
Doors referenced	0013:08 MAN-000206 MAN-000208
Description	Replace existing intumescent smoke seals as appropriate for door rating. Fix new fire door signage. Self-adhesive signs on glass.
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Metal doors



Building	Station Building
Methodology Ref:	DOOR_MET_088
Instances	1
Doors referenced	0015:08
Description	Make intrusive inspection at perimeter of frame to verify no gaps between frame and surrounding wall. Replace existing intumescent smoke seals as appropriate for door rating. Replace hinges and screws, rehang door to correct spacing all round. Fix new door signage. Make good door and surround decorations.
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Timber doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_089
Instances	10
Doors referenced	0006:08 0008:08 0014:08 0016:08 0018:08 0020:08 0025:08 0027:08 0003:08 0004:08
Description	Replace existing intumescent smoke seals as appropriate for door rating. Replace hinges and screws, rehang door to correct spacing all round. Fix new fire door signage. Self-adhesive signs on glass.
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Metal doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_120
Instances	1
Doors referenced	0019:08
Description	Make intrusive inspection at perimeter of frame to verify no gaps between frame and surrounding wall. Replace existing intumescent smoke seals as appropriate for door rating Install new dropdown seal. Replace hinges and screws, rehang door to correct spacing all round. Fix new fire door signage. Make good door and surround decorations.
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Timber doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_121
Instances	3
Doors referenced	0021:08 0024:08 0026:08
Description	Replace existing intumescent smoke seals as appropriate for door rating Install new dropdown seal. Replace hinges and screws, rehang door to correct spacing all round. Fix new fire door signage
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Metal doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_130
Instances	1
Doors referenced	MAN-000154
Description	Make intrusive inspection at perimeter of frame to verify no gaps between frame and surrounding wall. Replace existing lipping with wider lipping to correct gap. Allow for rebate for intumescent smoke seal to suit door rating. Install certified door closer(s). Make good door and surround decorations.
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Timber doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_136
Instances	2
Doors referenced	MAN-000056 MAN-000286
Description	Make intrusive inspection at perimeter of frame to verify no gaps between frame and surrounding wall. Replace existing lipping with wider lipping to correct gap. Allow for rebate for intumescent smoke seal to suit door rating. Fix new fire door signage. Make good door and surround decorations.
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Wood doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_137
Instances	1
Doors referenced	MAN-000178
Description	Make adjustments to door to ensure correct spacing. Fix new fire door signage.
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Metal doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_138
Instances	2
Doors referenced	MAN-000062 MAN-000214
Description	Make intrusive inspection at perimeter of frame to verify no gaps between frame and surrounding wall. Replace existing lipping with wider lipping to correct gap. Allow for rebate for intumescent smoke seal to suit door rating Fix new fire door signage Install certified door closer(s) Make good door and surround decorations.
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Wood doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_139
Instances	3
Doors referenced	MAN-000172 MAN-000188 MAN-000236
Description	Replace existing lipping with wider lipping to correct gap. Allow for rebate for intumescent smoke seal to suit door rating Fix new fire door signage Install certified door closer(s)
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Metal doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_144
Instances	2
Doors referenced	MAN-000135 MAN-000136
Description	Make intrusive inspection at perimeter of frame to verify no gaps between frame and surrounding wall. Replace existing lipping with wider lipping to correct gap. Allow for rebate for intumescent smoke seal to suit door rating. Replace hinges and screws, rehang door to correct spacing all round. Make good door and surround decorations.
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Timber doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_146
Instances	2
Doors referenced	MAN-000076 MAN-000084
Description	Make intrusive inspection at perimeter of frame to verify no gaps between frame and surrounding wall. Replace existing lipping with wider lipping to correct gap. Allow for rebate for intumescent smoke seal to suit door rating Replace hinges and screws, rehang door to correct spacing all round. Install certified door closer(s) Make good door and surround decorations.
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Wood doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_152
Instances	8
Doors referenced	MAN-000075 MAN-000157 MAN-000161 MAN-000249 MAN-000285 MAN-000287 No code available/ B7 MAN-000243
Description	Make intrusive inspection at perimeter of frame to verify no gaps between frame and surrounding wall. Replace existing lipping with wider lipping to correct gap. Allow for rebate for intumescent smoke seal to suit door rating. Replace hinges and screws, rehang door to correct spacing all round. Fix new fire door signage. Make good door and surround decorations.
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Timber doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_153
Instances	1
Doors referenced	0029:08
Description	Replace hinges and screws, rehang door to correct spacing all round. Fix new fire door signage.
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Metal doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_154
Instances	5
Doors referenced	MAN-000146 MAN-000151 MAN-000316
Description	Make intrusive inspection at perimeter of frame to verify no gaps between frame and surrounding wall. Replace existing lipping with wider lipping to correct gap. Allow for rebate for intumescent smoke seal to suit door rating Replace hinges and screws, rehang door to correct spacing all round. Fix new fire door signage Install certified door closer(s) Make good door and surround decorations.
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Timber doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_155
Instances	2
Doors referenced	MAN-000175 MAN-000186
Description	Replace existing lipping with wider lipping to correct gap. Allow for rebate for intumescent smoke seal to suit door rating Replace hinges and screws, rehang door to correct spacing all round. Fix new fire door signage Install certified door closer(s)
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Metal doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_192
Instances	3
Doors referenced	MAN-000228 MAN-000264 MAN-000305
Description	Make intrusive inspection at perimeter of frame to verify no gaps between frame and surrounding wall. Replace existing lipping with wider lipping to correct gap. Allow for rebate for intumescent smoke seal to suit door rating Replace existing intumescent smoke seals as appropriate for door rating. Make good door and surround decorations.
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Timber doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_194
Instances	2
Doors referenced	MAN-000313 MAN-000241
Description	Make intrusive inspection at perimeter of frame to verify no gaps between frame and surrounding wall. Replace existing lipping with wider lipping to correct gap. Allow for rebate for intumescent smoke seal to suit door rating Replace existing intumescent smoke seals as appropriate for door rating Install certified door closer(s) Make good door and surround decorations.
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Timber doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_203
Instances	7
Doors referenced	00017:08 MAN-000204 MAN-000212 MAN-000217 MAN-000230 MAN-000234 MAN-000239
Description	Make adjustments to door to ensure correct spacing. Replace existing intumescent smoke seals as appropriate for door rating Fix new fire door signage Install certified door closer(s)
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Metal doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_205
Instances	1
Doors referenced	MAN-000223
Description	Replace existing lipping with wider lipping to correct gap. Allow for rebate for intumescent smoke seal to suit door rating Replace existing intumescent smoke seals as appropriate for door rating Fix new fire door signage Verify glazing and replace if not certified, replace glazing beads to match existing, apply finish to match existing.
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Metal doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_208
Instances	5
Doors referenced	MAN-000290 MAN-000295 MAN-000302 MAN-000310 MAN-000203
Description	Make intrusive inspection at perimeter of frame to verify no gaps between frame and surrounding wall. Replace existing lipping with wider lipping to correct gap. Allow for rebate for intumescent smoke seal to suit door rating Replace existing intumescent smoke seals as appropriate for door rating Replace hinges and screws, rehang door to correct spacing all round. Make good door and surround decorations.
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Timber doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_216
Instances	3
Doors referenced	MAN-000255 MAN-000326 MAN-000329
Description	Make intrusive inspection at perimeter of frame to verify no gaps between frame and surrounding wall. Replace existing lipping with wider lipping to correct gap. Allow for rebate for intumescent smoke seal to suit door rating. Replace existing intumescent smoke seals as appropriate for door rating. Replace hinges and screws, rehang door to correct spacing all round. Fix new fire door signage. Make good door and surround decorations.
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Timber doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_217
Instances	1
Doors referenced	0028:08
Description	Make adjustments to door to ensure correct spacing. Replace existing intumescent smoke seals as appropriate for door rating. Replace hinges and screws, rehang door to correct spacing all round. Fix new fire door signage.
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Metal doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_218
Instances	4
Doors referenced	MAN-000185 No code available No code available No code available
Description	Make intrusive inspection at perimeter of frame to verify no gaps between frame and surrounding wall. Replace existing lipping with wider lipping to correct gap. Allow for rebate for intumescent smoke seal to suit door rating. Replace existing intumescent smoke seals as appropriate for door rating. Replace hinges and screws, rehang door to correct spacing all round. Fix new fire door signage. Install certified door closer(s). Make good door and surround decorations.
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Timber doors



Building	1830s Warehouse
Methodology Ref:	DOOR_MET_256
Instances	7
Doors referenced	MAN-000054 MAN-000190 MAN-000191 MAN-000193
Description	Remove existing doorset and make good surround. Replace doorset to match existing style and rating, include new ironmongery, signage, closers and intumescent smoke seals. Decorate door as existing and make good surrounding decorations.
NBS references	
AtelierMB Drawings	
Other information referenced	
Notes	Timber doors



ateliermb



0161 236 0051



ateliermbarchitects



atelier mb architects



info@ateliermb.co.uk



Atelier MB Ltd. Suite 2A, Amazon House, Brazil Street, Manchester, M1 3PJ