N
SO2
MIDWAY STREET
STOCKPORT ROAD
TARMAC
PAVING
CONC
TARMAC
UNABLE TO FULLY SURVEY DUE TO OBSTRUCTIONS
EXISTING BUILDING
STORE
SHED
METAL PLATE
UNABLE TO FULLY SURVEY DUE TO OBSTRUCTION
EXISTING BUILDING
ROUGH GROUND
BRICK WALL
SO1
SO3
SO4
SO5
STUMP
STUMP
TAC
IC CL54.48
TL
EIC 54.45
WSV
CCTV
WSV
RS
CB
SP
MG
IC CL54.39
SLP
DR
FLOOR LEVEL = +54.700
FLOOR LEVEL = +54.700
FLOOR LEVEL = +54.700
FLOOR LEVEL = +54.700
FLOOR LEVEL = +54.500
FLOOR LEVEL = +54.500
FLOOR LEVEL = +54.500
FLOOR LEVEL = +54.500
FLOOR LEVEL = +54.300
FLOOR LEVEL = +54.300
CH1 8mM
CH1 2.0m
CH1 1.2mH
CH1 1.2mH
CH1 1.2mH