
Attenuation Tank Drawing (also attached as separate file)



Photographic Evidence of Attenuation Tank

Photo 1 – Attenuation Tank 27.01.2025



Photo 2 – Attenuation Tank 27.01.2025





Photo 3 – Attenuation Tank 28.01.2025



Photo 4 – Attenuation Tank 29.01.2025



Photographic Evidence of Installation of Surface Water Drainage (also attached as separate file)




Photo 5 – SW3 – 07.04.2025




Photo 6 – SW2 – 10.04.2025




Photo 7 – SW5 – 09.04.2025




Photo 8 – SW6 – 05.03.2025



Photo 9 – SW7 – 05.02.2025



Photo 10 – SW8 – 28.01.2025



Photo 11 – SW9 – 24.04.2025



Photo 12 – SW10 – 21.01.2025




Photo 13 – SW11 – 08.08.2024



Photo 14 – SW12 – 22.08.2024




Photo 15 – SW13 – 18.09.2024



Photo 16 – SW14 - 19.11.2024




Photo 17 – SW15 – 25.09.2024




Photo 18 – SW16 – 12.12.2024



Photo 19 – SW17 – 12.12.2024



Photo 20 – SW18 – 19.12.2024



Photo 21 – SW19 – 20.01.2025






Photo 22 – SW20 – 12.04.2025




S8 - Hydrobrake Drawing (also attached as separate file)




S8 - Hydrobrake Photos




F1 - B1 Underslung Drainage Drawing (also attached as separate file)




F2 - B1 Underslung Drainage Drawing (also attached as separate file)



F1 - B1 Underslung Drainage



F2 - B1 Underslung Drainage



F2 Diffuser 03/03/26 - diffuser, chamber and stone in place



F2 Perforated Pipe 03/03/26

