

NOTE: POINTING AND REPAIRS TO BRICKWORK ARE INDICATIVE AND ARE TO BE CONFIRMED FOLLOWING DETAILED INSPECTION

KEY

NEW RECLAIMED FACING
BRICK SPEC F10/140

NEW BLOCKWORK
SPEC F10/120

EXTG MODERN BRICKS TO BE
REMOVED AND REPLACED WITH
RECLAIMED BRICK SPEC F10/140

APPROX AREAS OF LOCALISED
REPAIRS AND REPOINTING OF EXTG
BRICKWORK AS SPEC F10/665

CRACK IN BRICKWORK TO BE
REPAIRED AS ENGINEER DETAIL

PPC ALUMINIUM SLEEVES TO REVEALS
OF WINDOWS AND DOOR OPENINGS

