

Wall between roofs ER12 and NR02
Brick and stone repairs


Indent section of reclaimed
stone to hole through coping

Revision: -
First issue
Date: 11 June 2024

Page 1 of 5

OTH-PUR-TH-RF-SKE-A-3666

Wall between roofs ER12 and NR02
Brick and stone repairs



Revision: -
First issue
Date: 11 June 2024

Page 2 of 5

OTH-PUR-TH-RF-SKE-A-3666

Wall between roofs ER12 and NR02
Brick and stone repairs




Revision: -
First issue
Date: 11 June 2024

Page 3 of 5

OTH-PUR-TH-RF-SKE-A-3666

Wall between roofs ER12 and NR02
Brick and stone repairs



Remove fixing and fill hole

Brick replacement

Revision: -
First issue
Date: 11 June 2024

Page 4 of 5

OTH-PUR-TH-RF-SKE-A-3666

Wall between roofs ER12 and NR02
Brick and stone repairs



Brick replacement

16

15

Revision: -
First issue
Date: 11 June 2024

Page 5 of 5